

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 46146

USING DEPT NO:	507301	OPENED DATE:	02/14/2023 09:36:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2023 08:15:44	METER 1 - M:	9527	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2023 14:36:32	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	0.00	5.00	43.94
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6193652		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11915538	02/17/2023 07:00:00	02/17/2023 07:19:48	0.33	\$38.94
LABOR						38.94

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 46146

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by RC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM done by Tuscaloosa Toyota. No charge 10,000-mile service is free.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 46913

USING DEPT NO:	507301	OPENED DATE:	05/01/2023 08:44:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2023 08:29:58	METER 1 - M:	14020	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2023 10:07:55	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.29	\$0.00	\$0.00	\$28.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.24	28.29	0.00	5.00	33.29
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/01/2023 14:30:00	05/01/2023 14:42:49	0.21	\$25.21
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/01/2023 14:13:26	05/01/2023 14:15:00	0.03	\$3.08
					LABOR	28.29

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 46913

Work Order Notes

(EHANNAH) pm- replace wipers - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, filters good, tires and tire pressure.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 48125

USING DEPT NO:	507301	OPENED DATE:	09/08/2023 08:35:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2023 15:24:39	METER 1 - M:	19093	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/13/2023 07:19:56	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6218822		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11915538	09/11/2023 07:00:00	09/11/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 48125

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by RC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) 20,000 mile service done by Toyota no charge

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 49060

USING DEPT NO:	507301	OPENED DATE:	11/27/2023 13:54:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/29/2023 07:15:54	METER 1 - M:	25474	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/29/2023 08:49:13	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$24.08	\$0.00	\$47.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.40	\$46.96	\$0.00	\$82.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	71.04	5.00	135.04
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/28/2023 07:12:00	11/28/2023 07:30:00	0.30	\$35.40
03-51-038	REPLACE NEW WIPER BLADES	12395904	11/29/2023 07:00:00	11/29/2023 07:12:00	0.20	\$23.60
					LABOR	59.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.91	5	\$39.53
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
					PARTS	71.04

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 49060

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) FC REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) FC PERFORMED OIL CHANGE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 49945

USING DEPT NO:	507301	OPENED DATE:	02/26/2024 13:00:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/29/2024 15:23:13	METER 1 - M:	28841	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/04/2024 07:05:36	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$59.49	\$78.14	\$0.00	\$137.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.50	59.49	78.14	5.00	142.63
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/26/2024 14:30:00	02/26/2024 14:43:35	0.23	\$26.71
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/26/2024 13:58:20	02/26/2024 14:15:00	0.28	\$32.78
				LABOR		59.49

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	35.61	1	\$35.61
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
				PARTS		78.14

Work Order Charge Detail

UNIT NO:	244965	2022 TOYOTA CAMRY	WORK ORDER NO:	49945
----------	--------	-------------------	----------------	-------

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 50897

USING DEPT NO:	507301	OPENED DATE:	05/20/2024 11:28:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2024 15:19:21	METER 1 - M:	33402	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/21/2024 11:25:21	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.15	\$44.33	\$0.00	\$45.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.01	1.15	44.33	5.00	50.48
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/20/2024 15:04:25	05/20/2024 15:05:00	0.01	\$1.15
					LABOR	1.15

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
					PARTS	44.33

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 50897

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 51699

USING DEPT NO:	507301	OPENED DATE:	08/05/2024 13:29:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2024 14:16:52	METER 1 - M:	37521	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/12/2024 07:39:43	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.11	\$0.00	\$24.11
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$43.37	\$0.00	\$43.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	67.48	5.00	72.48
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.31	5	\$36.53
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	67.48

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 51699

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, found no issues at this time-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 37,521

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 52649

USING DEPT NO:	507301	OPENED DATE:	10/30/2024 12:36:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/31/2024 08:37:28	METER 1 - M:	42209	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/31/2024 08:43:40	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$84.08	\$0.00	\$84.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	84.08	5.00	89.08
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	14.90	5	\$74.48
					PARTS	84.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 52649

Work Order Notes

(EHANNAH) pm-

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR-perform PM, changed oil and filter, checked fluids, checked air and cabin air filter, checked tires and tire pressures.
42209 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 52815

USING DEPT NO:	507301	OPENED DATE:	11/15/2024 08:58:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/15/2024 10:59:57	METER 1 - M:	42908	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/15/2024 12:56:37	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 52815

Work Order Notes

(EHANNAH) low tire pressure light is on

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) tire pressure was low 29 psi on all tires filled to factory spec checked ok, cm 42908

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 54010

USING DEPT NO:	507301	OPENED DATE:	03/07/2025 07:33:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2025 08:25:44	METER 1 - M:	47498	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/18/2025 11:00:44	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.31	\$0.00	\$51.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	51.31	5.00	56.31
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.18	5	\$40.88
					PARTS	51.31

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 54010

Work Order Notes

(EHANNAH) pm- wipers-
(GARAGE) did not need wipers.cq

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) bottom end drained oil and filter, fletcher. aired tires and checked fluids, jr filled with oil and recorded build dates and tread depth. cq

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 54505

USING DEPT NO:	507301	OPENED DATE:	04/17/2025 07:33:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/17/2025 09:16:00	METER 1 - M:	51023	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/17/2025 15:44:14	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-34-017	INSPECT HEADLIGHT/TAILLIGHT SOCKE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 54505

Work Order Notes

(EHANNAH) INSPECT TAILLIGHT

Job Notes

06-34-017 - INSPECT HEADLIGHT/TAILLIGHT SOCKET

(GARAGE) inspected lights on car all ligths checked ok, both front and back, cm 51023miles,

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 55002

USING DEPT NO:	507301	OPENED DATE:	06/05/2025 12:54:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2025 13:55:39	METER 1 - M:	53050	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2025 09:36:54	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	48.90	5.00	53.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
					PARTS	48.90

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 55002

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- topside

GC- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tirtes and tire pressures, changed sticker, reset oil light, filled up washer fluid
53052 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 55172

USING DEPT NO:	507301	OPENED DATE:	06/23/2025 08:08:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2025 10:35:46	METER 1 - M:	53228	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/24/2025 07:29:54	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2PU080092	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/25/2025 09:19:03 By User: GLOBETTI

UNIT NO: 244965 2022 TOYOTA CAMRY

WORK ORDER NO: 55172

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) performed perp for sale cm 53283 miles,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Jun 25 2025 09:19:03 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244965') //Q=