

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 40663

USING DEPT NO:	504131	OPENED DATE:	08/06/2021 15:26:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2021 15:27:10	METER 1 - M:	133	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2021 08:33:01	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	2.00	120.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11310047	08/06/2021 15:26:42	08/06/2021 16:26:42	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 40663

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 40831

USING DEPT NO:	504131	OPENED DATE:	08/24/2021 14:50:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2021 13:43:20	METER 1 - M:	707	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2021 15:54:16	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-062	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.17	\$20.13	\$1,351.76	\$0.00	\$1,371.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.17	20.13	1,351.76	2.00	1,373.89
--------------	-------------------	------	-------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-51-062	INSTALL TOOLBOX ASSY	11213180	08/26/2021 13:08:53	08/26/2021 13:19:07	0.17	\$20.13
					LABOR	20.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-062	INSTALL TOOLBOX ASSY	127-5-02	WEATHERGUARD TOOLBOX	1332.26	1	\$1,332.26
14-51-062	INSTALL TOOLBOX ASSY	SHIPPING	SHIPPING AND HANDLING	19.50	1	\$19.50
					PARTS	1351.76

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 40831

Work Order Notes

(LISAPATE) Install tool box

Job Notes

14-51-062 - INSTALL TOOLBOX ASSY

(MSIDES) Installed toolbox in bed of truck. MS 0.5hrs.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 42122

USING DEPT NO:	504131	OPENED DATE:	01/20/2022 10:05:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2022 11:08:27	METER 1 - M:	3812	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/24/2022 13:45:28	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.62	\$63.06	\$0.00	\$69.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.06	6.62	63.06	2.00	71.68
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/21/2022 09:42:35	01/21/2022 09:45:57	0.06	\$6.62
					LABOR	6.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	6.81	7	\$47.67
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	6.81	(7)	(\$47.67)
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.23	8	\$57.84
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.22	1	\$5.22
					PARTS	63.06

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 42122

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Chad RC/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 43659

USING DEPT NO:	504131	OPENED DATE:	06/15/2022 08:40:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/17/2022 11:26:39	METER 1 - M:	6625	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2022 15:09:41	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.15	\$15.57	\$0.00	\$20.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.01	\$71.09	\$0.00	\$104.10
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.09	\$10.75	\$35.19	\$0.00	\$45.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.41	48.91	121.85	2.00	172.76
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/15/2022 10:31:42	06/15/2022 10:48:29	0.28	\$33.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	06/15/2022 10:25:59	06/15/2022 10:31:27	0.09	\$10.75
03-51-038	REPLACE NEW WIPER BLADES	11901357	06/15/2022 10:23:06	06/15/2022 10:25:43	0.04	\$5.15
				LABOR		48.91

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.49	8	\$59.88
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.21	1	\$11.21
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.79	2	\$15.57
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WP10266	CABIN AIR FILTER	35.19	1	\$35.19
				PARTS		121.85

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 43659

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 6625 Completed PM topside, Scott was bottomsides. Completed checklist. AMG/SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 45394

USING DEPT NO:	504131	OPENED DATE:	12/01/2022 08:50:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2022 09:16:42	METER 1 - M:	9476	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2022 09:39:52	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.63	\$0.00	\$33.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$77.55	\$91.61	\$0.00	\$169.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.81	95.25	107.24	5.00	207.49
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/01/2022 14:30:00	12/01/2022 15:09:26	0.66	\$77.55
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/01/2022 14:15:04	12/01/2022 14:15:04	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11915538	12/01/2022 14:24:08	12/01/2022 14:24:08	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11915538	12/01/2022 14:24:08	12/01/2022 14:24:08	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11915538	12/01/2022 14:24:08	12/01/2022 14:33:08	0.15	\$17.70
				LABOR		95.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	10.68	8	\$85.44
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.17	1	\$6.17
					PARTS	107.24

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 45394

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers \RC

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,RC/GC
MILEAGE-9476

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 45672

USING DEPT NO:	504131	OPENED DATE:	01/04/2023 13:29:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2023 15:23:16	METER 1 - M:	9825	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2023 07:31:35	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.10	\$11.80	\$213.78	\$0.00	\$225.58
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	2.15	\$253.14	\$916.50	\$0.00	\$1,169.64
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	5.93	\$699.41	\$4.02	\$0.00	\$703.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	8.17	964.35	1,134.30	5.00	2,103.65
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	11915538	01/24/2023 07:00:00	01/24/2023 07:06:00	0.10	\$11.80
66-17-030	PERFORM TIRE PATCH	11310047	01/06/2023 09:16:47	01/06/2023 15:12:25	5.93	\$699.41
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11310047	01/06/2023 07:08:04	01/06/2023 09:16:47	2.15	\$253.14
					LABOR	964.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.65	2	\$1.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VJL3Z13C788A	CORNER STROBE KIT AMB/WHT FORD	916.50	1	\$916.50
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
14-02-013	INSTALL FLOOR COVERINGS	446971V	FRONT FLOOR MATS	213.78	1	\$213.78
					PARTS	1134.30

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 45672

Work Order Notes

(EHANNAH) install strobe lights

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(LISAPATE) RC installed floor mats

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(GARAGE) Removed front grille and mounted strobe lights in the grille. Ran wires inside the cab. Drilled a hole and mounted switch in a plastic panel. Ran power and ground wire across the vehicle and connected them behind the passenger kick panel. Removed third brake light assembly and ran wires above the headliner, down the pillar, and to the switch harness. Mounted new strobe light at third brake light assembly. EH

66-17-030 - PERFORM TIRE PATCH

(EHOWELL) Left rear tire was punctured. Installed a tire patch and balanced tire. EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 45944

USING DEPT NO:	504131	OPENED DATE:	01/26/2023 15:40:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/31/2023 13:04:31	METER 1 - M:	9825	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/31/2023 15:42:03	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-51-043	RECALL WIPER ARM	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-71-045	RECALL Undercarriage	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-51-043	RECALL WIPER ARM	11099772	100604915		\$0.00
				COMML	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 45944

Work Order Notes

(CWIGLEY) Recall 22s26 for wiper assembly.

Job Notes

17-51-043 - RECALL WIPER ARM

(CWIGLEY) Long Lewis Ford Mobile Unit completed recall.

17-71-045 - RECALL Undercarriage

(LISAPATE) Long Lewis secured underbody shields with rivets Per 22S53

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 47031

USING DEPT NO:	504131	OPENED DATE:	05/12/2023 13:03:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/15/2023 15:04:48	METER 1 - M:	11804	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/16/2023 08:01:01	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.53	\$62.34	\$16.65	\$0.00	\$78.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.50	\$72.47	\$0.00	\$87.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.21	\$24.55	\$0.00	\$0.00	\$24.55

JOB COUNT: 4	WORK ORDER TOTAL:	0.87	102.39	89.12	5.00	196.51
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12052187	05/12/2023 13:56:33	05/12/2023 14:09:02	0.21	\$24.55
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/12/2023 13:22:44	05/12/2023 13:54:26	0.53	\$62.34
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/12/2023 13:14:41	05/12/2023 13:22:34	0.13	\$15.50
				LABOR		102.39

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.65	8	\$61.20
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
				PARTS		89.12

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 47031

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,GC/GC
MILEAGE-11804

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Hand washed unit.

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 48828

USING DEPT NO:	504131	OPENED DATE:	11/06/2023 07:11:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2023 12:09:22	METER 1 - M:	14655	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2023 13:55:57	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.28	\$16.65	\$0.00	\$17.93
06-15	INSPECT STEERING	DON	N	N	GARAGE	4.33	\$510.58	\$0.00	\$0.00	\$510.58
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	3.13	\$369.50	\$0.00	\$0.00	\$369.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.15	\$17.77	\$460.11	\$0.00	\$477.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.39	\$114.50	\$0.00	\$128.89
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$2.98	\$18.30	\$0.00	\$21.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.48	\$0.00	\$0.00	\$1.48

JOB COUNT: 8	WORK ORDER TOTAL:	7.78	917.98	609.56	5.00	1,532.54
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11310047	11/08/2023 11:20:54	11/08/2023 15:40:31	4.33	\$510.58
WA-00	WASH COMPLETE VEHICLE	12395904	11/06/2023 15:39:15	11/06/2023 15:40:00	0.01	\$1.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	11/06/2023 15:08:03	11/06/2023 15:17:05	0.15	\$17.77
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	11/06/2023 11:41:16	11/06/2023 11:42:47	0.03	\$2.98
03-51-038	REPLACE NEW WIPER BLADES	12395904	11/06/2023 11:12:03	11/06/2023 11:12:42	0.01	\$1.28
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/06/2023 11:01:49	11/06/2023 11:09:08	0.12	\$14.39
66-17-013	PERFORM ALIGNMENT	11310047	11/08/2023 08:05:41	11/08/2023 11:13:34	3.13	\$369.50
				LABOR		917.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.59	8	\$76.68

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.41	2	\$6.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	1	\$0.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.95	2	\$1.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	3586500	TIRE 265/70R17 PIR SCPN ATR	225.00	2	\$450.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	3586500	TIRE 265/70R17 PIR SCPN ATR	225.00	(1)	(\$225.00)
66-PM-PMA	PERFORM OIL CHANGE	PA5642F	AIR FILTER	24.30	1	\$24.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC8214	CABIN FILTER	18.30	1	\$18.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	3586500	TIRE 265/70R17 PIR SCPN ATR	225.00	1	\$225.00
					PARTS	609.56

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 48828

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc

06-15 - INSPECT STEERING

(EHOWELL) FC checked front end.

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Set front toe. Performed alignment procedure for image processing module using the Ford scan tool. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(FCONTRER) Perform replaced 2tires f and 2 Val 21060 1 58103 2 58104 1 58102 fc

(EKIMBREL) USED 2 NEW TIRES FROM NONSTOCK

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check fc-sh

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) Replaced cabln filter fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 49101

USING DEPT NO:	504131	OPENED DATE:	11/30/2023 11:49:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2023 10:57:43	METER 1 - M:	14821	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 10:57:46	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-79-001	RECALL AIR BAG	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-79-001	RECALL AIR BAG	11099772	100617967		\$0.00
				COMML	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 49101

Work Order Notes

(LISAPATE) Recall airbag

Job Notes

17-79-001 - RECALL AIR BAG

(LISAPATE) Long Lewis resecured harness

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 50776

USING DEPT NO:	504131	OPENED DATE:	05/08/2024 07:09:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2024 07:49:08	METER 1 - M:	17218	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/13/2024 11:58:59	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.02	\$82.85	\$0.00	\$83.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.05	\$0.00	\$0.00	\$1.05

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.07	82.85	5.00	89.92
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	05/08/2024 07:45:36	05/08/2024 07:46:08	0.01	\$1.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/08/2024 07:45:05	05/08/2024 07:45:36	0.01	\$1.02
				LABOR	2.07	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.71	8	\$61.68
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
				PARTS	82.85	

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 50776

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) DID NOT NEED WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed was full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 50958

USING DEPT NO:	504131	OPENED DATE:	05/29/2024 09:25:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/29/2024 12:19:21	METER 1 - M:	17384	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/30/2024 08:25:41	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.02	\$2.10	\$216.44	\$0.00	\$218.54
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.02	\$2.69	\$0.00	\$0.00	\$2.69
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.04	4.79	216.44	5.00	226.23
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	12395904	05/29/2024 09:48:16	05/29/2024 09:49:20	0.02	\$2.10
06-32-002	INSPECT BATTERY	12395904	05/29/2024 09:45:41	05/29/2024 09:47:03	0.02	\$2.69
LABOR						4.79

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	216.44	1	\$216.44
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	221.08	(1)	(\$221.08)
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	221.08	1	\$221.08
PARTS						216.44

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 50958

Work Order Notes

(EHANNAH) check battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(FCONTRER) replaced new battery FC -sh

06-32-002 - INSPECT BATTERY

(FCONTRER) inspect battery FC

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 5/31/2024 8:11 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 52491

USING DEPT NO:	504131	OPENED DATE:	10/16/2024 09:07:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/16/2024 09:55:11	METER 1 - M:	19237	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/16/2024 12:16:14	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.65	\$0.00	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$83.12	\$0.00	\$83.12
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$30.00	\$0.00	\$30.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	129.77	5.00	134.77
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	30.00	1	\$30.00
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.85	8	\$70.80
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
					PARTS	129.77

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 52491

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-CM

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm-CM,GC, changed oil and oil filter, checked fluids, air filter good, changed cabin filter, tires and tire pressure.
Miles, 19,237

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) replaced cabin filter-CM

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed vehicle-CM

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54051

USING DEPT NO:	504131	OPENED DATE:	03/18/2025 07:53:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2025 07:45:42	METER 1 - M:	20928	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2025 11:44:48	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$306.47	\$0.00	\$306.47
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	306.47	5.00	311.47
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	4128600	TIRE 265/70R17 PIR SCORP ATR	303.57	1	\$303.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.90	1	\$2.90
				PARTS		306.47

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54051

Work Order Notes

(CWIGLEY) Tire Patch LR

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) FJ REPLACED LR TIRE

66-17-030 - PERFORM TIRE PATCH

(GARAGE) FJ- LR tire leaking. Puncture was too close to a previous patch to safely repair. New tire installed.

(EHOWELL) We installed the spare, then the customer came back and we installed the new tire.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54211

USING DEPT NO:	504131	OPENED DATE:	03/28/2025 09:51:04	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/28/2025 10:57:01	METER 1 - M:	21233	METER 2 - H:	6				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/28/2025 13:05:42	IN-SERVICE DATE:	08/05/2021						
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4									
				UNIT SERIAL NO:	1FTFW1E53MFB95503						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$30.09	\$0.00	\$30.09
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$8.88	\$0.00	\$8.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	38.97	5.00	43.97
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.88	1	\$8.88
03-51-038	REPLACE NEW WIPER BLADES	25-220	BEAM WIPER BLADE	15.05	2	\$30.09
PARTS						38.97

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54211

Work Order Notes

(EHANNAH) PM- WIPERS- WASH

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- replaced wipers

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) GC,JR, performed safety inspection, found no issues at this time
brake pads are 8mm front and rear
Miles, 21,233

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC,JR, -PM, Fluid check only, vehicle driven 1,996, checked fluids, filters good, tires and tire pressure, updated oil change sticker
Miles, 21,233

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54655

USING DEPT NO:	504131	OPENED DATE:	05/02/2025 07:24:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/06/2025 10:56:38	METER 1 - M:	21612	METER 2 - H: 6
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/06/2025 14:19:51	IN-SERVICE DATE:	08/05/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E53MFB95503	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-16-031	INSPECT SUSPENSION SHACKLE BOLT	DON	N	N	GARAGE	0.00	\$0.00	\$15.02	\$0.00	\$15.02
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	15.02	5.00	20.02
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
06-16-031	INSPECT SUSPENSION SHACKLE BOLT	DOR35623	U-BOLT	15.02	1	\$15.02
PARTS						15.02

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54655

Work Order Notes

(EHOWELL) inspect the U bolt it is broken and please check the tire pressure on all tires Ethan said they look low. The bottom piece of the U bolt was broken. The customer pulled it over a curb or something.

Job Notes

06-16-031 - INSPECT SUSPENSION SHACKLE BOLT

(EKIMBREL) CQ replaced U-bolt. labor 1.5hr

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54760

USING DEPT NO:	504131	OPENED DATE:	05/13/2025 07:43:49	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/14/2025 08:50:53	METER 1 - M:	21612	METER 2 - H:	6				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/22/2025 13:32:38	IN-SERVICE DATE:	08/05/2021						
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4									
			UNIT SERIAL NO:	1FTFW1E53MFB95503							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PR-13-129	PROGRAM CONTROLLER	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PR-13-129	PROGRAM CONTROLLER	2714700	180779		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 54760

Work Order Notes

(EHANNAH) Tire [patch on Rear Pass tire after it sat for a week

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

(EHOWELL) Automotive Services opened a work order and documented repairs performed by Stivers Ford.

66-17-030 - PERFORM TIRE PATCH

(GARAGE) CHECKED FOR CUSTOMER COMPLAINT AND FOUND SCREW IN RIGHT REAR TREAD OF TIRE. JACKED UP REAR OF TRUCK AND INSTALLED JACK STAND AND REMOVED TIRE AND RIM. BROKE DOWN TIRE ON TIRE MACHINE AND PATCHED TIRE. WHEN INSTALLING THE TIRE ON THE RIM A PIECE OF THE BEED ROLLED OFF. CHECKED FOR TIRE AVAILABILITY AND WE HAD ONE IN STOCK INSTALLED TIRE AND BALANCED AND INSTALLED ON TRUCK. CQ

(EKIMBREL) non-inv tire

PR-13-129 - PROGRAM CONTROLLER

(EHOWELL) Stivers Ford performed recall # 25S15B and reprogramed integrated trailer relay module.

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 55033

USING DEPT NO:	504131	OPENED DATE:	06/09/2025 09:08:07	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/09/2025 15:29:52	METER 1 - M:	21935	METER 2 - H:	6				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2025 10:25:16	IN-SERVICE DATE:	08/05/2021						
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E53MFB95503					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-34-022	REMOVE STROBE LIGHT/BULB/MOTOR	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-78-044	REMOVE TOOLBOX ASSY	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2025 12:29:16 By User: GLOBETTI

UNIT NO: 244156 2021 FORD F150 4X4

WORK ORDER NO: 55033

Work Order Notes

(CWIGLEY) Prep for sale. Remove strobe lights

Job Notes

25-34-022 - REMOVE STROBE LIGHT/BULB/MOTOR/ASSY

(GARAGE) GC- removed strobe kit for unit 6919B, had to remove the front grill and lower plastic piece to get the front strobes out, unhooked and cut zip ties and removed wires and rear tail light assembly

Miles, 21,968

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) GC removed GPS# 87U030640085.

25-78-044 - REMOVE TOOLBOX ASSY

(EHOWELL) CM/CQ removed toolbox.

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) GC- prep for sale unit 6919B, removed GPS, word marks, tag, RFID, papers, and any personal items

Miles, 21,968

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Jun 11 2025 12:29:16 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244156') //Q=