

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 44025

| | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|----------------|
| USING DEPT NO: | 507201 | OPENED DATE: | 07/20/2022 13:02:24 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 08/25/2022 13:33:12 | METER 1 - M: | 145 | METER 2 - H: 5 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 08/26/2022 10:44:46 | IN-SERVICE DATE: | 07/18/2022 | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 14-02-013 | INSTALL FLOOR COVERINGS | DON | O | N | GARAGE | 0.10 | \$12.29 | \$331.93 | \$0.00 | \$344.22 |
| 14-34-022 | INSTALL STROBE LIGHT/BULB/MOTOR/ | DON | O | N | GARAGE | 5.36 | \$632.74 | \$916.50 | \$0.00 | \$1,549.24 |
| 14-51-062 | INSTALL TOOLBOX ASSY | DON | O | N | GARAGE | 0.01 | \$0.75 | \$0.00 | \$0.00 | \$0.75 |
| 14-71-029 | INSTALL LINEX BED LINER | DON | O | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$595.13 | \$595.13 |
| 16-71 | TRANSPORT BODY | DON | O | N | GARAGE | 0.50 | \$59.00 | \$0.00 | \$0.00 | \$59.00 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| PS-00-001 | PREP SERVICE NEW UNIT IN-SERVICE | DON | C | N | GARAGE | 1.00 | \$118.00 | \$0.00 | \$0.00 | \$118.00 |

| | | | | | | |
|--------------|-------------------|------|--------|----------|--------|----------|
| JOB COUNT: 7 | WORK ORDER TOTAL: | 6.97 | 822.78 | 1,248.43 | 600.13 | 2,671.34 |
|--------------|-------------------|------|--------|----------|--------|----------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|-----------|-------------------------|------------|-------------|--------------------|------------|
| 14-71-029 | INSTALL LINEX BED LINER | 11177989 | 9008 | | \$595.13 |
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 600.13 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---|--------------|---------------------|---------------------|----------|--------------|
| 14-34-022 | INSTALL STROBE LIGHT/BULB/MOTOR/ASSY | 11310047 | 08/04/2022 07:04:22 | 08/04/2022 09:26:06 | 2.36 | \$278.74 |
| 14-34-022 | INSTALL STROBE LIGHT/BULB/MOTOR/ASSY | 11310047 | 08/03/2022 14:01:40 | 08/04/2022 07:04:07 | (17.04) | (\$2,010.82) |
| 14-34-022 | INSTALL STROBE LIGHT/BULB/MOTOR/ASSY | 11310047 | 08/03/2022 14:01:40 | 08/04/2022 07:04:07 | 17.04 | \$2,010.82 |
| 14-34-022 | INSTALL STROBE LIGHT/BULB/MOTOR/ASSY | 11310047 | 08/03/2022 14:01:40 | 08/03/2022 17:01:40 | 3.00 | \$354.00 |
| 14-51-062 | INSTALL TOOLBOX ASSY | 12052187 | 07/26/2022 09:32:31 | 07/26/2022 09:32:54 | 0.01 | \$0.75 |
| PS-00-001 | PREP SERVICE NEW UNIT IN-SERVICE INSPECTION | 11901357 | 07/22/2022 07:00:00 | 07/22/2022 08:00:00 | 1.00 | \$118.00 |
| 16-71 | TRANSPORT BODY | 11915538 | 08/25/2022 07:00:00 | 08/25/2022 07:30:00 | 0.50 | \$59.00 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 11074414 | 07/20/2022 14:32:59 | 07/20/2022 14:39:14 | 0.10 | \$12.29 |
| | | | | LABOR | | 822.78 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|----------|-----------------|----------|-------------|------------|----------|------------|
|----------|-----------------|----------|-------------|------------|----------|------------|

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 14-34-022 | INSTALL STROBE LIGHT/BULB/MOTOR/ASSY | VJL3Z13C788A | CORNER STROBE KIT AMB/WHT FORD | 916.50 | 1 | \$916.50 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446972 | F150 REAR MATS | 150.23 | 1 | \$150.23 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446972 | F150 REAR MATS | 150.23 | (1) | (\$150.23) |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446972 | F150 REAR MATS | 150.23 | 1 | \$150.23 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446972 | F150 REAR MATS | 150.23 | (1) | (\$150.23) |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446972 | F150 REAR MATS | 150.23 | 1 | \$150.23 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446972 | F150 REAR MATS | 150.23 | (1) | (\$150.23) |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446972 | F150 REAR MATS | 150.23 | 1 | \$150.23 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446971V | FRONT FLOOR MATS | 181.64 | 1 | \$181.64 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446971V | FRONT FLOOR MATS | 181.64 | (1) | (\$181.64) |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446971V | FRONT FLOOR MATS | 181.70 | 1 | \$181.70 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446971V | FRONT FLOOR MATS | 181.70 | (1) | (\$181.70) |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446971V | FRONT FLOOR MATS | 181.64 | 1 | \$181.64 |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446971V | FRONT FLOOR MATS | 181.64 | (1) | (\$181.64) |
| 14-02-013 | INSTALL FLOOR COVERINGS | 446971V | FRONT FLOOR MATS | 181.70 | 1 | \$181.70 |
| | | | | | PARTS | 1248.43 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 44025

Work Order Notes

(EKIMBREL) install floor mats
(LISAPATE) New unit do PDI
(CHANNELL) install toolbox and strobe lights

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(HHARBIN) Installed front and rear floor mats. SH

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(EHOWELL) Mounted two strobe lights in the front grille of the vehicle. Installed a new third brake light adapter and ran wires inside the vehicle. Fastened wires with zip ties and ran harness to the power source. Verified operation of lights after repair. EH

14-51-062 - INSTALL TOOLBOX ASSY

(JWRIGHT) Installed toolbox. JAW,JM

14-71-029 - INSTALL LINEX BED LINER

(EKIMBREL) line-x tusc installed bed lining

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Line-X by RC

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) AG completed PDI

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 45522

| | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|----------------|
| USING DEPT NO: | 507201 | OPENED DATE: | 12/12/2022 08:41:46 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 12/12/2022 15:18:15 | METER 1 - M: | 1637 | METER 2 - H: 5 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 12/13/2022 08:34:29 | IN-SERVICE DATE: | 07/18/2022 | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.18 | \$21.17 | \$0.00 | \$0.00 | \$21.17 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|-------|------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.18 | 21.17 | 0.00 | 5.00 | 26.17 |
|--------------|-------------------|------|-------|------|------|-------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 12/12/2022 11:12:11 | 12/12/2022 11:22:57 | 0.18 | \$21.17 |
| | | | | | LABOR | 21.17 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 45522

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) New vehicle has 1637 miles on it. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 46909

| | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|----------------|
| USING DEPT NO: | 507201 | OPENED DATE: | 05/01/2023 07:34:09 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 05/02/2023 08:38:32 | METER 1 - M: | 2837 | METER 2 - H: 5 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 05/02/2023 10:02:58 | IN-SERVICE DATE: | 07/18/2022 | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|-----------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.07 | \$7.77 | \$81.12 | \$0.00 | \$88.89 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| WA-00 | WASH COMPLETE VEHICLE | DON | P | N | GARAGE | 0.09 | \$10.75 | \$0.00 | \$0.00 | \$10.75 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.16 | 18.52 | 81.12 | 5.00 | 104.64 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|-----------------------|--------------|---------------------|---------------------|----------|------------|
| WA-00 | WASH COMPLETE VEHICLE | 12052187 | 05/01/2023 13:33:30 | 05/01/2023 13:38:58 | 0.09 | \$10.75 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 05/01/2023 13:29:23 | 05/01/2023 13:33:20 | 0.07 | \$7.77 |
| | | | | LABOR | | 18.52 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL | 9.42 | 8 | \$75.36 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 5.76 | 1 | \$5.76 |
| | | | | | PARTS | 81.12 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 46909

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,CW,RC/GC
MILEAGE-2837

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Washed unit

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 48160

| | | | | | | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|--------------|---|--|--|--|--|
| USING DEPT NO: | 507201 | OPENED DATE: | 09/11/2023 10:56:18 | LOCATION: | GARAGE - University Automotive Services | | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/28/2023 15:05:15 | METER 1 - M: | 4348 | METER 2 - H: | 5 | | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/28/2023 15:37:40 | IN-SERVICE DATE: | 07/18/2022 | | | | | | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | | | | | | | | |
| | | | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | | | | | | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|-------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 03-33-004 | REPLACE NEW SPARK PLUGS | DON | N | N | GARAGE | 0.14 | \$17.04 | \$4.25 | \$0.00 | \$21.29 |
| 10-36-014 | SERVICE GENERATOR | DON | N | N | GARAGE | 0.40 | \$46.87 | \$7.65 | \$0.00 | \$54.52 |
| 16-71 | TRANSPORT BODY | DON | A | N | GARAGE | 0.50 | \$59.00 | \$0.00 | \$0.00 | \$59.00 |
| 24-71 | REPAIR BODY | DON | A | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.17 | \$19.73 | \$0.00 | \$0.00 | \$19.73 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| WA-00 | WASH COMPLETE VEHICLE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|--------------|-------------------|------|--------|-------|------|--------|
| JOB COUNT: 7 | WORK ORDER TOTAL: | 1.21 | 142.64 | 11.90 | 5.00 | 159.54 |
|--------------|-------------------|------|--------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|-------------------------|--------------|---------------------|---------------------|----------|------------|
| 16-71 | TRANSPORT BODY | 11399745 | 09/28/2023 07:00:00 | 09/28/2023 07:30:00 | 0.50 | \$59.00 |
| 16-71 | TRANSPORT BODY | 11399745 | 09/28/2023 07:00:00 | 09/28/2023 07:30:00 | (0.50) | (\$59.00) |
| 16-71 | TRANSPORT BODY | 11399745 | 09/28/2023 07:00:00 | 09/28/2023 07:30:00 | 0.50 | \$59.00 |
| 10-36-014 | SERVICE GENERATOR | 11074414 | 09/27/2023 13:09:09 | 09/27/2023 13:32:59 | 0.40 | \$46.87 |
| 10-36-014 | SERVICE GENERATOR | 11074414 | 09/27/2023 13:09:09 | 09/27/2023 13:32:59 | (0.40) | (\$46.87) |
| 10-36-014 | SERVICE GENERATOR | 11074414 | 09/27/2023 13:09:09 | 09/27/2023 13:32:59 | 0.40 | \$46.87 |
| 03-33-004 | REPLACE NEW SPARK PLUGS | 11074414 | 09/27/2023 13:00:12 | 09/27/2023 13:08:52 | 0.14 | \$17.04 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 09/20/2023 07:48:20 | 09/20/2023 07:58:22 | 0.17 | \$19.73 |
| LABOR | | | | | | 142.64 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|-------------------|----------|--------------------------------|------------|----------|------------|
| 10-36-014 | SERVICE GENERATOR | 10W30TQT | OIL QT BOTTLE 10W30SEMI THOMAS | 7.65 | 1 | \$7.65 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|-------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 03-33-004 | REPLACE NEW SPARK PLUGS | NGK7131 | SPARK PLUG | 4.25 | 1 | \$4.25 |
| 10-36-014 | SERVICE GENERATOR | 10W30TQT | OIL QT BOTTLE 10W30SEMI THOMAS | 7.65 | (1) | (\$7.65) |
| 10-36-014 | SERVICE GENERATOR | 10W30TQT | OIL QT BOTTLE 10W30SEMI THOMAS | 7.65 | 1 | \$7.65 |
| | | | | | PARTS | 11.90 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 48160

Work Order Notes

(EHANNAH) pm-wipers- wash- Driver reports Cable hanging in rear end
(EKIMBREL) did not need wipers

Job Notes

03-33-004 - REPLACE NEW SPARK PLUGS

(SHARBIN) Replaced the spark plug due to wear. SH

03-51-038 - REPLACE NEW WIPER BLADES

06-02 - INSPECT CAB & SHEET METAL

10-36-014 - SERVICE GENERATOR

(SHARBIN) Generator came in with a no start. Found the oil level was low. Motor has a sensor that will not allow it to start if the oil level is low. Did not see any oil leak. Changed the oil and rechecked. Generator is starting and running good. Air filter is clean. SH
(AJONES) Visit Reason Changed On 9/28/2023 9:47 PM By AJONES

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by RC/CW
(AJONES) Visit Reason Changed On 9/28/2023 9:47 PM By AJONES

24-71 - REPAIR BODY

(LISAPATE) Andrews has not completed repairs. Closing work order due to fiscal year end will reopen Oct 1
(AJONES) Visit Reason Changed On 9/28/2023 9:47 PM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1614 miles since the last PM. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

CL-36-010 - CLEANED CARBURETOR

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed by SH

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 48476

| | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|----------------|
| USING DEPT NO: | 507201 | OPENED DATE: | 10/10/2023 07:29:39 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 10/10/2023 07:44:34 | METER 1 - M: | 4542 | METER 2 - H: 5 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 10/10/2023 10:04:13 | IN-SERVICE DATE: | 07/18/2022 | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|----------|----------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 24-71 | REPAIR BODY | DON | A | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$1,150.00 | \$1,150.00 |
| CH-SP | CHARGE Shop Supplies | DON | A | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|------|------|----------|----------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 1,155.00 | 1,155.00 |
|--------------|-------------------|------|------|------|----------|----------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | (\$5.75) |
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.75 |
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | (\$5.00) |
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| 24-71 | REPAIR BODY | 11150605 | 1697720 | | \$1,150.00 |
| | | | | COMML | 1155.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 48476

Work Order Notes

(LISAPATE) Previous work order closed due to fiscal year end

Job Notes

24-71 - REPAIR BODY

(IFALLS) Andrews repaired Body per estimate. Paid by State Auto Ck# 1001393924 on 9-29-23 \$3297.39. UA paid \$1000.00 ded on PO

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 10/18/2023 3:20 PM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 49782

| | | | | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|-------------------|---|--|--|
| USING DEPT NO: | 507201 | OPENED DATE: | 02/13/2024 07:12:58 | LOCATION: | GARAGE - University Automotive Services | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 02/14/2024 09:04:41 | METER 1 - M: | 5542 | METER 2 - H: | 5 | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 02/14/2024 10:54:14 | IN-SERVICE DATE: | 07/18/2022 | | | | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | | | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|---------------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.03 | \$2.95 | \$16.65 | \$0.00 | \$19.60 |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE | DON | P | N | GARAGE | 0.57 | \$67.78 | \$0.00 | \$0.00 | \$67.78 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.11 | \$12.88 | \$68.40 | \$0.00 | \$81.28 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| WA-00 | WASH COMPLETE VEHICLE | DON | P | N | GARAGE | 0.13 | \$14.75 | \$0.00 | \$0.00 | \$14.75 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 5 | WORK ORDER TOTAL: | 0.83 | 98.36 | 85.05 | 5.00 | 188.41 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--|--------------|---------------------|---------------------|----------|------------|
| WA-00 | WASH COMPLETE VEHICLE | 12395904 | 02/13/2024 09:07:30 | 02/13/2024 09:15:00 | 0.13 | \$14.75 |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE INSPECTION | 12395904 | 02/13/2024 08:32:33 | 02/13/2024 09:07:01 | 0.57 | \$67.78 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 12395904 | 02/13/2024 08:30:34 | 02/13/2024 08:32:04 | 0.03 | \$2.95 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 02/13/2024 08:23:38 | 02/13/2024 08:30:11 | 0.11 | \$12.88 |
| LABOR | | | | | | 98.36 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|-----------------------------|------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 22-1 | WIPER BLADE 22" TRICO EXACT | 8.33 | 2 | \$16.65 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 5.76 | 1 | \$5.76 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL | 7.83 | 8 | \$62.64 |
| PARTS | | | | | | 85.05 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 49782

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Rotate tires and check Brakes f 10 m R 10 m fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Was fc

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 50296

| | | | | | | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|--------------|---|--|--|--|--|
| USING DEPT NO: | 507201 | OPENED DATE: | 03/26/2024 13:13:30 | LOCATION: | GARAGE - University Automotive Services | | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 04/09/2024 14:24:17 | METER 1 - M: | 6071 | METER 2 - H: | 5 | | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 04/16/2024 14:10:09 | IN-SERVICE DATE: | 07/18/2022 | | | | | | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | | | | | | | | |
| | | | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | | | | | | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|-----------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 17-02-076 | RECALL WINDSHIELD WIPER MOTOR | DON | R | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 17-79-001 | RECALL AIR BAG | DON | R | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 17-GA-005 | RECALL Scheduling and Preparation | DON | N | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|--------------|-------------------|------|------|------|------|------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
|--------------|-------------------|------|------|------|------|------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|-----------|-------------------------------|------------|-------------|--------------------|------------|
| 17-02-076 | RECALL WINDSHIELD WIPER MOTOR | 11099772 | 100625307 | | \$0.00 |
| COMML | | | | | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 50296

Work Order Notes

(EHANNAH) recall for wiper motor
(LISAPATE)

Job Notes

17-02-076 - RECALL WINDSHIELD WIPER MOTOR

(LISAPATE) Per vendor inspect wiper motor and replace wiper motor per recall-

17-79-001 - RECALL AIR BAG

(LISAPATE) Per vendor inspect harness and secure harness per recall.

17-GA-005 - RECALL Scheduling and Preparation

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 51392

| | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|----------------|
| USING DEPT NO: | 507201 | OPENED DATE: | 07/08/2024 07:46:46 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 07/08/2024 11:52:33 | METER 1 - M: | 7078 | METER 2 - H: 5 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 07/08/2024 13:25:35 | IN-SERVICE DATE: | 07/18/2022 | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|-----------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.01 | \$0.98 | \$0.00 | \$0.00 | \$0.98 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$1.54 | \$1.54 |
| WA-00 | WASH COMPLETE VEHICLE | DON | P | N | GARAGE | 0.00 | \$0.56 | \$0.00 | \$0.00 | \$0.56 |

| | | | | | | |
|--------------|-------------------|------|------|------|------|------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.01 | 1.54 | 0.00 | 1.54 | 3.08 |
|--------------|-------------------|------|------|------|------|------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$1.54 |
| | | | | COMML | 1.54 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|-----------------------|--------------|---------------------|---------------------|----------|------------|
| WA-00 | WASH COMPLETE VEHICLE | 12395904 | 07/08/2024 08:34:08 | 07/08/2024 08:34:25 | 0.00 | \$0.56 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 07/08/2024 08:33:16 | 07/08/2024 08:33:46 | 0.01 | \$0.98 |
| | | | | | LABOR | 1.54 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 51392

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 52904

| | | | | | | | | | | | |
|------------------|---------------|--------------------|---------------------|-------------------|---|--------------|---|--|--|--|--|
| USING DEPT NO: | 507201 | OPENED DATE: | 11/25/2024 07:42:59 | LOCATION: | GARAGE - University Automotive Services | | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 11/26/2024 11:33:49 | METER 1 - M: | 9009 | METER 2 - H: | 5 | | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 11/27/2024 07:31:30 | IN-SERVICE DATE: | 07/18/2022 | | | | | | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | | | | | | | | |
| | | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | | | | | | | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|---------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.00 | \$0.00 | \$21.69 | \$0.00 | \$21.69 |
| 66-79-003 | PERFORM SAFETY INSPECTION | DON | Y | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$83.36 | \$0.00 | \$83.36 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|------|--------|------|--------|
| JOB COUNT: 4 | WORK ORDER TOTAL: | 0.00 | 0.00 | 105.05 | 5.00 | 110.05 |
|--------------|-------------------|------|------|--------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|---------------------|------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.85 | 2 | \$21.69 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 12.32 | 1 | \$12.32 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL | 8.88 | 8 | \$71.04 |
| PARTS | | | | | | 105.05 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 52904

Work Order Notes

(EHANNAH) pm- Si - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Installed new wiper blades

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ- Performed SI.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM service. Changed oil, set tire pressure to spec, recorded tread depth readings & build dates, topped off fluids.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 54496

| | | | | | | | | | | | |
|------------------|------------------|--------------------|---------------------|------------------|---|-------------------|---|--|--|--|--|
| USING DEPT NO: | 507201 | OPENED DATE: | 04/16/2025 09:42:16 | LOCATION: | GARAGE - University Automotive Services | | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 04/16/2025 12:52:06 | METER 1 - M: | 10383 | METER 2 - H: | 5 | | | | |
| WO VISIT REASON: | PREVENTIVE MAINT | CLOSED DATE: | 04/17/2025 09:23:59 | IN-SERVICE DATE: | 07/18/2022 | | | | | | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | | | | | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|-------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| JOB COUNT: 1 | | | | | | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 54496

Work Order Notes

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) perform PM, fluid check only

JR- checked tread depths and date codes

CM- checked fluids, checked air filters, checked tire pressures, changed sticker, reset oil light, filled up washer fluid

10383 miles, 1375 miles

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 56172

| | | | | | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|--------------|---|--|--|-------------------|
| USING DEPT NO: | 507201 | OPENED DATE: | 08/29/2025 10:56:11 | LOCATION: | GARAGE - University Automotive Services | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 08/29/2025 12:35:58 | METER 1 - M: | 11620 | METER 2 - H: | 5 | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 08/29/2025 13:58:47 | IN-SERVICE DATE: | 07/18/2022 | | | | | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | UNIT SERIAL NO: | | | | | | | 1FTFW1E50NFB29430 |
| | | | | | | | | | | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|---------------------------------|-------------|------------|-------------|----------------|-------------------|--------------|-----------------|-------------------|-------------------|
| 25-78-047 | REMOVE SUPER SIDE TOOL BOX ASSY | DON | 5 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| JOB COUNT: 1 | | | | | | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 56172

Work Order Notes

(EHANNAH) remove tool box from this one and place his new vehilce

Job Notes

25-78-047 - REMOVE SUPER SIDE TOOL BOX ASSY

(GARAGE) CQ,GC- swapped tool box off of unit 4336C and installed it on other unit that was construction admins old truck they got ride of

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 56227

| | | | | | | | | | | | |
|------------------|---------------|--------------------|---------------------|------------------|---|-------------------|---|--|--|--|--|
| USING DEPT NO: | 507201 | OPENED DATE: | 09/04/2025 13:05:44 | LOCATION: | GARAGE - University Automotive Services | | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/08/2025 11:02:49 | METER 1 - M: | 11901 | METER 2 - H: | 5 | | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/08/2025 15:20:53 | IN-SERVICE DATE: | 07/18/2022 | | | | | | |
| TECH SPEC NO: | 22FORDF1504X4 | 2022 Ford F150 4X4 | | | UNIT SERIAL NO: | 1FTFW1E50NFB29430 | | | | | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|----------------------------------|-------------|------------|-------------|----------------|-------------------|--------------|-----------------|-------------------|-------------------|
| 25-34-022 | REMOVE STROBE LIGHT/BULB/MOTOR | DON | D | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| PD-00-999 | PREP DISPOSE PREPARE UNIT FOR DI | DON | D | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| JOB COUNT: 2 | | | | | | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 08:47:15 By User: GLOBETTI

UNIT NO: 244774 2022 FORD F150 4X4

WORK ORDER NO: 56227

Work Order Notes

(EHANNAH) prep for sale
(EKIMBREL) remove strobe lights

Job Notes

25-34-022 - REMOVE STROBE LIGHT/BULB/MOTOR/ASSY

(GARAGE) 11901 miles, cm removed strobe light kit from vehicle removed front grill removed lights and wiring harness going to front of vehicle removed lights and wiring harness from rear cab, removed strobe light switch and wiring harness unit checked ok, 2 hours labor,

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) cm performed prep for sale 11901 miles unit checked ok,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Sep 15 2025 08:47:15 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244774') //Q=