

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 41252

USING DEPT NO:	507302	OPENED DATE:	10/07/2021 14:56:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/07/2021 14:58:22	METER 1 - M:	273	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/08/2021 08:19:15	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.00	118.00	0.00	0.00	118.00
--------------	-------------------	--	--	--	--	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
COMML					0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11915538	10/07/2021 14:56:42	10/07/2021 15:56:42	1.00	\$118.00
LABOR						118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 41252

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed by RC

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 41343

USING DEPT NO:	507302	OPENED DATE:	10/15/2021 14:55:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/22/2021 14:16:47	METER 1 - M:	307	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/23/2021 13:58:35	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.50	\$59.00	\$105.06	\$0.00	\$164.06
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	4.00	\$472.00	\$915.00	\$0.00	\$1,387.00
14-36-006	INSTALL COMPRESSOR	DON	O	N	GARAGE	1.00	\$118.00	\$295.76	\$0.00	\$413.76
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOC	DON	O	N	GARAGE	0.10	\$11.80	\$72.43	\$0.00	\$84.23
14-71-029	INSTALL LINEX BED LINER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$862.50	\$862.50
16-71-029	TRANSPORT LINEX BED LINER	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 7	WORK ORDER TOTAL:	6.10	719.80	1,388.25	864.50	2,972.55
--------------	-------------------	------	--------	----------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
14-71-029	INSTALL LINEX BED LINER	11177989	9638		\$862.50
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					864.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	11/22/2021 07:00:00	11/22/2021 11:00:00	4.00	\$472.00
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	11074414	11/22/2021 07:00:00	11/22/2021 07:06:00	0.10	\$11.80
14-36-006	INSTALL COMPRESSOR	11213180	11/22/2021 11:00:00	11/22/2021 12:00:00	1.00	\$118.00
14-02-013	INSTALL FLOOR COVERINGS	11074414	11/22/2021 07:00:00	11/22/2021 07:30:00	0.50	\$59.00
16-71-029	TRANSPORT LINEX BED LINER	11915538	11/22/2021 07:00:00	11/22/2021 07:30:00	0.50	\$59.00
LABOR						719.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT40074	2 X 1 X 3 HITCH BALL	15.17	1	\$15.17
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45840	2" BALL MOUNT	19.94	1	\$19.94
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45405	RECEIVER REDUCER 2.5 TO 2 IN	18.57	1	\$18.57
14-36-006	INSTALL COMPRESSOR	3514854	PADLOCK	23.99	1	\$23.99

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-36-006	INSTALL COMPRESSOR	3514707	CABLE	15.99	1	\$15.99
14-36-006	INSTALL COMPRESSOR	B02419745	EYE BOLTS W/NUTS	8.82	1	\$8.82
14-36-006	INSTALL COMPRESSOR	NUT	NUT	0.98	2	\$1.95
14-36-006	INSTALL COMPRESSOR	MIL100232	COMPRESSOR OIL	20.31	2	\$40.62
14-36-006	INSTALL COMPRESSOR	MILS727	MALE AIR HOSE COUPLER	3.79	1	\$3.79
14-36-006	INSTALL COMPRESSOR	GAT27489	AIR SERVICE HOSE	98.31	2	\$196.62
14-36-006	INSTALL COMPRESSOR	MILS728	1/4 NPT FEM M-TYPE PLUG	3.98	1	\$3.98
14-02-013	INSTALL FLOOR COVERINGS	HC3Z2513086CB	FLOOR MATS	105.06	1	\$105.06
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT23021	BRASS COUPLER LOCK W/KEYS	18.75	1	\$18.75
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VJC3Z13C788A	STROBE LIGHT KIT-FORD	915.00	1	\$915.00
					PARTS	1388.25

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 41343

Work Order Notes

(LISAPATE) New Shop truck

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(LISAPATE) SH installed floor mats

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) MS installed strobe lights

14-36-006 - INSTALL COMPRESSOR

(LISAPATE) MS installed air compressor

14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK

(LISAPATE) SH installed receiver and pin

14-71-029 - INSTALL LINEX BED LINER

(LISAPATE) LineX installed bed liner PD by CC

16-71-029 - TRANSPORT LINEX BED LINER

(LISAPATE) Truck was taken to LineX by RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42386

USING DEPT NO:	507302	OPENED DATE:	02/17/2022 10:01:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2022 13:20:24	METER 1 - M:	494	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 08:12:14	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-066	INSTALL TRAILER 4WIRE FLAT/7 PIN CC	DON	O	N	GARAGE	0.10	\$11.80	\$16.44	\$0.00	\$28.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.10	11.80	16.44	2.00	30.24
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-51-066	INSTALL TRAILER 4WIRE FLAT/7 PIN CONN	10208562	02/17/2022 10:03:11	02/17/2022 10:09:11	0.10	\$11.80
LABOR						11.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-066	INSTALL TRAILER 4WIRE FLAT/7 PIN CONN	HOP47375	7 TO 5 PIN ADAPTER	16.44	1	\$16.44
PARTS						16.44

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42386

Work Order Notes

(EKIMBREL) 7 PIN TO 5 WIRE ADAPTER

Job Notes

14-51-066 - INSTALL TRAILER 4WIRE FLAT/7 PIN CONN

(EKIMBREL) EK INSTALL ADAPTER

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42407

USING DEPT NO:	507302	OPENED DATE:	02/18/2022 13:47:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2022 15:19:59	METER 1 - M:	672	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2022 15:19:59	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.22	\$0.00	\$0.00	\$20.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.17 20.22 0.00 2.00 22.22

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/22/2022 07:47:33	02/22/2022 08:02:33	0.25	\$29.50
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/22/2022 07:47:33	02/22/2022 08:02:33	(0.25)	(\$29.50)
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/22/2022 07:37:16	02/22/2022 07:47:33	0.17	\$20.22
LABOR						20.22

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42407

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 672 miles. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-672

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 43819

USING DEPT NO:	507302	OPENED DATE:	07/05/2022 08:09:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/08/2022 11:03:09	METER 1 - M:	1219	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 08:52:33	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.43	\$59.10	\$0.00	\$92.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.28	33.43	59.10	2.00	94.53
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/06/2022 13:54:44	07/06/2022 14:11:44	0.28	\$33.43
LABOR						33.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	7.50	7	\$52.50
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	6.60	1	\$6.60
PARTS						59.10

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 43819

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 44679

USING DEPT NO:	507302	OPENED DATE:	09/13/2022 15:18:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/14/2022 07:37:55	METER 1 - M:	1257	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/14/2022 13:14:44	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOC	DON	O	N	GARAGE	0.10	\$11.80	\$539.78	\$0.00	\$551.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.10 11.80 539.78 5.00 556.58

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	11915538	09/14/2022 07:00:00	09/14/2022 07:06:00	0.10	\$11.80
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	10208562	09/14/2022 07:00:00	09/14/2022 07:06:00	(0.10)	(\$11.80)
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	10208562	09/14/2022 07:00:00	09/14/2022 07:06:00	0.10	\$11.80
LABOR						11.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45902	ADJ CHANNEL MOUNT HD 2-2 5/16	539.78	1	\$539.78
PARTS						539.78

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 44679

Work Order Notes

(EKIMBREL) INSTALL CHANNEL MOUNT

Job Notes

14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK

(LISAPATE) RC installed new trailer hitch

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 44708

USING DEPT NO:	507302	OPENED DATE:	09/16/2022 14:44:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/19/2022 09:49:11	METER 1 - M:	1257	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/19/2022 13:41:12	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-051	INSTALL SEAT COVER	DON	O	N	GARAGE	0.50	\$59.00	\$361.05	\$0.00	\$420.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.50	59.00	361.05	5.00	425.05
--------------	-------------------	--	--	--	--	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-02-051	INSTALL SEAT COVER	11915538	09/16/2022 14:46:28	09/16/2022 15:16:28	0.50	\$59.00
LABOR						59.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-02-051	INSTALL SEAT COVER	VFL3Z25600D20D	SEAT COVER SET FRONT	361.05	1	\$361.05
PARTS						361.05

Work Order Charge Detail

UNIT NO:	244317	2021 FORD F250 SERVICE BODY	WORK ORDER NO:	44708
----------	--------	-----------------------------	----------------	-------

Work Order Notes

(EKIMBREL) install front seat cover

Job Notes

14-02-051 - INSTALL SEAT COVER

(EKIMBREL) rc installed seat cover

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 45450

USING DEPT NO:	507302	OPENED DATE:	12/06/2022 08:07:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/08/2022 11:23:45	METER 1 - M:	1963	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/08/2022 13:58:36	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.42	\$0.00	\$0.00	\$18.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.16	18.42	0.00	5.00	23.42
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/06/2022 09:44:12	12/06/2022 09:53:34	0.16	\$18.42
LABOR						18.42

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 45450

Work Order Notes

(LISAPATE) pm replace wiper blades
(GARAGE) wipers good-GC

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM- Fluid check only- GC checked tires and tire pressure, battery good
Miles- 1,963

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 45945

USING DEPT NO:	507302	OPENED DATE:	01/26/2023 15:42:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/31/2023 13:03:17	METER 1 - M:	2093	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/31/2023 13:50:19	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-51-043	RECALL WIPER ARM	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-51-043	RECALL WIPER ARM	11099772	100604926		\$0.00
				COMML	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: **244317** **2021 FORD F250 SERVICE BODY** **WORK ORDER NO:** **45945**

Work Order Notes

(CWIGLEY) Recall 22s26 for wiper assembly.

Job Notes

17-51-043 - RECALL WIPER ARM

(CWIGLEY) Long Lewis Ford Mobile Unit completed recall.

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 46771

USING DEPT NO:	507302	OPENED DATE:	04/20/2023 07:56:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/24/2023 11:21:59	METER 1 - M:	2823	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2023 13:05:44	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.08	\$9.21	\$0.00	\$0.00	\$9.21
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.60	\$70.37	\$0.00	\$0.00	\$70.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.91	\$57.71	\$0.00	\$76.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.34	\$39.92	\$0.00	\$0.00	\$39.92

JOB COUNT: 5	WORK ORDER TOTAL:	1.17	138.41	57.71	5.00	201.12
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/20/2023 09:30:00	04/20/2023 09:39:37	0.16	\$18.91
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/20/2023 09:19:07	04/20/2023 09:19:07	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/20/2023 09:39:50	04/20/2023 10:15:37	0.60	\$70.37
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/20/2023 10:15:47	04/20/2023 10:20:28	0.08	\$9.21
WA-00	WASH COMPLETE VEHICLE	11074414	04/20/2023 13:20:50	04/20/2023 13:41:08	0.34	\$39.92
				LABOR		138.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	7.40	7	\$51.77
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
					PARTS	57.71

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 46771

Work Order Notes

(EHANNAH) pm- replace wipers- do SI - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires adjusted the tire pressure relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front and rear brake pads measure 10MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 48386

USING DEPT NO:	507302	OPENED DATE:	10/03/2023 07:31:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/03/2023 15:35:09	METER 1 - M:	3968	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/04/2023 07:33:41	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.36	\$21.69	\$0.00	\$24.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.07	\$0.00	\$0.00	\$2.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.04	4.43	21.69	5.00	31.12
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/03/2023 08:54:15	10/03/2023 08:55:18	0.02	\$2.07
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/03/2023 08:51:57	10/03/2023 08:53:09	0.02	\$2.36
					LABOR	4.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
					PARTS	21.69

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 48386

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Closed FC

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 49828

USING DEPT NO:	507302	OPENED DATE:	02/16/2024 07:19:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/19/2024 12:27:58	METER 1 - M:	5124	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2024 12:45:26	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.80	\$72.90	\$0.00	\$96.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.29	\$34.45	\$0.00	\$0.00	\$34.45

JOB COUNT: 3	WORK ORDER TOTAL:	0.49	58.25	72.90	5.00	136.15
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	02/19/2024 09:30:00	02/19/2024 09:47:31	0.29	\$34.45
WA-00	WASH COMPLETE VEHICLE	11074414	02/19/2024 09:29:24	02/19/2024 09:29:24	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/19/2024 09:02:54	02/19/2024 09:15:00	0.20	\$23.80
LABOR						58.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	(1)	(\$13.52)
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	8.37	8	\$66.96
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	8.37	(7)	(\$58.59)
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	8.37	7	\$58.59
PARTS						72.90

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 49828

Work Order Notes

(EHANNAH) pm-wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 51839

USING DEPT NO:	507302	OPENED DATE:	08/16/2024 08:36:38	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	08/19/2024 09:38:02	METER 1 - M:	5834	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/19/2024 11:28:30	IN-SERVICE DATE:	10/07/2021						
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 51839

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PREFORMED PM CM MOTOR DID NOT NEED OIL CHANGED DID NOT HAVE ENOUGH MILES, CHECKED ALL FLUIDS VEHICLE CHECKED OK,

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) WASHED

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 53459

USING DEPT NO:	507302	OPENED DATE:	01/24/2025 09:56:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/28/2025 08:53:56	METER 1 - M:	6279	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2025 09:40:41	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.65	\$0.00	\$16.65
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$57.18	\$0.00	\$57.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	73.83	5.00	78.83
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	8	\$51.24
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
PARTS						73.83

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 53459

Work Order Notes

(EHANNAH) pm-wipers- SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JR- replaced wiper blades

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si cm rotated tire relearned tpms brake pads 10 mm checked ok,

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
6668 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 55207

USING DEPT NO:	507302	OPENED DATE:	06/25/2025 14:08:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/26/2025 10:06:32	METER 1 - M:	7655	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/26/2025 13:02:47	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
10-36-006	SERVICE COMPRESSOR	DON	P	N	GARAGE	0.00	\$0.00	\$37.88	\$0.00	\$37.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	37.88	5.00	42.88
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
10-36-006	SERVICE COMPRESSOR	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
10-36-006	SERVICE COMPRESSOR	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	8.61	1	\$8.61
10-36-006	SERVICE COMPRESSOR	BALPA4820	AIR FILTER ELEMENT SMALL ENGINE	17.37	1	\$17.37
10-36-006	SERVICE COMPRESSOR	NGK7131	SPARK PLUG	4.25	1	\$4.25
PARTS						37.88

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 55207

Work Order Notes

Job Notes

10-36-006 - SERVICE COMPRESSOR

(GARAGE) JR,GC- serviced compressor, drained engine oil and changed engine air filter and spark plug, checked compressor oil and it was good.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC,JR- PM, Fluid check only, checked fluids, filter good, tires and tire pressure, updated oil change sticker, reset oil life
Miles, 7,655

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 2021 FORD F250 SERVICE BODY WORK ORDER NO: 56163

USING DEPT NO:	507302	OPENED DATE:	08/29/2025 08:55:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/29/2025 09:15:49	METER 1 - M:	7830	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/29/2025 14:10:10	IN-SERVICE DATE:	10/07/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A69MED53198	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 09/05/2025 15:09:14 By User: GLOBETTI

UNIT NO: 244317 **2021 FORD F250 SERVICE BODY** **WORK ORDER NO:** 56163

Work Order Notes

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) cm performed prep for sale, 7830 miles, swapped strobe lights, air compressor, and all tools from service body to new truck,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Sep 05 2025 15:09:14 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244317') //Q=