

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 43403

USING DEPT NO:	507301	OPENED DATE:	05/25/2022 11:08:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/25/2022 11:10:49	METER 1 - M:	9	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/27/2022 14:48:41	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>	<b>1.00</b>	<b>118.00</b>	<b>0.00</b>	<b>2.00</b>	<b>120.00</b>
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11074414	05/25/2022 11:08:57	05/25/2022 12:08:57	1.00	\$118.00
					<b>LABOR</b>	<b>118.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 43403

## Work Order Notes

(LISAPATE) New unit do PDI

## Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 44635

USING DEPT NO:	507301	OPENED DATE:	09/09/2022 08:48:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/12/2022 10:49:39	METER 1 - M:	3813	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/12/2022 12:52:36	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.17	\$0.00	\$0.00	\$27.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.23	27.17	0.00	5.00	32.17
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/09/2022 13:37:10	09/09/2022 13:47:39	0.17	\$20.62
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/09/2022 13:13:34	09/09/2022 13:16:54	0.06	\$6.56
					LABOR	27.18

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 44635

---

## Work Order Notes

(CWIGLEY) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has 3813 miles on it will go to Toyota at 10,000 miles. Checked fluids battery tire pressure and updated the oil change sticker. SH

### CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 45457

USING DEPT NO:	507301	OPENED DATE:	12/06/2022 10:36:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2022 11:06:03	METER 1 - M:	9997	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/12/2022 07:43:16	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.20	23.60	0.00	5.00	28.60
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11076422	6185443		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11915538	12/12/2022 07:00:00	12/12/2022 07:12:00	0.20	\$23.60
					LABOR	23.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 45457

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Tuscaloosa Toyota completed 10,000 mile service for free

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 46429

USING DEPT NO:	507301	OPENED DATE:	03/09/2023 12:09:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/09/2023 15:33:49	METER 1 - M:	14670	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/10/2023 07:32:18	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.65	\$42.78	\$0.00	\$71.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	40.45	42.78	5.00	88.23
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12052187	03/09/2023 13:48:09	03/09/2023 13:54:09	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/09/2023 13:33:35	03/09/2023 13:48:09	0.24	\$28.65
				LABOR		40.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.35	5	\$36.75
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.03	1	\$6.03
					PARTS	42.78

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 46429

## Work Order Notes

(EHANNAH) pm- replace wiper- wash vehicle

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,CW/GC  
MILEAGE-14670

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Fleet do not wash



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 47163

USING DEPT NO:	507301	OPENED DATE:	05/24/2023 09:35:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2023 08:21:11	METER 1 - M:	18748	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/31/2023 11:34:35	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.36	\$24.06	\$0.00	\$28.42
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.29	\$34.55	\$0.00	\$0.00	\$34.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.49	\$77.64	\$0.00	\$129.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.03	\$3.21	\$22.73	\$0.00	\$25.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.79	93.61	124.43	5.00	223.04
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/24/2023 10:50:03	05/24/2023 11:07:37	0.29	\$34.55
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/24/2023 10:48:14	05/24/2023 10:49:52	0.03	\$3.21
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/24/2023 10:45:51	05/24/2023 10:48:04	0.04	\$4.36
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/24/2023 10:19:13	05/24/2023 10:45:24	0.44	\$51.49
				LABOR		93.61

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	14.37	5	\$71.85
				PARTS		124.43

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 47163

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) GC Replaced the wipers. SH

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated the tires and inspected the brakes. Found no issues at this time. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Performed PM. SH

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(SHARBIN) GC Replaced the cabin air filter. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 47591

USING DEPT NO:	507301	OPENED DATE:	07/13/2023 09:39:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/17/2023 11:44:25	METER 1 - M:	22462	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/17/2023 13:51:32	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6211804		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11915538	07/17/2023 07:00:00	07/17/2023 07:30:00	0.50	\$59.00
LABOR						59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 47591

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by RC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM done by Tuscaloosa Toyota for 20,000 mile service. No charge

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 47879

USING DEPT NO:	507301	OPENED DATE:	08/10/2023 13:34:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/14/2023 13:09:45	METER 1 - M:	24316	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2023 12:09:02	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	O	N	GARAGE	0.11	\$13.18	\$0.00	\$0.00	\$13.18
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.23	\$27.70	\$232.83	\$0.00	\$260.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.35	40.88	232.83	5.00	278.71
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/11/2023 15:38:18	08/11/2023 15:52:23	0.23	\$27.70
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	08/11/2023 10:21:03	08/11/2023 10:27:45	0.11	\$13.18
				LABOR		40.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	11.82	1	\$11.82
66-17-028	PERFORM MOUNT AND BALANCE TIRES	17537	TIRE 215/55R17 MICH DEF2	220.50	1	\$220.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	2	\$0.51
				PARTS		232.83

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 47879

## Work Order Notes

(EHANNAH) low tire pressure light is on, they don't know which tire it is.

## Job Notes

### 06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) Found the left rear tire at 23 pounds. It has a screw in it to close to the side wall to patch. it will have to be replaced. SH

### 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 1 tire. SH

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 48775

USING DEPT NO:	507301	OPENED DATE:	10/31/2023 10:15:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2023 10:09:17	METER 1 - M:	28493	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2023 13:17:22	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$29.50	\$24.08	\$0.00	\$53.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.47	\$49.88	\$0.00	\$69.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.42	48.97	73.96	5.00	127.93
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/01/2023 07:00:00	11/01/2023 07:15:00	0.25	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/31/2023 13:27:34	10/31/2023 13:37:28	0.17	\$19.47
					LABOR	48.97

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.07	1	\$8.07
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.07	(1)	(\$8.07)
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.49	5	\$42.45
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.43	1	\$7.43
					PARTS	73.96

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 48775

## Work Order Notes

(EHANNAH) pm- wash

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) replaced wipers SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM. SH

**CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 50030

USING DEPT NO:	507301	OPENED DATE:	03/01/2024 13:03:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/05/2024 07:41:51	METER 1 - M:	33082	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/05/2024 10:50:09	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$31.04	\$42.53	\$0.00	\$73.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.26	31.04	42.53	5.00	78.57
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/04/2024 09:33:49	03/04/2024 09:49:36	0.26	\$31.04
					LABOR	31.04

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					PARTS	42.53

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 50030

## Work Order Notes

(EHANNAH) pm

## Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil cheged fc

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 51223

USING DEPT NO:	507301	OPENED DATE:	06/17/2024 10:57:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/17/2024 15:31:16	METER 1 - M:	38345	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/20/2024 07:29:01	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.57	\$24.11	\$0.00	\$25.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.15	\$43.79	\$0.00	\$44.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.72	67.90	5.00	75.62
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12395904	06/17/2024 15:15:02	06/17/2024 15:15:50	0.01	\$1.57
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/17/2024 15:14:05	06/17/2024 15:14:40	0.01	\$1.15
					LABOR	2.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.89	1	\$6.89
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
					PARTS	67.90

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 51223

## Work Order Notes

(EHANNAH) pm- wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers fc

### 66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 52111

USING DEPT NO:	507301	OPENED DATE:	09/12/2024 09:21:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/16/2024 14:13:48	METER 1 - M:	42282	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2024 14:56:09	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$43.44	\$0.00	\$43.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	43.44	5.00	48.44
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.32	5	\$36.60
					PARTS	43.44

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 52111

## Work Order Notes

(EHANNAH) pm- SI

## Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) cm 42282 miles, changed motor oil and filter, checked all fluids checked ok checked over vehicle checked ok

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 52938

USING DEPT NO:	507301	OPENED DATE:	12/02/2024 09:45:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/03/2024 11:07:47	METER 1 - M:	46245	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/03/2024 12:56:52	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$83.23	\$0.00	\$83.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$34.07	\$0.00	\$34.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	141.38	5.00	146.38
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	32.15	1	\$32.15
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.30	5	\$41.48
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	34.07	1	\$34.07
					PARTS	141.38

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 52938

## Work Order Notes

(EHANNAH) wipers- pm

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- Replaced wiper blades.

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) JR-perform SI per SI sheet

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- Top

JR- Bottom

FJ- Set tire pressure to spec., recorded tread depths & date codes, and topped off all fluids.

JR- Drained oil, swapped oil filter.

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(GARAGE) JR- Replaced cabin filter.

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 54015

USING DEPT NO:	507301	OPENED DATE:	03/07/2025 09:02:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2025 12:06:44	METER 1 - M:	51024	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/17/2025 09:13:27	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.31	\$0.00	\$51.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	51.31	5.00	56.31
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.18	5	\$40.88
					PARTS	51.31

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 54015

## Work Order Notes

(EHANNAH) pm

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- topside

JR- pit

perform PM, changed oil and filter, checked air filters, checked fluids, checked tires and tire pressures, changed sticker, reset oil light  
51024 miles

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 54821

USING DEPT NO:	507301	OPENED DATE:	05/19/2025 11:56:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/19/2025 13:22:53	METER 1 - M:	55588	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/19/2025 14:58:24	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$56.55	\$0.00	\$56.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	56.55	5.00	61.55
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
					PARTS	56.55

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 54821

---

## Work Order Notes

(CWIGLEY) PM

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) GC- Oil change

FJ- Top (added oil, checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths)

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 55230

USING DEPT NO:	507301	OPENED DATE:	07/01/2025 08:12:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/08/2025 10:08:34	METER 1 - M:	57246	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/08/2025 15:29:43	IN-SERVICE DATE:	05/19/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU053209	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$914.19	\$914.19
16-00	TRANSPORT COMPLETE VEHICLE	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	0.00	919.19	919.19
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2129033		\$914.19
03-02-061	REPLACE NEW WINDSHIELD	11078716	2129033		\$914.19
03-02-061	REPLACE NEW WINDSHIELD	11078716	2129033		(\$914.19)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	919.19

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 55230

## Work Order Notes

(CHANNELL) replace windshield

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(EKIMBREL) glass dr replaced windshield

### **16-00 - TRANSPORT COMPLETE VEHICLE**

(EKIMBREL) rc/cw transported vehicle to and from vendor

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 56332

USING DEPT NO:	507301	OPENED DATE:	09/10/2025 14:42:23	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	COMPLETED	COMPLETED DATE:	09/11/2025 10:19:02	METER 1 - M:	60000	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	05/19/2022						
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry			UNIT SERIAL NO:	4T1C11AK9NU053209					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/11/2025 15:49:31 By User: GLOBETTI

UNIT NO: 244636 2022 TOYOTA CAMRY

WORK ORDER NO: 56332

## Work Order Notes

(EHANNAH) prep for sale

## Job Notes

### **25-52-021 - REMOVE GPS SYSTEM**

(EHOWELL) JR removed GPS S/N: 87B010630224

### **PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) JR- prepped vehicle for sale, removed GPS  
GPS S/N: 87B010630224



# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Thu Sep 11 2025 15:49:31 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '244636') //Q=