

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 44138

USING DEPT NO:	507301	OPENED DATE:	08/01/2022 10:53:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/05/2022 14:29:30	METER 1 - M:	9	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/08/2022 10:53:28	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.00	118.00	0.00	2.00	120.00
--------------	-------------------	--	--	--	--	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12052187	08/05/2022 07:00:00	08/05/2022 08:00:00	1.00	\$118.00
LABOR						118.00

# Work Order Charge Detail

UNIT NO:2448092022 TOYOTA CAMRY

WORK ORDER NO:44138

Work Order Notes

(LISAPATE)  
(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 44205

USING DEPT NO:	507301	OPENED DATE:	08/05/2022 15:27:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/18/2022 11:04:19	METER 1 - M:	9	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/18/2022 12:49:12	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-42-014	WARRANTY HEATER CORE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.65	76.70	0.00	2.00	78.70
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-42-014	WARRANTY HEATER CORE	11076422	6170499		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-42	DIAGNOSE COOLING SYSTEM	11213180	08/18/2022 07:00:00	08/18/2022 07:09:00	0.15	\$17.70
16-42	TRANSPORT COOLING SYSTEM	11915538	08/18/2022 07:00:00	08/18/2022 12:00:00	5.00	\$590.00
16-42	TRANSPORT COOLING SYSTEM	11915538	08/18/2022 07:00:00	08/18/2022 12:00:00	(5.00)	(\$590.00)
16-42	TRANSPORT COOLING SYSTEM	11915538	08/18/2022 07:00:00	08/18/2022 07:30:00	0.50	\$59.00
					LABOR	76.70

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 44205

## Work Order Notes

(LRUSHING) Per Mario unit is running hot

## Job Notes

### 15-42-014 - WARRANTY HEATER CORE

(LISAPATE) Toyota had towed to the dealership under warranty. they replaced heater core and coolant. Installed new carpet and padding. replaced accelerator pedal also was covered in coolant

### 16-42 - TRANSPORT COOLING SYSTEM

(LISAPATE) Picked up from Toyota by RC

### 35-42 - DIAGNOSE COOLING SYSTEM

(LRUSHING) MS verified coolant is low and leaking call dealership Tuscaloosa Toyota is having towed.

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 44951

USING DEPT NO:	507301	OPENED DATE:	10/11/2022 09:28:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2022 14:28:03	METER 1 - M:	3655	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2022 07:24:40	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.38	\$44.32	\$0.00	\$0.00	\$44.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.88	\$0.00	\$0.00	\$28.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.62	73.20	0.00	5.00	78.20
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	10/11/2022 13:44:15	10/11/2022 14:06:47	0.38	\$44.32
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/11/2022 13:23:15	10/11/2022 13:37:56	0.24	\$28.88
					LABOR	73.20

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 44951

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated tires and inspected brakes. Found no issues at this time. Front pads are 10MM. Rear pads are 8MM. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has 3655 miles on it. Will go to Toyota at 10,000 miles for service. Checked fluids battery tire pressure and updated the oil change sticker. SH

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 46459

USING DEPT NO:	507301	OPENED DATE:	03/20/2023 09:37:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/24/2023 14:21:21	METER 1 - M:	11376	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/24/2023 15:01:24	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	0.00	5.00	43.94
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6197436		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11915538	03/24/2023 07:00:00	03/24/2023 07:19:48	0.33	\$38.94
LABOR						38.94

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 46459

## Work Order Notes

(EHANNAH) pm= replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM - TRANSPORT PM SERVICE

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) tuscaloosa toyota performed 10k mile oil change

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 47093

USING DEPT NO:	507301	OPENED DATE:	05/17/2023 11:52:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/17/2023 15:36:26	METER 1 - M:	14658	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2023 07:11:37	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.08	\$41.34	\$0.00	\$97.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.48	56.08	41.34	5.00	102.42
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/17/2023 13:46:29	05/17/2023 14:15:00	0.48	\$56.08
					LABOR	56.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
					PARTS	41.34

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 47093

## Work Order Notes

(CWIGLEY) PM. Wash

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 14,658

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 47631

USING DEPT NO:	507301	OPENED DATE:	07/18/2023 12:51:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/21/2023 11:50:16	METER 1 - M:	19361	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/21/2023 12:42:14	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	0.00	5.00	43.94
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6212393		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11399745	07/21/2023 07:00:00	07/21/2023 07:19:48	0.33	\$38.94
16-33	TRANSPORT IGNITION SYSTEM	11399745	07/21/2023 07:00:00	07/21/2023 07:30:00	(0.50)	(\$59.00)
16-33	TRANSPORT IGNITION SYSTEM	11399745	07/21/2023 07:00:00	07/21/2023 07:30:00	0.50	\$59.00
LABOR						38.94

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 47631

## Work Order Notes

(CWIGLEY) PM, replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-33 - TRANSPORT IGNITION SYSTEM

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by CW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Pm done by Toyota 20,000 mile service no charge

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 48455

USING DEPT NO:	507301	OPENED DATE:	10/09/2023 11:25:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/10/2023 09:37:11	METER 1 - M:	24852	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/10/2023 09:37:16	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.15	\$19.60	\$0.00	\$22.75
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.74	\$87.35	\$0.00	\$0.00	\$87.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.56	\$51.59	\$0.00	\$87.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.07	126.06	71.19	5.00	202.25
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12395904	10/09/2023 14:30:00	10/09/2023 15:14:25	0.74	\$87.35
66-79-003	PERFORM SAFETY INSPECTION	12395904	10/09/2023 14:17:10	10/09/2023 14:17:10	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/09/2023 14:13:24	10/09/2023 14:15:00	0.03	\$3.15
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/09/2023 13:51:01	10/09/2023 14:09:06	0.30	\$35.56
				LABOR		126.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	9.09	5	\$45.45
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.14	1	\$6.14
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	(1)	(\$8.33)
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.27	1	\$11.27
					PARTS	71.19

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 48455

## Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(FCONTRER) Ranplaced new wipers fc

### **66-79-003 - PERFORM SAFETY INSPECTION**

(FCONTRER) Safety inspection good fc

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changed fluid check tires pressure and tread fc

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 49105

USING DEPT NO:	507301	OPENED DATE:	11/30/2023 13:09:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2023 10:39:07	METER 1 - M:	29260	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 10:39:10	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.13	\$57.73	\$0.00	\$73.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.14	16.13	57.73	5.00	78.86
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/30/2023 13:55:14	11/30/2023 14:03:26	0.14	\$16.13
					LABOR	16.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.91	5	\$39.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.77	1	\$10.77
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					PARTS	57.73

# Work Order Charge Detail

UNIT NO:2448092022 TOYOTA CAMRY

WORK ORDER NO:49105

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed FC -sh

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 50041

USING DEPT NO:	507301	OPENED DATE:	03/04/2024 08:33:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2024 14:33:46	METER 1 - M:	33052	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/05/2024 09:43:05	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$24.09	\$73.38	\$0.00	\$97.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.20	24.09	73.38	5.00	102.47
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/04/2024 11:39:37	03/04/2024 11:51:52	0.20	\$24.09
					LABOR	24.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	6	\$42.12
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	AIR FILTER	30.92	1	\$30.92
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	(6)	(\$42.12)
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.01	5	\$35.03
					PARTS	73.38

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 50041

## Work Order Notes

(EHANNAH) pm- wipers  
(EKIMBREL) did not need wiers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH FC/SH Performed PM. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 50910

USING DEPT NO:	507301	OPENED DATE:	05/22/2024 10:26:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2024 07:31:50	METER 1 - M:	37636	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/23/2024 08:29:10	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$19.61	\$0.00	\$19.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.05	\$44.33	\$0.00	\$45.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.01	1.05	63.94	5.00	69.99
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/22/2024 13:29:39	05/22/2024 13:30:11	0.01	\$1.05
03-51-038	REPLACE NEW WIPER BLADES	12201267	05/22/2024 12:15:17	05/22/2024 12:15:17	0.00	\$0.00
					LABOR	1.05

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.28	1	\$11.28
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
					PARTS	63.94

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 50910

## Work Order Notes

(EHANNAH) PM- WIPERS

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 51761

USING DEPT NO:	507301	OPENED DATE:	08/09/2024 14:24:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/17/2024 09:00:43	METER 1 - M:	41211	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/17/2024 09:05:00	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$43.37	\$0.00	\$43.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	43.37	5.00	48.37
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
	COMML				5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.31	5	\$36.53
	PARTS					43.37

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 51761

---

## Work Order Notes

(EHANNAH) pm

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 41,211

### CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 52896

USING DEPT NO:	507301	OPENED DATE:	11/22/2024 10:45:33	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/22/2024 15:39:39	METER 1 - M:	45600	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/25/2024 07:25:40	IN-SERVICE DATE:	07/28/2022						
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry			UNIT SERIAL NO:	4T1C11AK4NU072198					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$102.44	\$0.00	\$102.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	102.44	5.00	107.44
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	PC99237C	CABIN FILTER 2020 CAMRY	31.23	1	\$31.23
66-PM-PMA	PERFORM OIL CHANGE	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	26-1	WIPER BLADE	11.28	1	\$11.28
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.40	5	\$42.00
PARTS						102.44

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 52896

## Work Order Notes

(EHANNAH) pm-wipers- SI - inspect tire

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) CM/FJ. CM- Replaced passenger side wiper blade

FJ- Replaced driver side wiper blade

### **06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

(GARAGE) FJ- Inspected all tires for wear. All tires are measuring at 5/32 at this time. Tire pressure set to spec., (35 PSI). Rotated tires. LF, RF, & RR tires have date codes of 2022. LR has date code of 2122.

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) FJ- Performed SI.

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- Performed PM service. Set tire pressure to spec., recorded tread depths & date codes, and topped off all fluids, and changed oil.

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 53938

USING DEPT NO:	507301	OPENED DATE:	03/03/2025 12:59:32	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2025 15:06:42	METER 1 - M:	49963	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2025 08:07:47	IN-SERVICE DATE:	07/28/2022						
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry			UNIT SERIAL NO:	4T1C11AK4NU072198					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-71	INSPECT BODY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$1,285.38	\$0.00	\$1,285.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.31	\$0.00	\$51.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	1,336.69	5.00	1,341.69
--------------	-------------------	------	------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.90	4	\$11.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	318.45	4	\$1,273.80
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.18	5	\$40.88
PARTS						1336.69

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 53938

## Work Order Notes

(EHANNAH) pm- noise in tires like a whoop in FP

## Job Notes

### **06-15 - INSPECT STEERING**

(GARAGE) inspected steering cm checked ok,

### **06-71 - INSPECT BODY**

(GARAGE) inspected noise test drove found it was coming from tires, installed new set of tires test drove checked ok, 49964 cm  
(IFALLS) .25 labor for troubleshooting,

### **66-17-013 - PERFORM ALIGNMENT**

(GARAGE) performed alignment cm cq checked ok, test drove checked ok,

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) performed mounn and balance tire cq checked ok, 49963 miles,

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) GC- DROPPED OIL AND FILTER, INSTALLED NEW FILTER. CQ FILLED WITH OIL AND TOPPED OFF ALL FLUIDS, SERVICE STICKER. CM RECORDED TREAD DEPTH AND BUILD DATES.

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 54301

USING DEPT NO:	507301	OPENED DATE:	04/03/2025 10:25:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/03/2025 12:25:13	METER 1 - M:	52017	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2025 10:38:42	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$32.76	\$0.00	\$32.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	32.76	5.00	37.76
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	1	\$15.04
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	17.72	1	\$17.72
					PARTS	32.76

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI*

**UNIT NO:**                    **244809**                    **2022 TOYOTA CAMRY**

**WORK ORDER NO:**                    **54301**

---

## Work Order Notes

### Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- Replaced blades. Mileage is 52,017.

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 54727

USING DEPT NO:	507301	OPENED DATE:	05/09/2025 09:35:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/12/2025 09:27:23	METER 1 - M:	54781	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/12/2025 09:27:23	IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	48.90	5.00	53.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
					PARTS	48.90

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 54727

## Work Order Notes

(EHANNAH) pm

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(GARAGE) GC,JR- rotated tires and inspected brakes, brake pads are 8mm front and rear  
Miles, 54,782

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- top side, checked fluids, filters good, tires and tire pressure, reset oil life and installed oil change sticker.  
JR- filled with oil and checked oil level  
GC- bottom side, drained oil and changed oil filter  
Miles, 54,782

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 55232

USING DEPT NO:	507301	OPENED DATE:	07/01/2025 08:46:48	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/01/2025 14:34:37	METER 1 - M:	58549	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/03/2025 07:14:30	IN-SERVICE DATE:	07/28/2022				
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry			UNIT SERIAL NO:	4T1C11AK4NU072198			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-00	TRANSPORT COMPLETE VEHICLE	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-02-061	REPAIR WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$126.44	\$126.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	48.90	131.44	180.34
--------------	-------------------	------	------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-02-061	REPAIR WINDSHIELD	11078716	2-129049		\$126.44
24-02-061	REPAIR WINDSHIELD	11078716	2-129049		(\$126.44)
24-02-061	REPAIR WINDSHIELD	11078716	2-129049		\$126.44
COMML					131.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	39525	DRAIN PLUG TOYOTA	2.28	(1)	(\$2.28)
66-PM-PMA	PERFORM OIL CHANGE	39525	DRAIN PLUG TOYOTA	2.28	1	\$2.28
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
PARTS						48.90

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 55232

## Work Order Notes

(CHANNELL) pm

(CWIGLEY) Taking to Glass Doctor to get a rock chip repaired on the passenger side.

## Job Notes

### **16-00 - TRANSPORT COMPLETE VEHICLE**

(EHOWELL) The vehicle was driven to/from Glass Doctor. Typically Glass Doctor performs the repairs at our facility, however, we had another vehicle that was ready at GD so we sent two of our techs to their facility. (One tech to pickup the vehicle that was ready, and another tech to wait for 7357B to be repaired.)

### **24-02-061 - REPAIR WINDSHIELD**

(EHOWELL) Glass Doctor repaired three different spots on the windshield.

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) 58,795 miles

PM

JR- Checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths

FJ- Oil change & added new oil

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI

UNIT NO: 244809 2022 TOYOTA CAMRY

WORK ORDER NO: 56358

USING DEPT NO:	507301	OPENED DATE:	09/12/2025 07:52:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	62638	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	07/28/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4NU072198	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 09/16/2025 09:25:14 By User: GLOBETTI*

**UNIT NO:**                    **244809**                    **2022 TOYOTA CAMRY**

**WORK ORDER NO:**                    **56358**

---

**Work Order Notes**

(EHANNAH) PREP FOR SALE

---

**Job Notes**

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

---

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Tue Sep 16 2025 09:25:14 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '244809') //Q=