

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 43794

USING DEPT NO:	504103	OPENED DATE:	06/30/2022 08:40:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/30/2022 08:41:13	METER 1 - M:	145	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/01/2022 14:15:00	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	0.00	118.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
COMML					0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11213180	06/30/2022 08:41:02	06/30/2022 09:41:02	1.00	\$118.00
LABOR						118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 43794

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed MS

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 43877

USING DEPT NO:	504103	OPENED DATE:	07/07/2022 15:10:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/07/2022 15:11:13	METER 1 - M:	145	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 09:51:16	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	2.00	120.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11213180	07/07/2022 15:10:43	07/07/2022 16:10:43	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 43877

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed by MS

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 43964

USING DEPT NO:	504103	OPENED DATE:	07/13/2022 13:33:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2022 08:09:04	METER 1 - M:	161	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/15/2022 09:22:22	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.03	\$3.77	\$215.67	\$0.00	\$219.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.03	3.77	215.67	2.00	221.44
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	11915538	07/13/2022 13:42:24	07/13/2022 13:44:19	0.03	\$3.77
					LABOR	3.77

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	ML3Z1613300CA	FLOOR MATS	215.67	1	\$215.67
					PARTS	215.67

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 43964

Work Order Notes

(LISAPATE) Install floor mats

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(EKIMBREL) FLOOR MATS ARE FROM FORD REWARDS
(GARAGE) INSTALLED FLOOR COVERINGS\RC

14-52-021 - INSTALL GPS SYSTEM

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 44518

USING DEPT NO:	504103	OPENED DATE:	08/30/2022 14:52:13	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2022 07:22:17	METER 1 - M:	725	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/01/2022 10:39:43	IN-SERVICE DATE:	06/29/2022				
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E51NFB29548			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-71-029	INSTALL LINEX BED LINER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$595.13	\$595.13
16-00	TRANSPORT COMPLETE VEHICLE	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.50	59.00	0.00	600.13	659.13
--------------	-------------------	--	--	--	--	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
14-71-029	INSTALL LINEX BED LINER	11177989	9992		\$595.13
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					600.13

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-00	TRANSPORT COMPLETE VEHICLE	11915538	08/30/2022 14:59:33	08/30/2022 15:29:33	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 44518

Work Order Notes

(EKIMBREL) install bedliner

Job Notes

14-71-029 - INSTALL LINEX BED LINER

(EKIMBREL) line-x installed bedliner

16-00 - TRANSPORT COMPLETE VEHICLE

(EKIMBREL) rc transported vehicle to line-x

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 44612

USING DEPT NO:	504103	OPENED DATE:	09/08/2022 10:03:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2022 08:50:59	METER 1 - M:	725	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2022 09:55:37	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-27	WARRANTY TRANSMISSION - MAIN, AL	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-27	TRANSPORT TRANSMISSION - MAIN, A	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-27	DIAGNOSE TRANSMISSION - MAIN, AU	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.75	88.50	0.00	5.00	93.50
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-27	WARRANTY TRANSMISSION - MAIN, AUTOMATIC	11078175	103851		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-27	DIAGNOSE TRANSMISSION - MAIN, AUTOMATIC	11213180	09/22/2022 07:00:00	09/22/2022 07:15:00	0.25	\$29.50
16-27	TRANSPORT TRANSMISSION - MAIN, AUTOMATIC	11915538	09/22/2022 07:00:00	09/22/2022 07:30:00	0.50	\$59.00
LABOR						88.50

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 44612

Work Order Notes

(CWIGLEY) Diagnose transmission.

Job Notes

15-27 - WARRANTY TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Ford verified Concern, no DTS's. performed transmission strategy down load and adaptive learning drive cycle. Unit still had harsh 4-3 down shift. Over hauled main control assy. Filled unit with new ULV fluid and set level. Performed adaptive learning drive cycle. Road tested and verified repair

16-27 - TRANSPORT TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Taken to Tuscaloosa Ford by RC

35-27 - DIAGNOSE TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Truck is shifting hard take to dealer to check transmission under warranty

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 45291

USING DEPT NO:	504103	OPENED DATE:	11/16/2022 13:16:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/18/2022 11:30:37	METER 1 - M:	2154	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/22/2022 08:17:44	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.75	\$93.80	\$0.00	\$118.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.21	24.75	93.80	5.00	123.55
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/17/2022 09:31:50	11/17/2022 09:44:25	0.21	\$24.75
					LABOR	24.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	10.68	8	\$85.44
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	10.68	(6)	(\$64.08)
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.36	1	\$8.36
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	10.68	6	\$64.08
					PARTS	93.80

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 45291

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 46770

USING DEPT NO:	504103	OPENED DATE:	04/20/2023 07:50:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/24/2023 11:45:04	METER 1 - M:	4266	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2023 13:03:31	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.38	\$44.38	\$0.00	\$0.00	\$44.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.48	\$79.39	\$0.00	\$117.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.38	\$44.84	\$0.00	\$0.00	\$44.84

JOB COUNT: 4	WORK ORDER TOTAL:	1.08	127.70	79.39	5.00	212.09
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/20/2023 08:24:14	04/20/2023 08:46:48	0.38	\$44.38
WA-00	WASH COMPLETE VEHICLE	11074414	04/20/2023 08:48:16	04/20/2023 09:11:04	0.38	\$44.84
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/20/2023 08:02:54	04/20/2023 08:22:28	0.33	\$38.48
				LABOR		127.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.70	1	\$10.70
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	7.40	8	\$59.16
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	9.53	1	\$9.53
				PARTS		79.39

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 46770

Work Order Notes

(EHANNAH) pm- replace wipers - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 47261

USING DEPT NO:	504103	OPENED DATE:	06/05/2023 09:14:55	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/20/2023 12:57:45	METER 1 - M:	4794	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/20/2023 12:57:47	IN-SERVICE DATE:	06/29/2022				
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E51NFB29548			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,423.13	\$1,423.13
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	1,423.13	1,482.13
--------------	-------------------	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	1697510		(\$1,423.13)
24-71	REPAIR BODY	11150605	1697510		\$1,423.13
24-71	REPAIR BODY	11150605	1697510		\$1,423.13
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
					COMML 1423.13

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11915538	06/20/2023 07:00:00	06/20/2023 07:30:00	0.50	\$59.00
16-71	TRANSPORT BODY	11915538	06/20/2023 07:00:00	06/20/2023 07:30:00	0.50	\$59.00
16-71	TRANSPORT BODY	11915538	06/20/2023 07:00:00	06/20/2023 07:30:00	(0.50)	(\$59.00)
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 47261

Work Order Notes

(EHANNAH) transport to body shop for hood damage- department paying

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-71 - TRANSPORT BODY

(LISAPATE) Andrews repaired hood damage per the estimate. PD by PO
(AJONES) Visit Reason Changed On 6/26/2023 10:09 AM By AJONES

24-71 - REPAIR BODY

(LISAPATE) Taken to Andrews by RC/CW
(AJONES) Visit Reason Changed On 6/26/2023 10:09 AM By AJONES

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 6/26/2023 10:09 AM By AJONES

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 48279

USING DEPT NO:	504103	OPENED DATE:	09/21/2023 07:32:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2023 10:30:53	METER 1 - M:	6252	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2023 10:30:54	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$1.84	\$21.69	\$0.00	\$23.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.19	\$87.83	\$0.00	\$108.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.29	\$33.96	\$0.00	\$0.00	\$33.96

JOB COUNT: 4	WORK ORDER TOTAL:	0.47	55.99	109.52	5.00	170.51
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	09/21/2023 10:50:11	09/21/2023 11:07:27	0.29	\$33.96
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/21/2023 10:49:04	09/21/2023 10:50:00	0.02	\$1.84
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/21/2023 10:38:36	09/21/2023 10:48:52	0.17	\$20.19
				LABOR		55.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	12.35	1	\$12.35
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	8.72	8	\$69.72
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
				PARTS		109.52

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 48279

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 49910

USING DEPT NO:	504103	OPENED DATE:	02/23/2024 07:29:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/23/2024 10:13:16	METER 1 - M:	8272	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/26/2024 07:17:34	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.42	\$49.49	\$0.00	\$0.00	\$49.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$24.12	\$102.66	\$0.00	\$126.78
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.25	\$18.30	\$0.00	\$19.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.26	\$30.35	\$0.00	\$0.00	\$30.35

JOB COUNT: 5	WORK ORDER TOTAL:	0.89	105.21	120.96	5.00	231.17
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	02/23/2024 08:33:15	02/23/2024 08:48:41	0.26	\$30.35
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	02/23/2024 08:07:47	02/23/2024 08:32:57	0.42	\$49.49
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	02/23/2024 08:06:44	02/23/2024 08:07:22	0.01	\$1.25
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/23/2024 07:53:57	02/23/2024 08:06:13	0.20	\$24.12
				LABOR		105.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PA5642F	AIR FILTER	24.30	1	\$24.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC8214	CABIN FILTER	18.30	1	\$18.30
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	9.08	8	\$72.60
				PARTS		120.96

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 49910

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Rotate tires and check Brakes f 8m r 8m fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform iol changed fc - ah

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced cabin filter fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 51047

USING DEPT NO:	504103	OPENED DATE:	06/05/2024 15:38:21	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 09:11:17	METER 1 - M:	9136	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 10:15:25	IN-SERVICE DATE:	06/29/2022				
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E51NFB29548			

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-05-046	RECALL ENGINE WIRING HARNESS	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 51047

Work Order Notes

(EHANNAH) prep and schedule- RECALL wiring harness

Job Notes

17-05-046 - RECALL ENGINE WIRING HARNESS

(EHANNAH) LL Ford came to our shop for Recall for wiring harness.

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise.

(LRUSHING) Visit Reason Changed On 6/26/2024 3:13 PM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 51593

USING DEPT NO:	504103	OPENED DATE:	07/24/2024 09:46:04	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/30/2024 09:08:36	METER 1 - M:	9630	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/30/2024 09:08:40	IN-SERVICE DATE:	06/29/2022				
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E51NFB29548			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.02	\$2.00	\$222.14	\$0.00	\$224.14
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.02	\$1.97	\$0.00	\$0.00	\$1.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.02	\$0.00	\$0.00	\$1.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.04	4.99	222.14	5.00	232.13
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/24/2024 15:32:19	07/24/2024 15:32:50	0.01	\$1.02
66-79-003	PERFORM SAFETY INSPECTION	12395904	07/25/2024 15:14:50	07/25/2024 15:15:50	0.02	\$1.97
03-32-002	REPLACE NEW BATTERY	12395904	07/25/2024 15:13:20	07/25/2024 15:14:21	0.02	\$2.00
LABOR						4.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	222.14	1	\$222.14
PARTS						222.14

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 51593

Work Order Notes

(EHANNAH) pm- wipers- Si- wash- inspect battery- having reoccurring trouble with it not cranking.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(FCONTRER) replaced new battery fc

03-51-038 - REPLACE NEW WIPER BLADES

06-32-002 - INSPECT BATTERY

66-79-003 - PERFORM SAFETY INSPECTION

(FCONTRER) perform safety inspection FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 52425

USING DEPT NO:	504103	OPENED DATE:	10/08/2024 14:04:16	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/11/2024 14:06:00	METER 1 - M:	10450	METER 2 - H:	0				
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	10/14/2024 10:33:51	IN-SERVICE DATE:	06/29/2022						
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4									
			UNIT SERIAL NO:	1FTFW1E51NFB29548							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,029.19	\$1,029.19
16-02-061	TRANSPORT WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	0.00	1,029.19	1,029.19
--------------	-------------------	--	--	--	--	------	------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2122201		\$1,029.19
COMML					1029.19

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 52425

Work Order Notes

(EHOWELL) Transport to Glass Doctor for windshield replacement.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(EHOWELL) Glass Doctor replaced windshield.

16-02-061 - TRANSPORT WINDSHIELD

(EHOWELL) The vehicle was driven from our facility to Glass Doctor. Glass Doctor had to send the vehicle to the dealership for recalibration. They delivered the vehicle back to our facility.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 53161

USING DEPT NO:	504103	OPENED DATE:	12/16/2024 13:28:27	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2024 14:04:51	METER 1 - M:	11298	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2024 14:33:24	IN-SERVICE DATE:	06/29/2022				
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E51NFB29548			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$71.21	\$0.00	\$71.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	71.21	5.00	76.21
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	8	\$51.24
PARTS						71.21

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 53161

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) did not need wipers

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked air filters, checked fluids, checked tires and tire pressures, changed sticker, reset maintenance light, filled up washer fluid
11298 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) vehicle clean

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 54021

USING DEPT NO:	504103	OPENED DATE:	03/17/2025 07:21:21	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/17/2025 09:02:33	METER 1 - M:	11939	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/18/2025 10:58:59	IN-SERVICE DATE:	06/29/2022						
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E51NFB29548					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.00	\$0.00	\$2.90	\$0.00	\$2.90
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$3.34	\$3.34

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	2.90	3.34	6.24
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$3.34
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.90)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.90
COMML					3.34

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.90	1	\$2.90
PARTS						2.90

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 54021

Work Order Notes

(EHANNAH) tire patch on FD

Job Notes

66-17-030 - PERFORM TIRE PATCH

(GARAGE) pulled in shop and checked for tire leak, found screw in driver side front tire. removed tire and patched tire, mounted tire and balanced checked found no leak. returned to service.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 54766

USING DEPT NO:	504103	OPENED DATE:	05/13/2025 12:05:03	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/13/2025 12:17:25	METER 1 - M:	12564	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/13/2025 14:48:18	IN-SERVICE DATE:	06/29/2022						
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E51NFB29548					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$30.09	\$0.00	\$30.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	30.09	5.00	35.09
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	25-220	BEAM WIPER BLADE	15.05	2	\$30.09
PARTS						30.09

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 54766

Work Order Notes

(EHANNAH) pm-wipers- customer was asked about a wash but it is raining and he wants to wait on it, so ihe declined

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) CQ- Replaced blades.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ/CQ- Fluid check. Mileage is 12564. 1266 miles since PM. Checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 55383

USING DEPT NO:	504103	OPENED DATE:	07/11/2025 13:26:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2025 14:06:55	METER 1 - M:	13056	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2025 15:36:07	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	N	N	GARAGE	0.00	\$0.00	\$387.96	\$0.00	\$387.96
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	387.96	5.00	392.96
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	ML3Z13405F	TAILLIGHT ASSEMBLY	387.96	1	\$387.96
PARTS						387.96

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 55383

Work Order Notes

(EHANNAH) replace new taillight

Job Notes

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

(GARAGE) JR- replace taillight assembly, all lights worked

0.15 hours

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 56801

USING DEPT NO:	504103	OPENED DATE:	10/14/2025 07:42:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/14/2025 09:03:47	METER 1 - M:	14443	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	10/14/2025 12:09:12	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$75.00	\$63.27	\$0.00	\$138.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.50	75.00	63.27	5.00	143.27
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	10/14/2025 09:03:28	10/14/2025 09:33:28	0.50	\$75.00
					LABOR	75.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SFFL500S	FL500S OIL FILTER - STIVERS	13.22	1	\$13.22
66-PM-PMA	PERFORM OIL CHANGE	SF5W30BT	5W30BT OIL - STIVERS	6.26	8	\$50.05
					PARTS	63.27

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 56801

Work Order Notes

(EHOWELL) PM

(EHOWELL) This vehicle is going to be sold.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) GC = dropped oil and filter and installed new filter. CQ = filled with oil and topped off all fluids, recorded tread depth and build dates and set tire pressure. installed new sticker and set oil life.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 56856

USING DEPT NO:	504103	OPENED DATE:	10/17/2025 10:10:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/17/2025 10:52:03	METER 1 - M:	14443	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2025 12:21:08	IN-SERVICE DATE:	06/29/2022	
TECH SPEC NO:	22FORDF1504X4	2022 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E51NFB29548	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	150.00	0.00	5.00	155.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	10/17/2025 10:22:49	10/17/2025 10:30:39	(0.13)	(\$19.58)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	10/17/2025 10:22:49	10/17/2025 10:30:39	0.13	\$19.58
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	10/17/2025 10:22:49	10/17/2025 11:22:49	1.00	\$150.00
				LABOR		150.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 08:49:48 By User: GLOBETTI

UNIT NO: 244718 2022 FORD F150 4X4

WORK ORDER NO: 56856

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) JR- prepped vehicle for sale, no GPS, no upfittings
14443 miles

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Oct 21 2025 08:49:48 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244718') //Q=