

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 40577

USING DEPT NO:	510301	OPENED DATE:	07/29/2021 15:08:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/02/2021 15:06:27	METER 1 - M:	125	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/03/2021 11:44:06	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOC	DON	O	N	GARAGE	0.07	\$8.19	\$18.75	\$0.00	\$26.94
14-71-029	INSTALL LINEX BED LINER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$595.13	\$595.13
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.21	\$24.68	\$0.00	\$0.00	\$24.68
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.27	\$149.86	\$0.00	\$0.00	\$149.86

JOB COUNT: 6	WORK ORDER TOTAL:	2.05	241.73	18.75	597.13	857.61
--------------	-------------------	------	--------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
14-71-029	INSTALL LINEX BED LINER	11177989	9562		\$595.13
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	597.13

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11170580	08/02/2021 07:00:00	08/02/2021 07:30:00	0.50	\$59.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	07/30/2021 07:19:24	07/30/2021 08:35:36	1.27	\$149.86
14-78-044	INSTALL TOOLBOX ASSY	11170580	07/30/2021 07:06:31	07/30/2021 07:19:04	0.21	\$24.68
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	11170580	07/30/2021 07:02:06	07/30/2021 07:06:16	0.07	\$8.19
				LABOR		241.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT23021	BRASS COUPLER LOCK W/KEYS	18.75	1	\$18.75
					PARTS	18.75

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 40577

Work Order Notes

(LISAPATE) New truck Do PDI-install used tool box from other truck. Get a pin and lock for hitch

Job Notes

14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK

(ABLACK) AB installed a receiver and new pin lock

14-71-029 - INSTALL LINEX BED LINER

(LISAPATE) Linex installed spray in bed liner. Pd by CC

14-78-044 - INSTALL TOOLBOX ASSY

(ABLACK) AB installed tool box from 7333B onto new truck

16-71 - TRANSPORT BODY

(LISAPATE) TRuck was taken to Linex by the drivers

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(ABLACK) AB performed PDI

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 42208

USING DEPT NO:	510301	OPENED DATE:	01/28/2022 07:24:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/28/2022 09:33:48	METER 1 - M:	1584	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2022 09:38:22	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.51	\$20.37	\$0.00	\$23.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$26.55	\$69.62	\$0.00	\$96.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.25	30.06	89.99	2.00	122.05
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/28/2022 09:12:20	01/28/2022 09:14:07	0.03	\$3.51
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/28/2022 08:58:41	01/28/2022 09:12:11	0.23	\$26.55
					LABOR	30.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	2	\$20.37
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	7.38	8	\$59.04
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.58	1	\$10.58
					PARTS	89.99

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 42208

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW
MILEAGE-1584

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 42457

USING DEPT NO:	510301	OPENED DATE:	02/23/2022 15:05:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2022 13:20:47	METER 1 - M:	1781	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/28/2022 08:40:08	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.11	\$12.72	\$20.37	\$0.00	\$33.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.11	12.72	20.37	2.00	35.09
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/25/2022 06:59:36	02/25/2022 07:06:04	0.11	\$12.72
					LABOR	12.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	2	\$20.37
					PARTS	20.37

Work Order Charge Detail

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 42457

Work Order Notes

(CHANNELL) replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers per customer request. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 43686

USING DEPT NO:	510301	OPENED DATE:	06/16/2022 15:04:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/17/2022 13:44:59	METER 1 - M:	2515	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2022 15:33:55	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.38	\$0.00	\$0.00	\$48.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.41	48.38	0.00	2.00	50.38
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/17/2022 12:20:03	06/17/2022 12:44:39	0.41	\$48.38
					LABOR	48.38

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 43686

Work Order Notes

(CWIGLEY) PM-Replace Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 2515 Vehicle has been 931 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 45446

USING DEPT NO:	510301	OPENED DATE:	12/06/2022 07:09:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/08/2022 11:18:39	METER 1 - M:	4419	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/08/2022 14:00:38	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.57	\$20.91	\$0.00	\$38.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$74.77	\$86.52	\$0.00	\$161.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.78	92.34	107.43	5.00	204.77
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	12/06/2022 08:30:21	12/06/2022 08:39:17	0.15	\$17.57
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/06/2022 07:52:20	12/06/2022 08:30:21	0.63	\$74.77
				LABOR		92.34

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	10.10	8	\$80.76
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.46	2	\$20.91
				PARTS		107.43

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 45446

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-GRC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed pm- changed oil and oil filter-GRC- checked fluids and tires and tire pressure battery good,
Miles, 4,419

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 45932

USING DEPT NO:	510301	OPENED DATE:	01/26/2023 15:05:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/31/2023 12:44:24	METER 1 - M:	4499	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/31/2023 15:41:12	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-51-043	RECALL WIPER ARM	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-71-045	RECALL Undercarriage	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-51-043	RECALL WIPER ARM	11099772	100604925		\$0.00
				COMML	0.00

Work Order Charge Detail

UNIT NO:	244158	2021 FORD F150 4X4	WORK ORDER NO:	45932
----------	--------	--------------------	----------------	-------

Work Order Notes
(CWIGLEY) Recall 22s26 for wiper assembly.

Job Notes
17-51-043 - RECALL WIPER ARM
(CWIGLEY) Long Lewis Ford Mobile unit completed recall.
17-71-045 - RECALL Undercarriage
(LISAPATE) Long Lewis secured underbody shields with rivets Per 22S53

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 47017

USING DEPT NO:	510301	OPENED DATE:	05/11/2023 11:12:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2023 12:22:46	METER 1 - M:	5474	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2023 07:19:41	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-044	REPLACE NEW KEY FOB/REMOTE	DON	5	N	GARAGE	0.08	\$8.88	\$261.26	\$0.00	\$270.14
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$18.13	\$0.00	\$0.00	\$18.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.33	\$38.35	\$0.00	\$0.00	\$38.35

JOB COUNT: 4	WORK ORDER TOTAL:	0.55	65.36	261.26	5.00	331.62
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/12/2023 08:25:24	05/12/2023 08:34:37	0.15	\$18.13
03-51-044	REPLACE NEW KEY FOB/REMOTE	11310047	05/18/2023 14:00:42	05/18/2023 14:05:13	0.08	\$8.88
03-51-044	REPLACE NEW KEY FOB/REMOTE	11310047	05/18/2023 14:00:42	05/18/2023 14:05:13	0.08	\$8.88
03-51-044	REPLACE NEW KEY FOB/REMOTE	11310047	05/18/2023 14:00:42	05/18/2023 14:05:13	(0.08)	(\$8.88)
WA-00	WASH COMPLETE VEHICLE	12052187	05/12/2023 08:37:10	05/12/2023 08:56:40	0.33	\$38.35
					LABOR	65.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-044	REPLACE NEW KEY FOB/REMOTE	164R8265	KEY BLANK/FOB	261.26	1	\$261.26
03-51-044	REPLACE NEW KEY FOB/REMOTE	164R8265	KEY BLANK/FOB	261.26	(1)	(\$261.26)
03-51-044	REPLACE NEW KEY FOB/REMOTE	164R8265	KEY BLANK/FOB	261.26	1	\$261.26
					PARTS	261.26

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 47017

Work Order Notes

(LRUSHING) PM

Job Notes

03-51-044 - REPLACE NEW KEY FOB/REMOTE

(EHOWELL) Learned a new key to the vehicle. EH .5 HR

(AJONES) Visit Reason Changed On 6/1/2023 9:08 AM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1055 miles. Checked fluids and tires. Coolant -34°. JAW

MILEAGE-5474

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Hand washed unit

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 47937

USING DEPT NO:	510301	OPENED DATE:	08/21/2023 13:55:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2023 09:51:01	METER 1 - M:	6426	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2023 12:24:21	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.22	\$26.32	\$0.00	\$0.00	\$26.32
CH-32-002	CHARGE BATTERY	DON	B	N	GARAGE	1.30	\$153.96	\$0.00	\$0.00	\$153.96
CH-SP	CHARGE Shop Supplies	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60

JOB COUNT: 4	WORK ORDER TOTAL:	1.73	203.88	0.00	5.00	208.88
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	08/23/2023 07:00:00	08/23/2023 07:12:00	0.20	\$23.60
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	08/23/2023 07:00:00	08/23/2023 07:12:00	0.20	\$23.60
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	08/23/2023 07:00:00	08/23/2023 07:12:00	(0.20)	(\$23.60)
CH-32-002	CHARGE BATTERY	11310047	08/23/2023 07:00:00	08/23/2023 08:00:00	1.00	\$118.00
CH-32-002	CHARGE BATTERY	11310047	08/23/2023 07:00:00	08/23/2023 08:00:00	(1.00)	(\$118.00)
CH-32-002	CHARGE BATTERY	11310047	08/23/2023 07:00:00	08/23/2023 08:00:00	1.00	\$118.00
CH-32-002	CHARGE BATTERY	12201267	08/22/2023 08:52:14	08/22/2023 09:10:31	0.30	\$35.96
CH-32-002	CHARGE BATTERY	12201267	08/22/2023 08:52:14	08/22/2023 09:10:31	(0.30)	(\$35.96)
CH-32-002	CHARGE BATTERY	12201267	08/22/2023 08:52:14	08/22/2023 09:10:31	0.30	\$35.96
CH-32-002	CHARGE BATTERY	12201267	08/22/2023 08:52:14	08/22/2023 09:10:31	(0.30)	(\$35.96)
CH-32-002	CHARGE BATTERY	12201267	08/22/2023 08:52:14	08/22/2023 09:10:31	0.30	\$35.96

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	12201267	08/21/2023 14:01:37	08/21/2023 14:15:00	0.22	\$26.32
					LABOR	203.88

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 47937

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

06-32-002 - INSPECT BATTERY

66-79-002 - PERFORM SERVICE CALL

(GARAGE) Did service call for dead battery in parking lot in front of shop. Tried jump box and battery was so dead jump box wouldnt work. Had to jump dead battery off with jumper cables. Drove to shop and going to inspect battery.-GC

CH-32-002 - CHARGE BATTERY

(GRCOOK) Charged battery and tested and battery tested good. Installed battery back in vehicle and checked volts, volts are 14.06-GC

For some reason check engine light was on after installing battery, got EH to hook up and check the vehicle, EH found no issues and cleared the check engine light. -GC

(LISAPATE) Visit Reason Changed On 8/23/2023 9:50 AM By LISAPATE

(LRUSHING) Visit Reason Changed On 8/30/2023 8:49 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 8/30/2023 8:50 AM By LRUSHING

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) For some reason check engine light was on after installing battery, got EH to hook up and check the vehicle, EH found no issues and cleared the check engine light. -GC

(LRUSHING) Visit Reason Changed On 8/30/2023 8:50 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 48759

USING DEPT NO:	510301	OPENED DATE:	10/30/2023 09:49:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2023 10:23:42	METER 1 - M:	7163	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2023 13:11:00	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17-033	REPLACE NEW TIRE ROTATION AND BI	DON	P	N	GARAGE	0.46	\$54.48	\$0.00	\$0.00	\$54.48
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.64	\$21.69	\$0.00	\$27.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.86	\$81.48	\$0.00	\$97.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$2.95	\$0.00	\$0.00	\$2.95

JOB COUNT: 5	WORK ORDER TOTAL:	0.67	78.93	103.17	5.00	187.10
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:30:00	10/30/2023 14:57:42	0.46	\$54.48
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:29:28	10/30/2023 14:29:28	0.00	\$0.00
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:30:00	10/30/2023 14:57:42	0.46	\$54.48
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:29:28	10/30/2023 14:29:28	0.00	\$0.00
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:30:00	10/30/2023 14:57:42	(0.46)	(\$54.48)
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:29:28	10/30/2023 14:29:28	0.00	\$0.00
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:30:00	10/30/2023 14:57:42	0.46	\$54.48
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:29:28	10/30/2023 14:29:28	0.00	\$0.00
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:30:00	10/30/2023 14:57:42	(0.46)	(\$54.48)
03-17-033	REPLACE NEW TIRE ROTATION AND BRAKE INSPEC`	12201267	10/30/2023 14:29:28	10/30/2023 14:29:28	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	12201267	10/30/2023 14:13:30	10/30/2023 14:15:00	0.03	\$2.95
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/30/2023 13:37:10	10/30/2023 13:40:02	0.05	\$5.64
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/30/2023 13:28:37	10/30/2023 13:36:41	0.13	\$15.86

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

					LABOR	78.93
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	9.47	8	\$75.72
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
					PARTS	103.17

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 48759

Work Order Notes

(EHANNAH) pm wiper- wash

Job Notes

03-17-033 - REPLACE NEW TIRE ROTATION AND BRAKE INSPECTI

(GRCOOK) Rotated tires, and inspected brakes, found no issues at this time.-GC

Front and Rear brake pads are 8mm

Miles, 7,163

(LRUSHING) Visit Reason Changed On 11/3/2023 9:50 AM By LRUSHING

(LRUSHING) Visit Reason Changed On 11/8/2023 3:06 PM By LRUSHING

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4 WORK ORDER NO: 48900

USING DEPT NO:	510301	OPENED DATE:	11/08/2023 14:30:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2023 11:09:00	METER 1 - M:	7260	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 11:09:03	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-79-001	RECALL AIR BAG	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-79-001	RECALL AIR BAG	11099772	100617971		\$0.00
				COMML	0.00

Work Order Charge Detail

UNIT NO:	244158	2021 FORD F150 4X4	WORK ORDER NO:	48900
----------	--------	--------------------	----------------	-------

Work Order Notes

(LISAPATE) recall- airbag

Job Notes

17-51-039 - RECALL WIPER MOTOR

17-79-001 - RECALL AIR BAG

(LISAPATE) Lng Lewis resecured harness

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 50326

USING DEPT NO:	510301	OPENED DATE:	03/27/2024 14:04:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/28/2024 15:09:54	METER 1 - M:	8114	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2024 07:09:11	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.26	\$0.00	\$0.00	\$24.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.42	\$49.23	\$0.00	\$0.00	\$49.23

JOB COUNT: 3	WORK ORDER TOTAL:	0.62	73.49	0.00	5.00	78.49
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	03/27/2024 15:00:57	03/27/2024 15:25:59	0.42	\$49.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/27/2024 14:48:37	03/27/2024 15:00:57	0.21	\$24.26
					LABOR	73.49

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 50326

Work Order Notes

(EHANNAH) PM- WIPERS- WASH

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 50695

USING DEPT NO:	510301	OPENED DATE:	04/29/2024 12:01:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/30/2024 09:58:58	METER 1 - M:	8114	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2024 10:23:43	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.03	\$2.95	\$0.00	\$0.00	\$2.95
CH-32-002	CHARGE BATTERY	DON	B	N	GARAGE	0.02	\$2.07	\$0.00	\$0.00	\$2.07
CH-SP	CHARGE Shop Supplies	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.04	5.02	0.00	5.00	10.02
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	12201267	04/30/2024 07:32:11	04/30/2024 07:33:14	0.02	\$2.07
CH-32-002	CHARGE BATTERY	12201267	04/30/2024 07:32:11	04/30/2024 07:33:14	(0.02)	(\$2.07)
CH-32-002	CHARGE BATTERY	12201267	04/30/2024 07:32:11	04/30/2024 07:33:14	0.02	\$2.07
66-79-002	PERFORM SERVICE CALL	12201267	04/30/2024 07:23:45	04/30/2024 07:25:15	0.03	\$2.95
					LABOR	5.02

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 50695

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

06-32-002 - INSPECT BATTERY

66-79-002 - PERFORM SERVICE CALL

(GRCOOK) Performed service call for dead battery, jumped off vehicle and brought it back to the shop, pulled battery and going to charge it over night. CW,GC

CH-32-002 - CHARGE BATTERY

(GRCOOK) Pulled battery and let charge over night. Tested battery this morning and battery tested good. Reinstalled battery. -GC

(LRUSHING) Visit Reason Changed On 5/1/2024 7:45 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 5/1/2024 7:45 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 52455

USING DEPT NO:	510301	OPENED DATE:	10/11/2024 09:45:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/15/2024 07:38:36	METER 1 - M:	10189	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/15/2024 08:13:13	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$21.69	\$0.00	\$21.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$110.12	\$0.00	\$110.12
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$30.00	\$0.00	\$30.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	161.81	5.00	166.81
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FA1883	AIR FILTER	27.00	1	\$27.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	30.00	1	\$30.00
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	8.85	8	\$70.80
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
					PARTS	161.81

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 52455

Work Order Notes

(CWIGLEY) PM. Wipers. Wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-CW

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm-CW,GC, changed oil and oil filter, checked fluids, changed air filter and cabin filter, tires and tire pressure. miles, 10,189

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) replaced cabin filter-CW

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 53023

USING DEPT NO:	510301	OPENED DATE:	12/06/2024 15:38:23	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	12/10/2024 13:17:36	METER 1 - M:	10379	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/10/2024 13:17:46	IN-SERVICE DATE:	07/28/2021				
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$225.51	\$0.00	\$225.51
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PU-51-044	PURCHASED KEY FOB/REMOTE	DON	N	N	GARAGE	0.00	\$0.00	\$223.49	\$19.55	\$243.04

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	449.00	24.55	473.55
--------------	-------------------	------	------	--------	-------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
PU-51-044	PURCHASED KEY FOB/REMOTE	4910000	2628505		\$19.55
				COMML	24.55

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-51-044	PURCHASED KEY FOB/REMOTE	164R8269	KEY/KEY FOB FORD	223.49	1	\$223.49
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	225.51	1	\$225.51
					PARTS	449.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 53023

Work Order Notes

(CHANNELL) replace battery\ parking brake light on\ order new key fob

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) replaced battery, tested battery and original battery tested bad, installed new battery and checked battery volts, battery volts are 14.74- GC miles, 10,608

(EKIMBREL) After replacing battery, all lights checked good.

03-34-003 - REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS

CH-SP - CHARGE Shop Supplies

(JWEATHER) Visit Reason Changed On 12/13/2024 11:02 AM By JWEATHER

PU-51-044 - PURCHASED KEY FOB/REMOTE

(GARAGE) PROGRAMMED NEW KEY FOB TO TRUCK BY TURNING IGNITION ON DOOR LOCKS LOCKED AND HELD TO CRANK. TRUCK CRANKED CORRECTLY. CQ

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 54150

USING DEPT NO:	510301	OPENED DATE:	03/25/2025 13:05:42	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2025 07:20:23	METER 1 - M:	11416	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/27/2025 12:59:07	IN-SERVICE DATE:	07/28/2021						
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E5XMFB95501					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 4		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 54150

Work Order Notes

(EHANNAH) pm- wipers- wash- SI
(GARAGE) Pending SI & wash.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Blades are not needed at this time.

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si cm 11416 miles, checked over vehicle checked ok, brake pads were 8 mm tire were 5mm may need tire next service

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Fluid check. Mileage is 11416. Driven 1227 miles since PM. Topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed cm

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 54939

USING DEPT NO:	510301	OPENED DATE:	05/30/2025 11:28:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2025 15:10:37	METER 1 - M:	11790	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/30/2025 17:20:20	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.00	\$0.00	\$2.90	\$0.00	\$2.90
CH-SP	CHARGE Shop Supplies	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$3.34	\$3.34

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	2.90	3.34	6.24
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.90)
CH-SP	CHARGE Shop Supplies	503163	1		\$3.34
CH-SP	CHARGE Shop Supplies	503163	1		\$2.90
COMML					3.34

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.90	1	\$2.90
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.90	(1)	(\$2.90)
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.90	1	\$2.90
PARTS						2.90

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 54939

Work Order Notes

(CWIGLEY) LR is low.

Job Notes

66-17-030 - PERFORM TIRE PATCH

(GARAGE) FJ- Patched LR tire. 21060 valve stem used. Mileage:11,790

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 56457

USING DEPT NO:	510301	OPENED DATE:	09/19/2025 14:18:55	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2025 10:30:22	METER 1 - M:	12700	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2025 16:04:55	IN-SERVICE DATE:	07/28/2021				
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4			UNIT SERIAL NO:	1FTFW1E5XMFB95501			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$297.54	\$0.00	\$297.54
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$62.32	\$0.00	\$62.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	359.86	5.00	364.86
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	23131	TPMS SNAP IN VALVE 21060	3.01	1	\$3.01
66-PM-PMA	PERFORM OIL CHANGE	SF5W30BT	5W30BT OIL - STIVERS	5.87	8	\$46.92
66-PM-PMA	PERFORM OIL CHANGE	SFFL500S	FL500S OIL FILTER - STIVERS	12.39	1	\$12.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	4128600	TIRE 265/70R17 PIR SCORP ATR	297.54	1	\$297.54
PARTS						359.86

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 56457

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Not needed at this time

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) FJ- Mounted/balanced 1 tire. 21060 valve stem used

66-17-030 - PERFORM TIRE PATCH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) 12,700 miles

PM

FJ- Added oil & checked oil level

JR- Oil change, topped off fluids, set tire pressure, recorded date codes & tread depths, checked filters

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 56696

USING DEPT NO:	510301	OPENED DATE:	10/07/2025 10:51:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/08/2025 08:13:12	METER 1 - M:	12819	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/08/2025 12:39:00	IN-SERVICE DATE:	07/28/2021	
TECH SPEC NO:	21FORDF1504X4	2021 Ford F150 4X4		UNIT SERIAL NO:	1FTFW1E5XMFB95501	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.52	\$78.38	\$0.00	\$0.00	\$78.38

JOB COUNT: 2	WORK ORDER TOTAL:	0.52	78.38	0.00	5.00	83.38
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	10/08/2025 07:37:36	10/08/2025 08:08:57	0.52	\$78.38
					LABOR	78.38

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:55:35 By User: GLOBETTI

UNIT NO: 244158 2021 FORD F150 4X4

WORK ORDER NO: 56696

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) cm performed perp for sale unit checked ok,

PS-00-999 - PREP SERVICE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Oct 10 2025 07:55:35 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244158') //Q=