

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 45194

USING DEPT NO:	200721	OPENED DATE:	11/07/2022 14:02:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/07/2022 14:03:18	METER 1 - M:	8	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2022 13:48:02	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0PU104731	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	5.00	123.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11310047	11/09/2022 07:00:00	11/09/2022 08:00:00	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 45194

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 46781

USING DEPT NO:	200721	OPENED DATE:	04/20/2023 11:07:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/24/2023 11:12:39	METER 1 - M:	291	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2023 13:07:59	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0PU104731	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.49	\$0.00	\$0.00	\$18.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.06	\$6.85	\$0.00	\$0.00	\$6.85

JOB COUNT: 3	WORK ORDER TOTAL:	0.21	25.34	0.00	5.00	30.34
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	04/20/2023 15:21:37	04/20/2023 15:25:06	0.06	\$6.85
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/20/2023 15:12:01	04/20/2023 15:21:25	0.16	\$18.49
					LABOR	25.34

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 46781

Work Order Notes

(LISAPATE) PM-wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,- Fluid check only, filters good, tires and tire pressure.
Miles, 291

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-CW

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 48082

USING DEPT NO:	200721	OPENED DATE:	09/05/2023 09:43:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2023 15:34:34	METER 1 - M:	813	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 11:47:47	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0PU104731	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.06	\$53.64	\$0.00	\$81.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.24	28.06	53.64	5.00	86.70
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	09/05/2023 10:09:42	09/05/2023 10:23:58	0.24	\$28.06
					LABOR	28.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.46	5	\$42.30
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.34	1	\$11.34
					PARTS	53.64

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 48082

Work Order Notes

(EHANNAH) pm-wipers

(EKIMBREL) did not need wipers, new vehicle

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,SH, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 813

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 49738

USING DEPT NO:	200721	OPENED DATE:	02/07/2024 14:55:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/08/2024 13:12:52	METER 1 - M:	933	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/09/2024 07:25:50	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0PU104731	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.70	\$0.00	\$0.00	\$19.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.03	\$3.47	\$0.00	\$0.00	\$3.47
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.45	\$52.54	\$0.00	\$0.00	\$52.54

JOB COUNT: 4	WORK ORDER TOTAL:	0.64	75.71	0.00	5.00	80.71
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/08/2024 10:05:18	02/08/2024 10:07:04	0.03	\$3.47
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/08/2024 10:05:18	02/08/2024 10:07:04	(0.03)	(\$3.47)
WA-00	WASH COMPLETE VEHICLE	11074414	02/08/2024 08:18:30	02/08/2024 08:45:13	0.45	\$52.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/08/2024 08:08:29	02/08/2024 08:18:30	0.17	\$19.70
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/08/2024 10:05:18	02/08/2024 10:07:04	0.03	\$3.47
				LABOR		75.71

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 49738

Work Order Notes

(EHANNAH) pm- wipers- wash- Scan out
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 179 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(GARAGE) Scanned unit and found no active codes or history codes. Test drove and found no issues. JAW
(LRUSHING) Visit Reason Changed On 2/15/2024 1:04 PM By LRUSHING

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 51425

USING DEPT NO:	200721	OPENED DATE:	07/10/2024 07:06:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/19/2024 12:39:32	METER 1 - M:	933	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/19/2024 12:39:39	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0PU104731	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-PM-PMA	TRANSPORT OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11076422	6256748		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 51425

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM-PMA - TRANSPORT OIL CHANGE

(IFALLS) chad performed pm transport

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) tuscaloosa toyota performed pm free of charge

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 53027

USING DEPT NO:	200721	OPENED DATE:	12/09/2024 07:08:17	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2024 13:49:50	METER 1 - M:	1385	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/09/2024 13:57:39	IN-SERVICE DATE:	11/03/2022						
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry									
			UNIT SERIAL NO:	4T1C11AK0PU104731							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.00	\$0.00	\$51.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	75.08	5.00	80.08
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.28	5	\$41.40
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
PARTS						75.08

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 53027

Work Order Notes

(EHANNAH) pm- wipers- Wash- SI-
(EKIMBREL) only 1385mi, SI not needed yet.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced wiper blades

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM service. Oil change, checked filters, topped off fluids, set tire pressure, date codes & tread depths.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- Washed vehicle in wash bay

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 54560

USING DEPT NO:	200721	OPENED DATE:	04/23/2025 07:02:22	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	04/23/2025 12:20:20	METER 1 - M:	1617	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2025 07:32:01	IN-SERVICE DATE:	11/03/2022						
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry			UNIT SERIAL NO:	4T1C11AK0PU104731					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 54560

Work Order Notes

(EHANNAH) pm- wipers- wash - SI
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) JR- perform SI per SI sheet, everything checked OK
front and rear brakes were 8s

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, fluid check only, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
1617 miles, 232 miles driven

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 56550

USING DEPT NO:	200721	OPENED DATE:	09/25/2025 08:57:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2025 13:09:09	METER 1 - M:	1784	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2025 07:37:31	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0PU104731	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$50.33	\$0.00	\$50.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	50.33	5.00	55.33
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.57	5	\$42.83
					PARTS	50.33

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 56550

Work Order Notes

(EHANNAH) pm- wiper- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) fj=dropped oil and filter and installed new filter. CQ= filled with oil and checked all fluid levels. recorded build dates, tread depth and set tire pressure. installed new sticker.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 57067

USING DEPT NO:	200721	OPENED DATE:	11/04/2025 09:13:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2025 09:43:34	METER 1 - M:	1943	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2025 15:38:08	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0PU104731	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	150.00	0.00	5.00	155.00
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	11/04/2025 14:43:32	11/04/2025 15:43:32	1.00	\$150.00
					LABOR	150.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:55:35 By User: GLOBETTI

UNIT NO: 245079 2023 TOYOTA CAMRY

WORK ORDER NO: 57067

Work Order Notes

(EKIMBREL) prep 4 sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EHOWELL) cm performed prep for sale, unit had 1943 miles,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Nov 05 2025 12:55:35 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '245079') //Q=