

Work Order Charge Detail

UNIT NO: 236965 **2006 FORD E350**

WORK ORDER NO: 10230

USING DEPT NO: 504303	OPENED DATE: 02/03/2012 11:29:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/07/2012 07:52:03	METER 1 - M: 56291 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/07/2012 07:52:05	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$0.00	\$0.00	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$77.07	\$0.00	\$94.90

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **77.07** **0.00** **109.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11413680	02/06/2012 07:00:00	02/06/2012 07:15:00	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11413680	02/03/2012 13:57:36	02/06/2012 07:07:11	(65.16)	(\$3,746.68)
66-PM-PMA	PERFORM OIL CHANGE	11413680	02/03/2012 13:57:36	02/06/2012 07:07:11	65.16	\$3,746.68
66-PM-PMA	PERFORM OIL CHANGE	11413680	02/03/2012 13:57:36	02/03/2012 14:16:12	0.31	\$17.83
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	60-2040	WIPER BLADE	19.59	2	\$39.18
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	9.63	1	\$9.63
					PARTS	77.07

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 10230

Work Order Notes

(LPATE) PM-REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(RWINTERS) PM BY RT/RS-REPLACED OIL DRAIN PLUG, ADDED 10OZ OF FLUID TO LIFGATE AND ADJUSTED CHAINS. LIFTGATE IS NOW LEVEL WITH BED OF TRUCK AND OPERATING PROPERLY.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 10622

USING DEPT NO: 504303	OPENED DATE: 03/23/2012 09:59:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/28/2012 07:33:08	METER 1 - M: 60227 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/28/2012 07:33:09	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.02	\$1.12	\$39.27	\$0.00	\$40.39
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$11.42	\$57.05	\$0.00	\$68.47

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.22** **12.54** **96.32** **0.00** **108.86**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	03/23/2012 11:28:06	03/23/2012 11:40:01	0.20	\$11.42
03-51-038	REPLACE NEW WIPER BLADES	11338644	03/23/2012 11:38:00	03/23/2012 11:39:10	0.02	\$1.12
					LABOR	12.54

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	9.63	1	\$9.63
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	32	\$3.84
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	1	\$4.91
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.64	2	\$39.27
					PARTS	96.32

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 10622

Work Order Notes

(LPATE) PM-LUBE LIFT GATE

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY GM/RS-REPLACED OIL DRAIN PLUG

Work Order Charge Detail

UNIT NO: 236965 **2006 FORD E350**

WORK ORDER NO: 1087

USING DEPT NO: 504303	OPENED DATE: 04/07/2008 07:47:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/07/2008 07:49:25	METER 1 - M: 25199 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 04/07/2008 07:49:27	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-015	PERFORM TIRE ROTATION	DON	N	N	GARAGE	0.50	\$22.50	\$0.00	\$0.00	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$27.56	\$0.00	\$41.51

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **36.45** **27.56** **0.00** **64.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11128904	04/07/2008 08:00:00	04/07/2008 08:18:36	0.31	\$13.95
66-17-015	PERFORM TIRE ROTATION	11128904	04/07/2008 08:18:36	04/07/2008 08:48:36	0.50	\$22.50
					LABOR	36.45

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.09	224	\$20.16
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.40	1	\$7.40
					PARTS	27.56

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 1087

Work Order Notes

(LOBRIEN) PM AND TIRE ROTATION.

Job Notes

66-17-015 - PERFORM TIRE ROTATION

(LOBRIEN) ROTATED TIRES.

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY CHRIS MCRAE.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 11066

USING DEPT NO: 504303	OPENED DATE: 05/22/2012 07:10:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/23/2012 13:49:23	METER 1 - M: 64166 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/23/2012 13:49:25	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.54	\$145.97	\$105.73	\$0.00	\$251.70
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$3.47	\$64.64	\$0.00	\$68.11

JOB COUNT: 3	WORK ORDER TOTAL:	3.10	178.19	170.37	0.00	348.56
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	05/23/2012 09:03:56	05/23/2012 09:15:00	0.18	\$10.60
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	05/23/2012 09:30:00	05/23/2012 09:51:15	0.35	\$20.37
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	10260422	05/23/2012 07:00:00	05/23/2012 07:30:00	0.50	\$28.75
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	05/23/2012 07:00:00	05/23/2012 09:00:00	2.00	\$115.00
66-PM-PMA	PERFORM OIL CHANGE	10260422	05/22/2012 09:01:06	05/22/2012 09:04:43	0.06	\$3.47
					LABOR	178.19

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABPGD655M	FRONT PADS	80.35	1	\$80.35
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF24000	GREASE SEAL	12.69	2	\$25.38
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	2	\$9.81
					PARTS	170.37

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 11066

Work Order Notes

(LPATE) PM-ROTATE TIRES-CHECK BRAKES

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(RWINTERS) REPLACED FRONT PADS, PACKED BEARINGS. AND TURNED ROTORS

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 1372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 224
Description : OIL BOTTLE
Manufacturer :

Part No : 6418
Qty : 1
Description : FILTER-AIR
Manufacturer :

(LPATE) PM BY GM/RS-CLEANED AND LUBED LIFT GATE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 11384

USING DEPT NO: 504303	OPENED DATE: 07/11/2012 14:12:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/12/2012 14:23:11	METER 1 - M: 64166 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/12/2012 14:23:14	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1 **WORK ORDER TOTAL: 1.00 57.50 0.00 0.00 57.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	10260422	07/11/2012 17:00:00	07/11/2012 18:00:00	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 11384

Work Order Notes

(LPATE) DO SAFETY INSPECTION

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) SAFETY INSPECTION COMPLETE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 11688

USING DEPT NO: 504303	OPENED DATE: 08/17/2012 07:24:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/21/2012 14:04:18	METER 1 - M: 64172 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/21/2012 14:04:20	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.89	\$50.89	\$69.45	\$0.00	\$120.34

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.89** **50.89** **69.45** **0.00** **120.34**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11413680	08/18/2012 10:36:44	08/18/2012 10:47:40	(0.18)	(\$10.48)
66-PM-PMA	PERFORM OIL CHANGE	11413680	08/18/2012 13:04:51	08/18/2012 13:57:57	0.89	\$50.89
66-PM-PMA	PERFORM OIL CHANGE	11413680	08/18/2012 10:36:44	08/18/2012 10:47:40	0.18	\$10.48
					LABOR	50.89

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.51	1	\$14.51
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
					PARTS	69.45

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 11688

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 1372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20FS
Qty : 7
Description : HAVOLINE 5W20 FULL SYN. OIL QT
Manufacturer :

Part No : 6418
Qty : 1
Description : FILTER-AIR
Manufacturer :

(LPATE) PM BY RT/RS-REPLACED AIR FILTER AND OIL DRAIN PLUG-LUBED LIFT GATE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 12247

USING DEPT NO: 504303	OPENED DATE: 10/26/2012 07:54:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/29/2012 14:38:56	METER 1 - M: 70741 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/29/2012 14:38:58	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$22.34	\$55.39	\$0.00	\$77.73

JOB COUNT: 1	WORK ORDER TOTAL:	0.39	22.34	55.39	0.00	77.73
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	10/26/2012 13:25:06	10/26/2012 13:33:19	0.14	\$7.87
66-PM-PMA	PERFORM OIL CHANGE	10260422	10/26/2012 11:37:50	10/26/2012 11:52:56	0.25	\$14.47
					LABOR	22.34

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.19	1	\$5.19
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
					PARTS	55.39

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 12247

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 1372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20FS
Qty : 7
Description : HAVOLINE 5W20 FULL SYN. OIL QT
Manufacturer :

Part No : 6418
Qty : 1
Description : FILTER-AIR
Manufacturer :

(LPATE) PM BY GM/RS-REPLACED OIL DRAIN PLUG

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 12715

USING DEPT NO: 504303	OPENED DATE: 01/07/2013 13:49:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/09/2013 07:58:12	METER 1 - M: 74437 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/09/2013 07:58:14	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
07-55-039	LUBRICATE LIFTGATE ASSY	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1 **WORK ORDER TOTAL: 1.00 57.50 0.00 0.00 57.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
07-55-039	LUBRICATE LIFTGATE ASSY	11074414	01/07/2013 15:18:33	01/07/2013 16:18:33	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 12715

Work Order Notes

(GMANNING) LIFTGATE NOT OPERATING PROPERLY, WIRING HARNESS LOOSE

Job Notes

07-55-039 - LUBRICATE LIFTGATE ASSY

(GMANNING) SH CLEANED AND GREASED TFACKS, REMOVED REAR COVER, CHECKED FLUID, GREASED CHAIN AND REPLACED COVER. USED TIE STRAPS TO SECURE WIRING HARNESS. OPERATED LIFT SEVERAL TIMES, OPERATING GOOD.

Work Order Charge Detail

UNIT NO: 236965 **2006 FORD E350**

WORK ORDER NO: 12753

USING DEPT NO: 504303	OPENED DATE: 01/11/2013 07:23:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/11/2013 13:48:26	METER 1 - M: 75089 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/11/2013 13:48:28	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.60	\$67.41	\$0.00	\$85.01

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.60** **67.41** **0.00** **85.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/11/2013 08:18:27	01/11/2013 08:36:49	0.31	\$17.60
					LABOR	17.60

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
					PARTS	67.41

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 12753

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY BG,SH,RS/SH-REPLACED OIL DRAIN PLUG

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13069

USING DEPT NO: 504303	OPENED DATE: 02/18/2013 14:54:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/22/2013 08:29:43	METER 1 - M: 77136 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/22/2013 08:29:47	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-44-014	REPLACE NEW INJECTORS - ELECTRC	DON	O	N	GARAGE	1.11	\$63.95	\$578.94	\$0.00	\$642.89
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	1.61	\$92.67	\$7.85	\$0.00	\$100.52
CL-44-014	CLEANED INJECTORS - ELECTRONIC	DON	O	N	GARAGE	0.96	\$55.26	\$87.03	\$0.00	\$142.29
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.76	\$101.22	\$0.00	\$0.00	\$101.22

JOB COUNT: 4	WORK ORDER TOTAL:	5.45	313.10	673.82	0.00	986.92
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-44-014	CLEANED INJECTORS - ELECTRONIC	11397026	02/20/2013 10:08:04	02/20/2013 11:05:44	0.96	\$55.26
03-44-014	REPLACE NEW INJECTORS - ELECTRONIC	11397026	02/20/2013 14:24:47	02/20/2013 14:24:47	0.00	\$0.00
03-44-014	REPLACE NEW INJECTORS - ELECTRONIC	11397026	02/20/2013 14:30:00	02/20/2013 15:36:44	1.11	\$63.95
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11397026	02/21/2013 07:00:00	02/21/2013 07:30:00	0.50	\$28.75
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11397026	02/21/2013 07:02:42	02/21/2013 08:09:24	1.11	\$63.92
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	02/20/2013 09:30:00	02/20/2013 10:07:54	0.63	\$36.32
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	02/20/2013 08:07:17	02/20/2013 09:15:00	1.13	\$64.89

LABOR 313.09

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3595	FILTER-FUEL	7.85	1	\$7.85
CL-44-014	CLEANED INJECTORS - ELECTRONIC	MMM08955	3M FUEL SYSTEM CLEANER	37.11	2	\$74.22
CL-44-014	CLEANED INJECTORS - ELECTRONIC	SEESF16	SEAFOAM	12.81	1	\$12.81
03-44-014	REPLACE NEW INJECTORS - ELECTRONIC	MOTCM5075	FUEL INJECTOR	64.80	4	\$259.20
03-44-014	REPLACE NEW INJECTORS - ELECTRONIC	2L1Z9F593BA	FUEL INJECTOR	79.94	4	\$319.74

PARTS 673.82

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13069

Work Order Notes

(LPATE) PER ALLEN TRUCK IS SPITTING SPUTTERING AND RUNNING ROUGH

Job Notes

03-44-014 - REPLACE NEW INJECTORS - ELECTRONIC

(RWINTERS) REPLACED ALL 8 FUEL INJECTORS, ADDED SEA FOAM, CLEARED CODES TEST DROVE 20 MILES TO BLOW OUT CARBON. RUNS GOOD NO MISFIRES.

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE) REPLACED FUEL FILTER

CL-44-014 - CLEANED INJECTORS - ELECTRONIC

(LPATE) CLEANED FUEL INJECTORS, WOULD NOT CLEAN UP

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LPATE) CHECKED OUT, SCAN OUT MULTIPLE MISFIRE CODES- P0301,P0302,P0305,P0306,P0308

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13584

USING DEPT NO: 504303	OPENED DATE: 04/19/2013 15:44:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/25/2013 16:00:00	METER 1 - M: 82543 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/25/2013 16:00:00	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$960.08	\$960.08
03-44-003	REPLACE NEW FUEL PUMP	DON	O	N	GARAGE	2.40	\$138.00	\$489.60	\$0.00	\$627.60
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$38.97	\$0.00	\$53.35
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 5	WORK ORDER TOTAL:	5.15	296.13	528.57	960.08	1,784.78
---------------------	--------------------------	-------------	---------------	---------------	---------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	162520	0019608	\$960.08
				COMML	960.08

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11338644	04/25/2013 07:00:00	04/25/2013 08:30:00	1.50	\$86.25
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11074414	04/25/2013 06:00:00	04/25/2013 07:00:00	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	11268671	04/25/2013 07:00:00	04/25/2013 07:15:00	0.25	\$14.38
03-44-003	REPLACE NEW FUEL PUMP	11268671	04/25/2013 07:00:00	04/25/2013 09:24:00	2.40	\$138.00
					LABOR	296.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-003	REPLACE NEW FUEL PUMP	6C2Z9H307CA	FUEL PUMP	489.60	1	\$489.60
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	19.49	2	\$38.97
					PARTS	528.57

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13584

Work Order Notes

(RWINTERS) FUEL GAUGE READING EMPTY AND FUEL LIGHT IS ON. IS FULL OF GAS PER DRIVER, NEEDS TIRES (FRONT CUPPED AND BOTH OUTSIDE REAR TIRES WORN INTO TREAD/WEARBARS PER ISSAC, REPLACE WIPERS
(RWINTERS) DID NOT HAVE TIME TO CLEAN AND INSPECT LIFTGATE DUE TO TIRES BEING INSTALLED-VAN GONE ALL DAY AFTER FUEL PUMP MODULE REPLACEMENT

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(GMANNING) FIRESTONE REPLACED ALL 6 TIRES AND ALIGNED FRONT END. PD BY CC.

03-44-003 - REPLACE NEW FUEL PUMP

(GMANNING) IF REPLACED FUEL PUMP.

03-51-038 - REPLACE NEW WIPER BLADES

(GMANNING) REPLACED BOTH WIPER BLADES

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(GMANNING) TAKEN TO FIRESTONE BY SH

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(RWINTERS) SCANNED OUT PO4631 (FUEL LEVEL SENSOR A CIRCUIT HIGH INPUT). CLEARED CODE AFTER REPAIR-RETESTED. EVERYTHING CHECKED OK.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13658

USING DEPT NO: 504303	OPENED DATE: 04/29/2013 15:39:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/01/2013 10:19:00	METER 1 - M: 83339 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/01/2013 10:19:01	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$15.32	\$57.33	\$0.00	\$72.65

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.27** **15.32** **57.33** **0.00** **72.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	04/30/2013 09:24:31	04/30/2013 09:24:31	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11338644	04/30/2013 09:30:00	04/30/2013 09:45:59	0.27	\$15.32
					LABOR	15.32

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.53	1	\$5.53
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
					PARTS	57.33

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13658

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY IF/RS-CHECKED LIFTGATE IT IS OPERATING GOOD DID NOT SEE ANY REASON TO GREASE. LEFT IT ALONE GOING UP AND DOWN GOOD WAS NOT JUMPING UP OR DOWN.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13932

USING DEPT NO: 504303	OPENED DATE: 05/24/2013 11:17:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/28/2013 16:00:00	METER 1 - M: 85588 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/28/2013 16:00:00	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 1 **WORK ORDER TOTAL: 1.50 86.25 0.00 0.00 86.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	10260422	05/24/2013 11:32:57	05/24/2013 13:02:57	1.50	\$86.25
					LABOR	86.25

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 13932

Work Order Notes

(GMANNING) INSPECT VEHICLE

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GMANNING) GM INSPECTED COMPLETE VEHICLE. RECOMMENDED BATTERY REPLACEMENT, AND REPLACEMENT OF SLIDES ON LIFT GATE. THE DECALS ARE PEELING AND NEED REPLACEMENT ALSO. QUOTE GIVEN TO TERRI BOWMAN BY RW.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 14383

USING DEPT NO: 504303	OPENED DATE: 07/17/2013 15:25:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/18/2013 13:54:28	METER 1 - M: 85795 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/18/2013 13:54:29	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-53-999	INSPECT VEHICLE FLUIDS,LUBRCNTS,	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
07-55-002	LUBRICATE VERTICAL SLIDES-PWR TA	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **57.50** **0.00** **0.00** **57.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
07-55-002	LUBRICATE VERTICAL SLIDES-PWR TAIL GATE	11413680	07/17/2013 15:27:30	07/17/2013 16:27:30	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 14383

Work Order Notes

(LPATE) CLEAN LIFT GATE SLIDES, CHECK FLUIDS AND TIRE PRESSURES-DO NOT REPLACE BATTERY AT THIS TIME.

Job Notes

06-53-999 - INSPECT VEHICLE FLUIDS,LUBRCNTS,GASES&

(LPATE) CHECKED FLUIDS AND TIRE PRESSURES WAS NOT DUE FOR PM AT THIS TIME

07-55-002 - LUBRICATE VERTICAL SLIDES-PWR TAIL GATE

(LPATE) CLEANED LIFT GATE AND GREASED.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 14939

USING DEPT NO:	504303	OPENED DATE:	09/20/2013 08:58:30	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2013 11:57:26	METER 1 - M:	87795	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2013 11:57:28	IN-SERVICE DATE:	10/30/2006		
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$61.69	\$0.00	\$79.52

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	61.69	0.00	79.52
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/20/2013 10:56:34	09/20/2013 11:15:10	0.31	\$17.83

LABOR 17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 20OZ FUEL ADDITIVE	12.09	1	\$12.09
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86

PARTS 61.69

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 14939

Work Order Notes

(LPATE) PM-LUBE LIFT GATE

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY RS-GREASED LIFT GATE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 15399

USING DEPT NO: 504303	OPENED DATE: 11/14/2013 08:58:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/15/2013 07:53:11	METER 1 - M: 92285 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/15/2013 07:53:13	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$26.97	\$0.00	\$41.35
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.25** **71.88** **26.97** **0.00** **98.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11338644	11/14/2013 14:27:08	11/14/2013 14:42:08	0.25	\$14.38
66-79-003	PERFORM SAFETY INSPECTION	11338644	11/14/2013 08:59:05	11/14/2013 09:59:05	1.00	\$57.50
					LABOR	71.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	13.49	2	\$26.97
					PARTS	26.97

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 15399

Work Order Notes

(LPATE) PER TERRI DO SAFETY INSPECTION

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) SAFETY INSPECTION COMPLETE.NEEDS WIPERS AND WILL NEED REAR BRAKES IN ABOUT 6 MO. NO WORK PERFORMED AT THIS TIME

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 15484

USING DEPT NO: 504303	OPENED DATE: 11/22/2013 07:29:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/25/2013 06:54:23	METER 1 - M: 93227 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/25/2013 06:54:24	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.84	\$0.00	\$62.67

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **44.84** **0.00** **62.67**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11397026	11/22/2013 14:08:17	11/22/2013 14:26:53	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
					PARTS	44.84

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 15484

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY BG

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 1597

USING DEPT NO: 504303	OPENED DATE: 07/02/2008 09:00:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/02/2008 10:59:35	METER 1 - M: 28497 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/02/2008 10:59:37	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.50	\$22.50	\$112.67	\$0.00	\$135.17
06-13	INSPECT BRAKES	DON	N	N	GARAGE	1.00	\$45.00	\$0.00	\$0.00	\$45.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.45	\$30.97	\$0.00	\$31.42
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.60	\$27.00	\$13.17	\$0.00	\$40.17
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	0.93	\$41.65	\$93.94	\$0.00	\$135.59

JOB COUNT: 5	WORK ORDER TOTAL:	3.04	136.60	250.75	0.00	387.35
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/02/2008 09:08:55	07/02/2008 09:09:31	0.01	\$0.45
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11088474	07/02/2008 09:09:29	07/02/2008 09:15:00	0.09	\$4.14
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11088474	07/02/2008 09:30:00	07/02/2008 09:57:42	0.46	\$20.78
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11088474	07/02/2008 09:57:49	07/02/2008 10:33:49	0.60	\$27.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11088474	07/02/2008 09:57:49	07/02/2008 09:57:57	0.00	\$0.10
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11088474	07/02/2008 09:57:49	07/02/2008 09:57:57	0.00	(\$0.10)
03-32-002	REPLACE NEW BATTERY	11088474	07/02/2008 09:58:04	07/02/2008 10:28:04	0.50	\$22.50
03-32-002	REPLACE NEW BATTERY	11088474	07/02/2008 09:58:04	07/02/2008 09:58:14	0.00	\$0.13
03-32-002	REPLACE NEW BATTERY	11088474	07/02/2008 09:58:04	07/02/2008 09:58:14	0.00	(\$0.13)
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11088474	07/02/2008 10:06:25	07/02/2008 10:28:44	0.37	\$16.74
06-13	INSPECT BRAKES	11128904	07/02/2008 09:10:00	07/02/2008 10:10:00	1.00	\$45.00
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/02/2008 09:08:55	07/02/2008 09:09:09	0.00	(\$0.18)
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/02/2008 09:08:55	07/02/2008 09:09:09	0.00	\$0.18

LABOR	136.61
--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.45	1	\$7.45
03-32-002	REPLACE NEW BATTERY	665MF	BATTERY	112.67	1	\$112.67
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33595	FUEL FILTER	13.17	1	\$13.17
66-PM-PMT	PERFORM TRANSMISSION SERVICE	BALP7247	TRANS. FILTER	15.72	1	\$15.72
66-PM-PMT	PERFORM TRANSMISSION SERVICE	BAL20005	TRANS. FILTER	18.99	1	\$18.99
66-PM-PMT	PERFORM TRANSMISSION SERVICE	C111	RED BRAKE CLEANER	3.43	1	\$3.43
66-PM-PMT	PERFORM TRANSMISSION SERVICE	MERCON SP	TRANSMISSION FLUID	6.98	8	\$55.80
					PARTS	250.75

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 1597

Work Order Notes

Job Notes

03-32-002 - REPLACE NEW BATTERY

(RWINTERS) REPLACED THE BATTERY.

06-13 - INSPECT BRAKES

(RWINTERS) CHECKED BRAKES AT ALL WHEELS, ALL LININGS ARE GOOD.

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL PLUG FORD
Manufacturer :

Part No : 51372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 224
Description : MOTOR OIL
Manufacturer :

Part No : FA1632
Qty : 1
Description : FILTER-AIR FORD
Manufacturer :

(RWINTERS) PM BY JE

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(RWINTERS) REPLACED THE FUEL FILTER.

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(RWINTERS) SERVICE TRANS. AND CHANGE BOTH FILTERS.

Work Order Charge Detail

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 16167

USING DEPT NO: 504303	OPENED DATE: 02/21/2014 07:08:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/25/2014 08:59:01	METER 1 - M: 97698 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/25/2014 08:59:02	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$303.82	\$303.82
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.84	\$0.00	\$62.67

JOB COUNT: 3	WORK ORDER TOTAL:	1.31	75.33	44.84	303.82	423.99
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11531907	4341006690	0022777	\$303.82
				COMML	303.82

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	02/24/2014 06:00:00	02/24/2014 06:18:36	0.31	\$17.83
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10260422	02/24/2014 06:18:36	02/24/2014 07:18:36	1.00	\$57.50
					LABOR	75.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
					PARTS	44.84

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 16167

Work Order Notes

(LPATE) PM-PER ALLEN NEEDS TIRES VERY WORN ON THE INSIDE FRONT.

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) GOODYEAR MOUNTED AND BALANCED 2 TIRES FOR THE FRONT OF THE TRUCK. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) LOOSE TIRES TAKEN TO WINGFOOT BY GM

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM-CHECKED AND CLEANED THE LIFTGATE TRACKS

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 16262

USING DEPT NO: 504303	OPENED DATE: 02/27/2014 14:56:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/07/2014 08:09:01	METER 1 - M: 97989 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/07/2014 08:09:03	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	1.40	\$80.47	\$510.99	\$0.00	\$591.46
06-13	INSPECT BRAKES	DON	O	N	GARAGE	7.69	\$442.02	\$0.00	\$0.00	\$442.02
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$86.25	\$86.25
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 4	WORK ORDER TOTAL:	10.09	579.99	510.99	86.25	1,177.23
---------------------	--------------------------	--------------	---------------	---------------	--------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11074243	14360	0022950	\$86.25
				COMML	86.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-13	INSPECT BRAKES	11397026	03/03/2014 09:30:00	03/03/2014 12:00:00	2.50	\$143.75
06-13	INSPECT BRAKES	11397026	03/03/2014 08:54:10	03/03/2014 09:15:00	0.35	\$19.96
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	03/03/2014 07:29:59	03/03/2014 08:53:57	1.40	\$80.47
06-13	INSPECT BRAKES	11397026	03/03/2014 13:00:00	03/03/2014 13:02:02	0.03	\$1.95
06-13	INSPECT BRAKES	11568366	03/03/2014 07:45:52	03/03/2014 09:15:00	1.49	\$85.42
06-13	INSPECT BRAKES	11568366	03/03/2014 09:30:00	03/03/2014 12:00:00	2.50	\$143.75
06-13	INSPECT BRAKES	11568366	03/03/2014 13:00:00	03/03/2014 13:49:14	0.82	\$47.18
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10260422	03/05/2014 06:00:00	03/05/2014 07:00:00	1.00	\$57.50
					LABOR	579.98

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	4.86	1	\$4.86
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF24000	GREASE SEAL	12.80	2	\$25.59
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	19.40	2	\$38.79
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABPGD655M	FRONT PADS	80.35	1	\$80.35
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAM66529R	ROTOR/HUB	153.41	2	\$306.81

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PTX20353	DISC BRAKE LUBE	7.91	1	\$7.91
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	23.34	2	\$46.68
					PARTS	510.99

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 16262

Work Order Notes

(LPATE) TOOK TO FIRESTONE FOR ALIGNMENT AND NOTICED BRAKES PULSATING BAD.

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LPATE) REPLACED WORN OUT FRONT PADS AND ROTORS. REPLACED AND PACKED WHEEL BEARINGS AND REPLACED THE SEALS. REAR BRAKES STILL GOOD GOOD. TEST DROVE OK

06-13 - INSPECT BRAKES

(LPATE) CHECKED BRAKES FRONT BRAKES ARE WORN

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LPATE) WOULD NOT FIT ON FIRESTONE RACK TOOK TRUCK TO FRED ROBERTSON TO COMPLETE ALIGNMENT. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FRED ROBERTSON BY GM

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 16768

USING DEPT NO:	504303	OPENED DATE:	04/28/2014 15:11:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/29/2014 08:08:49	METER 1 - M:	102361	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2014 08:08:50	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$9.59	\$73.72	\$0.00	\$83.31

JOB COUNT: 1	WORK ORDER TOTAL:					0.17	9.59	73.72	0.00	83.31
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	04/29/2014 07:36:52	04/29/2014 07:46:52	0.17	\$9.59
					LABOR	9.59

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	23.39	1	\$23.39
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
					PARTS	73.72

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 16768

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM/SH-CLEANED TRACKS ON THE LIFTGATE. OPERATING SMOOTHLY. CHECKED OK

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 17224

USING DEPT NO: 504303	OPENED DATE: 06/06/2014 14:10:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/16/2014 13:13:42	METER 1 - M: 104799 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/16/2014 13:13:45	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$188.91	\$188.91
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	2.00	\$115.00	\$72.07	\$0.00	\$187.07
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$33.72	\$0.00	\$48.10
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.55	\$31.63	\$0.00	\$0.00	\$31.63
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.15	\$65.92	\$0.00	\$0.00	\$65.92

JOB COUNT: 5	WORK ORDER TOTAL:	3.95	226.93	105.79	188.91	521.63
---------------------	--------------------------	-------------	---------------	---------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11245625	322086	0024219	\$188.91
				COMML	188.91

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11568366	06/13/2014 07:00:00	06/13/2014 09:00:00	2.00	\$115.00
66-79-003	PERFORM SAFETY INSPECTION	11338644	06/09/2014 14:30:00	06/10/2014 09:15:00	18.75	\$1,078.13
66-79-003	PERFORM SAFETY INSPECTION	11338644	06/09/2014 13:58:22	06/09/2014 14:15:00	0.28	\$15.94
16-02	TRANSPORT CAB & SHEET METAL	11255091	06/10/2014 08:19:02	06/10/2014 08:52:02	0.55	\$31.63
66-79-003	PERFORM SAFETY INSPECTION	11338644	06/09/2014 14:30:00	06/10/2014 09:15:00	(18.75)	(\$1,078.13)
66-79-003	PERFORM SAFETY INSPECTION	11338644	06/10/2014 09:30:00	06/10/2014 10:22:09	0.87	\$49.98
16-02	TRANSPORT CAB & SHEET METAL	11255091	06/10/2014 14:19:04	06/10/2014 14:19:04	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11338644	06/13/2014 07:00:00	06/13/2014 07:15:00	0.25	\$14.38
					LABOR	226.93

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	1	\$16.86
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	(1)	(\$16.86)
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	2	\$33.72
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABPGD802M	REAR BRAKE PADS	72.07	1	\$72.07

Work Order Charge Detail

PARTS	105.79
--------------	---------------

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 17224

Work Order Notes

(LPATE) DO SAFETY INSPECTION WILL VEHICLE NEED ANY REPAIRS IN THE NEXT 12 MO? CHECK WINDSHIELD FOR DING OR CRACK.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LPATE) ROZAR'S REMOVED AND INSTALLED A NEW WINDSHIELD. PD BY CC

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(IFALLS) REPLACED REAR BRAKE PADS WERE WORN AND SCUFFED REAR ROTORS. TEST DROVE OK

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

16-02 - TRANSPORT CAB & SHEET METAL

(LPATE) TAKEN TO ROZAR'S BY NT

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) SAFETY INSPECTION COMPLETE. NEEDED WIPERS, A NEW WINDSHILED AND REAR BRAKE PADS. ALL COMPLETED. INSPECTION SHEET ATTACHED

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 17750

USING DEPT NO:	504303	OPENED DATE:	08/07/2014 08:29:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/07/2014 14:54:41	METER 1 - M:	104822	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/07/2014 14:54:42	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.19	\$10.88	\$131.87	\$0.00	\$142.75

JOB COUNT: 1	WORK ORDER TOTAL:					0.19	10.88	131.87	0.00	142.75
---------------------	--------------------------	--	--	--	--	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11074414	08/07/2014 08:30:34	08/07/2014 08:41:55	0.19	\$10.88
					LABOR	10.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	65-1	BATTERY- FORD TOP POST HD	131.87	1	\$131.87
					PARTS	131.87

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 17750

Work Order Notes

(LPATE) BATTERY DEAD

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) CHARGED STILL FAILED. REPLACED BATTERY

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 17904

Work Order Notes

(LPATE) ALLEN REQUESTED WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 17980

USING DEPT NO: 504303	OPENED DATE: 09/04/2014 14:38:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2014 10:12:46	METER 1 - M: 107317 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/08/2014 10:12:47	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$61.52	\$0.00	\$79.35

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	61.52	0.00	79.35
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/05/2014 11:05:04	09/05/2014 11:23:40	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/05/2014 11:05:04	09/05/2014 11:53:12	(0.80)	(\$46.13)
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/05/2014 11:05:04	09/05/2014 11:53:12	0.80	\$46.13
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	11.19	1	\$11.19
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
					PARTS	61.52

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 17980

Work Order Notes

(LPATE) PM
(GMANNING) CHAINS ON LIFT GATE ARE BROKEN. ADVISED TAMMY THAT THEY WOULD HAVE TO PUT IN A WORK ORDER TO THE WELDING SHOP TO HAVE THOSE REPAIRED.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(GMANNING) PM BY RS

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 18219

USING DEPT NO: 504303	OPENED DATE: 09/24/2014 14:18:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/25/2014 09:56:57	METER 1 - M: 108869 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/25/2014 09:56:58	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CL-55-002	CLEANED VERTICAL SLIDES-PWR TAIL	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-55-002	CLEANED VERTICAL SLIDES-PWR TAIL GATE	11074414	09/24/2014 14:21:29	09/24/2014 15:21:29	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 18219

Work Order Notes

(LPATE) PER ALLEN LIFTGATE IS CHATTERING WHEN GOING UP AND DOWN.

Job Notes

CL-55-002 - CLEANED VERTICAL SLIDES-PWR TAIL GATE

(LPATE) WELDERS REPAIRED LIFTGATE..THEN SCOTT WASHED OUT TRACKS WITH MINERAL SPIRITS. OPERATED UP AND DOWN. WORKING GOOD

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 18597

USING DEPT NO: 504303	OPENED DATE: 10/31/2014 14:11:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/03/2014 08:00:14	METER 1 - M: 111583 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/03/2014 08:00:16	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-72-004	ADJUST REAR DOOR ASSEMBLY - ROL	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
01-72-004	ADJUST REAR DOOR ASSEMBLY - ROLL-UP	11074414	10/31/2014 14:13:10	10/31/2014 14:43:10	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 18597

Work Order Notes

(LPATE) PER ALLEN ROLL UP DOOR HARD TO OPEN

Job Notes

01-72-004 - ADJUST REAR DOOR ASSEMBLY - ROLL-UP

(LPATE) ADJUSTED ROLLERS ON ROLL UP DOOR. RECHECKED OK

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 18858

USING DEPT NO: 504303	OPENED DATE: 11/21/2014 11:46:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/24/2014 11:17:37	METER 1 - M: 113121 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/24/2014 11:17:38	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$37.23	\$45.47	\$0.00	\$82.70

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.65** **37.23** **45.47** **0.00** **82.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11397026	11/24/2014 07:00:00	11/24/2014 07:18:36	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11338644	11/24/2014 08:36:50	11/24/2014 08:57:05	0.34	\$19.41
					LABOR	37.24

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
					PARTS	45.47

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 18858

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(GMANNING) PM BY BG/RS

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 19536

USING DEPT NO:	504303	OPENED DATE:	02/13/2015 07:49:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/13/2015 14:55:28	METER 1 - M:	117673	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/13/2015 14:55:29	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$50.33	\$0.00	\$68.16

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	50.33	0.00	68.16
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/13/2015 11:07:06	02/13/2015 11:25:42	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
					PARTS	50.33

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 19536

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULL SYN. OIL QT

Manufacturer :

Part No : FL820S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

(LPATE) PM BY GM/SH-CHECKED OPERATION OF LIFTGATE. CLEANED RAILS AND LUBED SPROCKETS

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 20031

USING DEPT NO:	504303	OPENED DATE:	04/17/2015 07:58:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/21/2015 10:09:16	METER 1 - M:	122260	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/21/2015 10:09:17	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.67	\$0.00	\$62.50

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 44.67 0.00 62.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	04/20/2015 07:00:00	04/20/2015 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.19	1	\$5.19
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
					PARTS	44.67

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 20031

Work Order Notes

(LPATE) PM-INSPECT LIFT GATE

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY RS-INSPECTED LIFT GATE RUNNING GOOD

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 20069

USING DEPT NO: 504303	OPENED DATE: 04/21/2015 15:51:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/27/2015 07:00:43	METER 1 - M: 122536 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/27/2015 07:00:44	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.60	\$149.50	\$633.73	\$0.00	\$783.23
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	4.00	\$230.00	\$241.85	\$0.00	\$471.85
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 3	WORK ORDER TOTAL:	7.10	408.25	875.58	0.00	1,283.83
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	04/24/2015 10:06:00	04/24/2015 12:06:00	2.00	\$115.00
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	04/24/2015 10:06:00	04/24/2015 12:06:00	(2.00)	(\$115.00)
06-13	INSPECT BRAKES	11213180	04/24/2015 07:00:00	04/24/2015 07:30:00	0.50	\$28.75
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	04/24/2015 10:06:00	04/24/2015 14:06:00	4.00	\$230.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	04/24/2015 07:30:00	04/24/2015 10:06:00	2.60	\$149.50
					LABOR	408.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF387AS	BEARING	28.35	(2)	(\$56.70)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF387AS	BEARING	22.68	2	\$45.36
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF382A	BEARING	12.90	2	\$25.80
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF382A	BEARING	16.13	(2)	(\$32.25)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR38	BEARING	19.99	2	\$39.98
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR38	BEARING	24.99	(2)	(\$49.98)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAB66834	BRAKE ROTOR	151.16	(2)	(\$302.31)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAB66834	BRAKE ROTOR	120.93	2	\$241.85
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRE09886610	ROTOR	246.45	(2)	(\$492.90)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRE09886610	ROTOR	197.16	2	\$394.32
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF387AS	BEARING	28.35	2	\$56.70
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF382A	BEARING	16.13	2	\$32.25
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR38	BEARING	24.99	2	\$49.98

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAB66834	BRAKE ROTOR	151.16	2	\$302.31
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRE09886610	ROTOR	246.45	2	\$492.90
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	4.86	3	\$14.58
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF28754	REAR WHEEL SEAL	17.52	2	\$35.04
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF24000	GREASE SEAL	13.28	2	\$26.55
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	23.06	2	\$46.11
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	19.19	2	\$38.37
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	3.80	3	\$11.41
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	4.86	(3)	(\$14.58)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	18.45	2	\$36.89
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	23.06	(2)	(\$46.11)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	15.35	2	\$30.70
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	19.19	(2)	(\$38.37)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF24000	GREASE SEAL	10.62	2	\$21.24
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF24000	GREASE SEAL	13.28	(2)	(\$26.55)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF28754	REAR WHEEL SEAL	14.02	2	\$28.03
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF28754	REAR WHEEL SEAL	17.52	(2)	(\$35.04)
					PARTS	\$75.58

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 20069

Work Order Notes

(LPATE) CHECK BRAKES SHAKING BAD WHEN BRAKING
RS CLEANED THE TRACKS ON THE LIFTGATE

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LPATE) REPLACED FRONT PADS, ROTORS, BEARINGS AND SEALS. PACKED BEARINGS WITH GREASE

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(RWINTERS) REPLACED REAR PADS, ROTORS, BEARINGS AND SEALS. TEST DROVE OK
(RWINTERS) TOPPED OFF AXLE FLUID

03-54-002 - REPLACE NEW ALARM - BACK-UP

06-13 - INSPECT BRAKES

(LPATE) CHECKED BRAKES ARE WORN

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 20811

USING DEPT NO: 504303	OPENED DATE: 07/16/2015 08:31:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/24/2015 18:00:00	METER 1 - M: 124709 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/24/2015 18:00:00	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-15-010	REPLACE NEW BALL JOINT	DON	P	N	GARAGE	3.80	\$218.60	\$187.08	\$0.00	\$405.68
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,046.12	\$1,046.12
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.95	\$54.56	\$20.47	\$0.00	\$75.03
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.77	\$44.29	\$0.00	\$0.00	\$44.29
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$13.64	\$38.77	\$0.00	\$52.41

JOB COUNT: 6	WORK ORDER TOTAL:	6.76	388.59	246.32	1,046.12	1,681.03
---------------------	--------------------------	-------------	---------------	---------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11321046	162906	0029377	\$1,046.12
				COMML	1046.12

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-010	REPLACE NEW BALL JOINT	11213180	07/22/2015 14:30:00	07/22/2015 18:09:00	3.65	\$209.88
03-15-010	REPLACE NEW BALL JOINT	11213180	07/22/2015 14:05:54	07/22/2015 14:15:00	0.15	\$8.72
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/16/2015 09:47:01	07/16/2015 10:01:15	0.24	\$13.64
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/16/2015 10:01:22	07/16/2015 10:58:18	0.95	\$54.56
03-15-010	REPLACE NEW BALL JOINT	11213180	07/22/2015 14:30:00	07/23/2015 07:09:09	16.65	\$957.52
03-15-010	REPLACE NEW BALL JOINT	11213180	07/22/2015 14:30:00	07/23/2015 07:09:09	(16.65)	(\$957.52)
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	07/23/2015 11:13:47	07/23/2015 12:00:00	0.77	\$44.29
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	07/23/2015 12:59:43	07/23/2015 12:59:43	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11074414	07/24/2015 06:00:00	07/24/2015 07:00:00	1.00	\$57.50
					LABOR	388.59

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	4.51	7	\$31.58
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.85	1	\$3.85

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	10.24	2	\$20.47
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.34	1	\$3.34
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ7025	BALL JOINT	40.32	2	\$80.64
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ1030	BALL JOINT	53.22	2	\$106.44
					PARTS	246.32

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 20811

Work Order Notes

(LPATE) PM-DO ANNUAL SAFETY INSPECTION

Job Notes

03-15-010 - REPLACE NEW BALL JOINT

(LPATE) REPLACED BOTH UPPER AND LOWER BALL JOINTS ON BOTH SIDES DUE TO EXCESSIVE WEAR.

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) OK TIRE REPLACED 6 TIRES AND ALIGNED. PD BY CC

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO OK TIRE BY AY

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) SAFETY INSPECTION COMPLETE. SEE ATTACHED

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 21527

USING DEPT NO: 504303	OPENED DATE: 09/24/2015 10:30:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2015 07:32:31	METER 1 - M: 128526 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2015 07:32:32	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-35-006	REPLACE NEW FUSE(S)	DON	O	N	GARAGE	0.30	\$17.25	\$2.41	\$0.00	\$19.66
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.08	\$0.00	\$50.91

JOB COUNT: 3	WORK ORDER TOTAL:	0.61	35.08	35.49	46.00	116.57
---------------------	--------------------------	-------------	--------------	--------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	227585	0030394	\$46.00
COMML					46.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/25/2015 07:00:00	09/25/2015 07:18:36	0.31	\$17.83
03-35-006	REPLACE NEW FUSE(S)	11338644	09/25/2015 07:18:36	09/25/2015 07:36:36	0.30	\$17.25
LABOR					35.08	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-35-006	REPLACE NEW FUSE(S)	7822075	FUSE HOLDER	2.41	1	\$2.41
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.78	1	\$2.78
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
PARTS					35.49	

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 21527

Work Order Notes

(LISAPATE) PM-REPAIR WINDSHIELD

Job Notes

03-35-006 - REPLACE NEW FUSE(S)

(LISAPATE) INSTALLED NEW FUSE LINK ON THE POSITIVE BATTERY CABLE DUE TO BROKEN.

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) GLASS DR CAME TO GARAGE AND REPAIRED DING IN THE WINDSHIELD. PD BY CC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULL SYN. OIL QT

Manufacturer :

Part No : FL820S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

(LISAPATE) PM BY RS

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 21988

USING DEPT NO: 504303	OPENED DATE: 11/13/2015 07:15:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/20/2015 06:49:16	METER 1 - M: 132725 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/20/2015 06:49:18	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.02	\$58.91	\$33.08	\$0.00	\$91.99
CL-55-002	CLEANED VERTICAL SLIDES-PWR TAIL	DON	O	N	GARAGE	0.50	\$28.75	\$21.73	\$0.00	\$50.48

JOB COUNT: 2 **WORK ORDER TOTAL:** 1.52 87.66 54.81 0.00 142.47

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-55-002	CLEANED VERTICAL SLIDES-PWR TAIL GATE	10260422	11/19/2015 06:00:00	11/19/2015 06:30:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/13/2015 10:06:28	11/13/2015 11:07:56	1.02	\$58.91
					LABOR	87.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-55-002	CLEANED VERTICAL SLIDES-PWR TAIL GATE	51322H	PAINT THINNER	21.73	1	\$21.73
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.78	1	\$2.78
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
					PARTS	54.81

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 21988

Work Order Notes

(LISAPATE) PM-CHECK LIFTGATE IS BOUNCING

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY GM

CL-55-002 - CLEANED VERTICAL SLIDES-PWR TAIL GATE

(LISAPATE) CLEANED LIFTGATE RAILS AND SLIDES WITH PAINT THINNER. RECHECKED OK

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 22649

USING DEPT NO: 504303	OPENED DATE: 02/26/2016 08:21:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/07/2016 11:45:13	METER 1 - M: 139586 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/07/2016 11:45:14	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$74.74	\$74.74
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.91	\$167.56	\$37.24	\$0.00	\$204.80

JOB COUNT: 3	WORK ORDER TOTAL:	2.91	167.56	37.24	74.74	279.54
---------------------	--------------------------	-------------	---------------	--------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11321046	165832	0032469	\$74.74	
					COMML	74.74

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10337093	03/07/2016 07:00:00	03/07/2016 08:00:00	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/04/2016 09:35:11	03/04/2016 11:30:02	1.91	\$110.06
					LABOR	167.56

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
					PARTS	37.24

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 22649

Work Order Notes

(LISAPATE) PM

Job Notes

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) NEEDED AN ALIGNMENT DUE TO TIRE WEAR. OK TIRE COMPLETED ALIGNMENT. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO OK BY AY

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY SH-REPLACED AIR FILTER-INSPECTED LIFTGATE GREASED CHAINS, CLEANED TRACKS AND CHECKED FLUID

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 24476

USING DEPT NO: 504303	OPENED DATE: 09/29/2016 07:39:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/29/2016 09:06:13	METER 1 - M: 140612 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/29/2016 09:06:16	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-15-009	REPLACE NEW TIE ROD	DON	O	N	GARAGE	1.30	\$74.75	\$98.26	\$0.00	\$173.01
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$94.54	\$0.00	\$123.29
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	3.20	\$184.00	\$72.96	\$0.00	\$256.96
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$2.04	\$0.00	\$2.04
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$195.50	\$195.50
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	16.00	\$920.00	\$34.62	\$0.00	\$954.62
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$28.52	\$0.00	\$46.35
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.50	\$28.75	\$9.40	\$0.00	\$38.15
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	1.00	\$57.50	\$80.05	\$0.00	\$137.55

JOB COUNT: 11 **WORK ORDER TOTAL: 24.81 1,426.58 420.39 195.50 2,042.47**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11074243	17621	0035521	\$195.50
					COMML 195.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11792814	09/29/2016 08:08:56	09/29/2016 16:08:56	8.00	\$460.00
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	10208562	09/29/2016 08:08:30	09/29/2016 16:08:30	8.00	\$460.00
03-33-004	REPLACE NEW SPARK PLUGS	11758845	09/29/2016 08:05:56	09/29/2016 11:17:56	3.20	\$184.00
03-15-009	REPLACE NEW TIE ROD	11397026	09/29/2016 08:05:40	09/29/2016 09:23:40	1.30	\$74.75
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11758845	09/29/2016 08:01:07	09/29/2016 09:01:07	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	09/29/2016 08:01:00	09/29/2016 08:31:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11758845	09/29/2016 08:00:44	09/29/2016 08:19:20	0.31	\$17.83

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11758845	09/29/2016 08:00:53	09/29/2016 09:00:53	1.00	\$57.50
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	09/29/2016 08:01:33	09/29/2016 09:01:33	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11758845	09/29/2016 08:01:16	09/29/2016 08:31:16	0.50	\$28.75
					LABOR	1426.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-33-004	REPLACE NEW SPARK PLUGS	ALPAPP103	SPARK PLUGS	5.15	8	\$41.20
66-PM-PMT	PERFORM TRANSMISSION SERVICE	3C3Z7B155BA	IN-LINE TRANSMISSION FILTER	25.83	1	\$25.83
03-33-004	REPLACE NEW SPARK PLUGS	STWSPP39E	BOOT	3.97	8	\$31.76
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	MMM08984	3M ADHESIVE REMOVER	17.31	1	\$17.31
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	MMM08984	3M ADHESIVE REMOVER	17.31	1	\$17.31
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	224	\$22.40
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
03-32-002	REPLACE NEW BATTERY	65X	BATTERY-EXTREME-FORD TOP POT	94.54	1	\$94.54
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.14	1	\$2.14
66-PM-PMT	PERFORM TRANSMISSION SERVICE	VV324	TRANS FLUID QT	4.25	8	\$34.00
03-15-009	REPLACE NEW TIE ROD	TRWJSA1027	ADJUSTING SLEEVES	17.11	1	\$17.11
03-15-009	REPLACE NEW TIE ROD	TRWJTE7035	TIE ROD END	35.71	1	\$35.71
03-15-009	REPLACE NEW TIE ROD	TRWJSA1025	ADJUSTING SLEEVE	20.29	1	\$20.29
03-15-009	REPLACE NEW TIE ROD	TRWJTE1549	TIE ROD END	25.15	1	\$25.15
66-PM-PMT	PERFORM TRANSMISSION SERVICE	BALP7247	TRANS. FILTER	9.46	1	\$9.46
66-PM-PMT	PERFORM TRANSMISSION SERVICE	BAL20005	TRANS. FILTER	10.76	1	\$10.76
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33595	FUEL FILTER	9.40	1	\$9.40
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	1.02	2	\$2.04
					PARTS	420.39

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 24476

Work Order Notes

(LISAPATE) CLEAN GATE-REMOVE WORDMARKS-DO SI- PM-TUNE UP

Job Notes

03-15-009 - REPLACE NEW TIE ROD

(LISAPATE) REPLACED BOTH OUTER TIE RODS AND SLEEVES

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) REPLACED BATTERY

03-33-004 - REPLACE NEW SPARK PLUGS

(LISAPATE) REPLACED ALL 8 SPARK PLUGS AND COIL BOOTS

03-51-046 - REPLACE NEW KEY BLANK(S)

(LISAPATE) CUT 2 KEYS

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) FRED ROBERTSON COMPLETED ALIGNMENT. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO FRED ROBERTSON BY EK

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(LISAPATE) REMOVED ALL OLD LETTERING AND CLEANED WITH ADHESIVE

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) SAFETY INSPECTION COMPLETED. SEE ATTACHED

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE) REPLACED FUEL FILTER

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(LISAPATE) REMOVED PAN REPLACED FILTER, REPLACED TOILET PAPER FILTER. AND TRANS FUEL FILTER. REINSTALLED. TORQUED TRANS PAN TO (14NM) AS CALLED FOR VIA MITCHELL. ADDED 71/2QTS OF FLUID. TEST DROVE. RECHECKED OK

Work Order Charge Detail

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 24624

USING DEPT NO:	504303	OPENED DATE:	10/13/2016 14:16:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/17/2016 10:48:28	METER 1 - M:	140965	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2016 10:48:30	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-004	REPLACE NEW STARTER DRIVE	DON	O	N	GARAGE	0.90	\$51.75	\$87.94	\$0.00	\$139.69
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 2 WORK ORDER TOTAL: 1.20 69.00 87.94 0.00 156.94

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11213180	10/13/2016 14:19:06	10/13/2016 14:37:06	0.30	\$17.25
03-32-004	REPLACE NEW STARTER DRIVE	11213180	10/13/2016 14:19:17	10/13/2016 15:13:17	0.90	\$51.75
					LABOR	69.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-004	REPLACE NEW STARTER DRIVE	REM28662	REMAN STARTER	87.94	1	\$87.94
					PARTS	87.94

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 24624

Work Order Notes

(LISAPATE) RECYCLING REQUESTED A SERVICE CALL

Job Notes

03-32-004 - REPLACE NEW STARTER DRIVE

(LISAPATE) REMOVED AND REPLACED STARTER. RECHECKED OK

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED FOUND STARTER NOT ENGAGING

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 24652

USING DEPT NO: 504303	OPENED DATE: 10/17/2016 11:11:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/25/2016 13:51:21	METER 1 - M: 140965 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/25/2016 13:51:23	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-55-028	ADJUST MASTER CONTROL SWITCH	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
14-02-023	INSTALL HANDLES - INNER & OUTER	DON	O	N	GARAGE	0.30	\$17.25	\$7.40	\$0.00	\$24.65
14-52-024	INSTALL BACK UP CAMERA	DON	O	N	GARAGE	5.78	\$332.35	\$371.34	\$0.00	\$703.69

JOB COUNT: 3	WORK ORDER TOTAL:	7.08	407.10	378.74	0.00	785.84
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-023	INSTALL HANDLES - INNER & OUTER	11170580	10/25/2016 07:00:00	10/25/2016 07:18:00	0.30	\$17.25
01-55-028	ADJUST MASTER CONTROL SWITCH	11170580	10/25/2016 07:18:00	10/25/2016 08:18:00	1.00	\$57.50
14-52-024	INSTALL BACK UP CAMERA	11170580	10/21/2016 15:27:50	10/21/2016 21:14:38	5.78	\$332.35
14-52-024	INSTALL BACK UP CAMERA	11170580	10/21/2016 15:27:50	10/24/2016 09:14:29	65.78	\$3,782.21
14-52-024	INSTALL BACK UP CAMERA	11170580	10/21/2016 15:27:50	10/24/2016 09:14:29	(65.78)	(\$3,782.21)
					LABOR	407.10

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-024	INSTALL BACK UP CAMERA	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	8.37	1	\$8.37
14-52-024	INSTALL BACK UP CAMERA	CWI16/4SJ	CABLE	4.62	1	\$4.62
14-52-024	INSTALL BACK UP CAMERA	CWI16/4SJ	CABLE	0.46	(10)	(\$4.62)
14-52-024	INSTALL BACK UP CAMERA	EMT STRAP	1-HOLE EMT STRAP	1.65	2	\$3.30
14-52-024	INSTALL BACK UP CAMERA	3/4 ELBOW	3/4" ELBOW	0.82	2	\$1.64
14-52-024	INSTALL BACK UP CAMERA	3/4 X 10 PVC PIPE	3/4 X 10 PVC PIPE	2.23	2	\$4.46
14-52-024	INSTALL BACK UP CAMERA	CWI16/4SJ	CABLE	0.46	10	\$4.62
14-02-023	INSTALL HANDLES - INNER & OUTER	DOR42410	LATCH	7.40	1	\$7.40
14-52-024	INSTALL BACK UP CAMERA	IATV205A	BACK UP CAMERA SYSTEM	319.00	1	\$319.00
14-52-024	INSTALL BACK UP CAMERA	RUSH CHARGE	SAME DAY RUSH CHARGE	15.00	1	\$15.00
14-52-024	INSTALL BACK UP CAMERA	SHIPPING	SHIPPING AND HANDLING	14.95	1	\$14.95
					PARTS	378.74

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 24652

Work Order Notes

(LISAPATE) INSTALL BACK UP CAMERA- FIX WALK THRU DOOR-RELOCATE HANDHELD REMOVE FROM FLOOR

Job Notes

01-55-028 - ADJUST MASTER CONTROL SWITCH

(LISAPATE) RELOCATED PLUG ON CARGO WALL FOR THE REMOTE LIFTGATE.

14-02-023 - INSTALL HANDLES - INNER & OUTER

(LISAPATE) INSTALLED DOOR LATCH ON DOOR GOING TO CARGO AREA

14-52-024 - INSTALL BACK UP CAMERA

(LISAPATE) WIRED AND INSTALLED BACK UP CAMERA SYSTEM. CHECKED OK

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 2500

USING DEPT NO: 504303	OPENED DATE: 11/25/2008 09:26:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/26/2008 07:08:30	METER 1 - M: 36563 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 11/26/2008 07:08:31	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
07-02-016	LUBRICATE TAIL&LIFT GATE	DON	P	N	GARAGE	0.50	\$28.75	\$6.01	\$0.00	\$34.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$67.56	\$0.00	\$85.39

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **46.58** **73.57** **0.00** **120.15**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
07-02-016	LUBRICATE TAIL&LIFT GATE	11089300	11/25/2008 10:18:36	11/25/2008 10:48:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11089300	11/25/2008 10:00:00	11/25/2008 10:18:36	0.31	\$17.83
					LABOR	46.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	8.99	1	\$8.99
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	23.83	1	\$23.83
07-02-016	LUBRICATE TAIL&LIFT GATE	RADL616	WHITE LITHIUM	6.01	1	\$6.01
					PARTS	73.57

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 2500

Work Order Notes

(LPATE) PM-LUBRICATE REAR LIFTGATE

Job Notes

07-02-016 - LUBRICATE TAIL&LIFT GATE

(LPATE) CLEANED, LUBRICATED, AND ADJUSTED REAR LIFT GATE

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part FA1632 FILTER-AIR FORD Qty 1 Cost 0

Part 5W20 MOTOR OIL Qty 224 Cost 0

Part 1198 OIL PLUG FORD Qty 1 Cost 0

Part 51372 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY MS

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 26

USING DEPT NO: 504303	OPENED DATE: 09/10/2007 09:05:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/10/2007 09:09:54	METER 1 - M: 11095 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 09/10/2007 09:10:08	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$30.14	\$0.00	\$44.09

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **13.95** **30.14** **0.00** **44.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11089300	09/10/2007 09:10:00	09/10/2007 09:28:36	0.31	\$13.95
					LABOR	13.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	6.62	1	\$6.62
					PARTS	30.14

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 26

Work Order Notes

(LOBRIEN) PM.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM by Michael Stamps.

Work Order Charge Detail

UNIT NO: 236965 **2006 FORD E350**

WORK ORDER NO: 26652

USING DEPT NO: 504303	OPENED DATE: 06/20/2017 13:49:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/27/2017 07:29:35	METER 1 - M: 143439 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/27/2017 07:29:37	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.18	\$0.00	\$17.43
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$51.96	\$19.54	\$0.00	\$71.50

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.20** **69.21** **19.72** **0.00** **88.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/22/2017 13:00:00	06/22/2017 13:54:13	0.90	\$51.96
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/22/2017 09:30:00	06/22/2017 12:00:00	2.50	\$143.75
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/22/2017 07:22:02	06/22/2017 09:15:00	1.88	\$108.26
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/22/2017 09:30:00	06/22/2017 12:00:00	(2.50)	(\$143.75)
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/22/2017 07:22:02	06/22/2017 09:15:00	(1.88)	(\$108.26)
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11758845	06/22/2017 07:21:56	06/22/2017 07:22:02	0.00	(\$0.10)
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11758845	06/22/2017 07:21:56	06/22/2017 07:22:02	0.00	\$0.10
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11758845	06/22/2017 07:21:56	06/22/2017 07:39:56	0.30	\$17.25
					LABOR	69.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	224	\$13.44
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	1156	BULB-BACK UP	0.18	1	\$0.18
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
					PARTS	19.72

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 26652

Work Order Notes

(LISAPATE) PM

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) REPLACED RR REVERSE LIGHT

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS

COOLANT -40'

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 27608

USING DEPT NO:	504303	OPENED DATE:	09/27/2017 11:49:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2017 07:45:15	METER 1 - M:	145113	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2017 07:45:17	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$1.02	\$0.00	\$1.02

JOB COUNT: 1	WORK ORDER TOTAL:					0.00	0.00	1.02	0.00	1.02
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	1.02	1	\$1.02
					PARTS	1.02

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 27608

Work Order Notes

(LISAPATE) DRIVER REQUESTED 1 KEY

Job Notes

03-51-046 - REPLACE NEW KEY BLANK(S)

(LISAPATE) CUT 1 NEW KEY

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 27973

USING DEPT NO: 504303	OPENED DATE: 10/27/2017 10:36:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2017 11:48:35	METER 1 - M: 14504 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 11/06/2017 11:48:37	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-02-016	ADJUST TAIL&LIFT GATE	DON	P	N	GARAGE	0.23	\$13.05	\$0.00	\$0.00	\$13.05
03-18-001	REPLACE NEW FRONT AXLE HUBS & B	DON	P	N	GARAGE	3.00	\$172.50	\$149.92	\$0.00	\$322.42
06-34-004	INSPECT CLEARANCE/MARKER	DON	P	N	GARAGE	0.50	\$28.75	\$0.53	\$0.00	\$29.28
09-15	ALIGN STEERING	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$127.51	\$127.51
16-15	TRANSPORT STEERING	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	P	N	GARAGE	1.20	\$69.00	\$17.93	\$0.00	\$86.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$25.28	\$0.00	\$43.11
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$911.77	\$911.77

JOB COUNT: 8	WORK ORDER TOTAL:	6.24	358.63	193.66	1,039.28	1,591.57
---------------------	--------------------------	-------------	---------------	---------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11074891	CTCS357919	0040976	\$127.51
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11321046	9110-1016307	0040975	\$911.77
COMML					1039.28

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-15	TRANSPORT STEERING	10208562	11/03/2017 07:00:00	11/03/2017 08:00:00	1.00	\$57.50
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	11170580	11/03/2017 07:00:00	11/03/2017 10:00:00	3.00	\$172.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/27/2017 13:35:45	10/27/2017 13:54:21	0.31	\$17.83
06-34-004	INSPECT CLEARANCE/MARKER	11074414	10/27/2017 13:36:13	10/27/2017 14:06:13	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/27/2017 13:03:11	10/27/2017 14:00:00	(0.95)	(\$54.45)
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/27/2017 14:15:00	10/27/2017 14:35:20	(0.34)	(\$19.49)
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/27/2017 13:03:11	10/27/2017 14:00:00	0.95	\$54.45
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/27/2017 14:15:00	10/27/2017 14:35:20	0.34	\$19.49
01-02-016	ADJUST TAIL&LIFT GATE	11074414	10/27/2017 14:35:31	10/27/2017 14:49:08	0.23	\$13.05

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-34-004	INSPECT CLEARANCE/MARKER	11074414	10/27/2017 14:49:18	10/27/2017 15:45:28	(0.94)	(\$53.83)
06-34-004	INSPECT CLEARANCE/MARKER	11074414	10/27/2017 14:49:18	10/27/2017 15:45:28	0.94	\$53.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/03/2017 06:00:00	11/03/2017 07:12:00	1.20	\$69.00
					LABOR	358.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	224	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
06-34-004	INSPECT CLEARANCE/MARKER	ATM20	FUSE-20 AMP MINI	0.53	1	\$0.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	LT1	19.5 WHEEL WEIGHT	0.51	15	\$7.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22611	METAL EXTENSION 1.25 LENGTH	1.25	4	\$5.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	0.88	6	\$5.28
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	CRS24000	GREASE SEALS	11.35	2	\$22.70
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	SKFBR15101	OUTER WHEEL BEARING	10.31	2	\$20.62
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	SKFBR50	BEARINGS	16.81	2	\$33.62
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	SKFBR15101	OUTER WHEEL BEARING	10.31	(2)	(\$20.62)
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	SKFBR15101	OUTER WHEEL BEARING	12.94	2	\$25.88
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	SKFBR15245	BEARINGS	5.01	2	\$10.02
03-18-001	REPLACE NEW FRONT AXLE HUBS & BEARINGS	RABSP655TRH	BRAKE PADS	57.70	1	\$57.70
					PARTS	193.66

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 27973

Work Order Notes

(IFALLS) PM INSPECT REAR LIFT GATE

Job Notes

01-02-016 - ADJUST TAIL&LIFT GATE

(IFALLS) SH CLEANED LIFT GATE TRACKS

03-18-001 - REPLACE NEW FRONT AXLE HUBS & BEARINGS

(IFALLS) AB REPLACED LEFT AND RIGHT FRONT INNER AND OUTER WHEEL BEARINGS AND GREASE SEALS

(IFALLS) AB ALSO REPLACED FRONT BRAKE PADS

06-34-004 - INSPECT CLEARANCE/MARKER

(GARAGE) SH FOUND MARKER LIGHTS INOP AND FOUND BLOWN FUSE

09-15 - ALIGN STEERING

(IFALLS) TUSCALOOSA CHEVY PERFORMED ALIGNMENT

16-15 - TRANSPORT STEERING

(IFALLS) EK PERFORMED TRANSPORT

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(IFALLS) SH MOUNTED AND BALANCED 6 TIRES

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(GARAGE) SH PERFORMED PM

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(IFALLS) PURCHASED 6 TIRES FROM TIRE ENGINEER

Work Order Charge Detail

UNIT NO: 236965 **2006 FORD E350**

WORK ORDER NO: 29221

USING DEPT NO: 504303	OPENED DATE: 03/28/2018 08:20:50	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/03/2018 10:46:56	METER 1 - M: 146187 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/03/2018 10:46:57	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$17.98	\$0.00	\$35.81
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.00	\$0.00	\$4.86	\$0.00	\$4.86

JOB COUNT: 3	WORK ORDER TOTAL:	0.56	32.21	39.90	0.00	72.11
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/29/2018 07:00:00	03/29/2018 07:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	10208562	03/29/2018 07:00:00	03/29/2018 07:15:00	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.00	7	\$14.00
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	VV324	TRANS FLUID QT	4.86	1	\$4.86
					PARTS	39.90

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 29221

Work Order Notes

(LISAPATE) CHECK TRANSMISSION FLUID IS LOW

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY SH,EK/AG

COOLANT -15'

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(LISAPATE) TOPPED OFF FLUID CHECKED FLUIDS. NO LEAKS FOUND

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 294

USING DEPT NO: 504303	OPENED DATE: 10/24/2007 08:09:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/24/2007 08:12:44	METER 1 - M: 15211 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 10/24/2007 08:12:44	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$27.47	\$0.00	\$41.42

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **13.95** **27.47** **0.00** **41.42**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	10/24/2007 08:10:00	10/24/2007 08:28:36	0.31	\$13.95

LABOR **13.95**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.09	224	\$20.16
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.31	1	\$7.31

PARTS **27.47**

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 294

Work Order Notes

(LOBRIEN) PM.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY JASON ELMORE (GREASED THE LIFT). -5°

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 29422

USING DEPT NO:	504303	OPENED DATE:	04/16/2018 10:13:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/18/2018 07:02:34	METER 1 - M:	146384	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/18/2018 07:02:36	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$23.00	\$3.61	\$0.00	\$26.61

JOB COUNT: 1	WORK ORDER TOTAL:					0.40	23.00	3.61	0.00	26.61
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	04/16/2018 13:07:53	04/16/2018 13:31:53	0.40	\$23.00
					LABOR	23.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.34	1	\$2.34
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.26	1	\$0.26
66-17-030	PERFORM TIRE PATCH	22000	VALVE STEM CHROME LOW BOLT IN	1.01	1	\$1.01
					PARTS	3.61

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 29422

Work Order Notes

(LISAPATE) LEFT FRONT TIRE HAS A BOLT IN IT

Job Notes

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) REMOVED AND PATCH LF TIRE FROM THE INSIDE. RECHECKED OK

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 29700

USING DEPT NO: 504303	OPENED DATE: 05/07/2018 08:24:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/08/2018 08:07:44	METER 1 - M: 146633 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/08/2018 08:07:46	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11758845	05/07/2018 11:21:11	05/07/2018 11:51:11	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 29700

Work Order Notes

(LISAPATE) INSTALL GPS SYSTEM

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) INSTALLED GPS SYSTEM WITH HARNESS KIT
SERIAL# 5015915189

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 30134

USING DEPT NO: 504303	OPENED DATE: 06/28/2018 11:18:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/23/2018 10:05:04	METER 1 - M: 146749 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/23/2018 10:05:06	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-71-002	REPAIR FRONT WALL &/OR HEADBOAF	DON	O	N	GARAGE	0.30	\$0.00	\$0.00	\$0.00	\$0.00
PU-55-012	PURCHASED CARGO RESTRAINTS	DON	O	N	GARAGE	0.00	\$0.00	\$91.96	\$0.00	\$91.96

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.30** **0.00** **91.96** **0.00** **91.96**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-71-002	REPAIR FRONT WALL &/OR HEADBOARD ASSY	11758845	07/18/2018 07:00:00	07/18/2018 07:18:00	0.30	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-55-012	PURCHASED CARGO RESTRAINTS	HET8GV	8' HORIZONTAL E-TRACK	22.99	(4)	(\$91.96)
PU-55-012	PURCHASED CARGO RESTRAINTS	HET8GV	8' HORIZONTAL E-TRACK	22.99	4	\$91.96
PU-55-012	PURCHASED CARGO RESTRAINTS	HET8GV	8' HORIZONTAL E-TRACK	22.99	4	\$91.96
					PARTS	91.96

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 30134

Work Order Notes

(LISAPATE) PER JEREMY ORDER ETRACK FOR WALLS TO SECURE BINS. ALSO REPAIR PASS THRU DOOR WAS TORN OFF

Job Notes

24-71-002 - REPAIR FRONT WALL &/OR HEADBOARD ASSY

(LISAPATE) FOUND WALL HAD BEEN HIT AND PUSHED FORWARD. LEVELED THE WALK THROUGH WALL AND SECURED IT TO THE FLOOR

PU-55-012 - PURCHASED CARGO RESTRAINTS

(LISAPATE) PURCHASED E TRACK AND GAVE TO DEPT TO HAVE BLDG MAINT INSTALL

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 30465

USING DEPT NO:	504303	OPENED DATE:	08/03/2018 07:45:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/07/2018 14:31:32	METER 1 - M:	147862	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/07/2018 14:31:35	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$26.81	\$0.00	\$26.81

JOB COUNT: 1 **WORK ORDER TOTAL: 0.31 0.00 26.81 0.00 26.81**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/03/2018 07:46:17	08/03/2018 08:04:53	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	3.30	1	\$3.30
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.79	7	\$19.53
					PARTS	26.81

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 30465

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(IFALLS) CS PERFORMED PM

(LISAPATE) COOLANT -30'

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 30628

USING DEPT NO:	504303	OPENED DATE:	08/22/2018 11:06:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2018 10:44:56	METER 1 - M:	147940	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2018 10:44:57	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-55-012	PURCHASED CARGO RESTRAINTS	DON	O	N	GARAGE	0.00	\$0.00	\$27.00	\$0.00	\$27.00

JOB COUNT: 1	WORK ORDER TOTAL:					0.00	0.00	27.00	0.00	27.00
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-55-012	PURCHASED CARGO RESTRAINTS	SHIPPING	SHIPPING AND HANDLING	27.00	1	\$27.00
					PARTS	27.00

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 30628

Work Order Notes

(RTUNAITI) Apply shipping charges for parts purchased on work order # 30134

Job Notes

PU-55-012 - PURCHASED CARGO RESTRAINTS

(RTUNAITI) Applied \$27.00 shipping charge that was omitted from WO 30134

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 3077

USING DEPT NO: 504303	OPENED DATE: 03/12/2009 15:18:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/13/2009 07:26:29	METER 1 - M: 40716 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/13/2009 07:26:32	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$40.02	\$0.00	\$57.85

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **70.92** **0.00** **103.13**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11088474	03/12/2009 16:18:36	03/12/2009 16:33:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11088474	03/12/2009 16:00:00	03/12/2009 16:18:36	0.31	\$17.83
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	4.32	2	\$8.64
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
					PARTS	70.92

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 3077

Work Order Notes

(LPATE) PM-REPLACE WIPERS*****WINDSHIELD IS CRACKED WILL NEED A WINDSHIELD SOON*****

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL PLUG FORD
Manufacturer :

Part No : 51372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 224
Description : MOTOR OIL
Manufacturer :

Part No : FA1632
Qty : 1
Description : FILTER-AIR FORD
Manufacturer :

(LPATE) PM BY JE

Work Order Charge Detail

UNIT NO: 236965 **2006 FORD E350**

WORK ORDER NO: 31391

USING DEPT NO: 504303	OPENED DATE: 11/05/2018 08:35:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2018 07:16:28	METER 1 - M: 149237 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/06/2018 07:16:30	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.00	\$0.00	\$2.59	\$0.00	\$2.59

JOB COUNT: 1	WORK ORDER TOTAL:					0.00	0.00	2.59	0.00	2.59
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20P	5W20 FS QRT OIL	2.59	1	\$2.59
					PARTS	2.59

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 31391

Work Order Notes

(LISAPATE) Per Kelton truck is low on oil

Job Notes

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(LISAPATE) Added 1 qt of oil, checked for leaks none found

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 32252

USING DEPT NO:	504303	OPENED DATE:	02/22/2019 11:10:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2019 13:42:09	METER 1 - M:	150421	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2019 13:42:12	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-016	REPLACE NEW HEADLIGHT SWITCH	DON	O	N	GARAGE	1.23	\$0.00	\$24.83	\$0.00	\$24.83
24-71-003	REPAIR SIDE WALL ASSEMBLY	DON	O	N	GARAGE	1.00	\$0.00	\$25.00	\$0.00	\$25.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$33.02	\$0.00	\$33.02

JOB COUNT: 3	WORK ORDER TOTAL:	2.54	0.00	82.85	0.00	82.85
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-71-003	REPAIR SIDE WALL ASSEMBLY	11074414	02/27/2019 06:00:00	02/27/2019 07:00:00	1.00	\$0.00
03-34-016	REPLACE NEW HEADLIGHT SWITCH	11074414	02/26/2019 10:40:52	02/26/2019 11:54:57	1.23	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/22/2019 13:55:29	02/25/2019 07:09:03	(65.23)	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/22/2019 13:55:29	02/25/2019 07:09:03	65.23	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/22/2019 13:55:29	02/22/2019 14:14:05	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-016	REPLACE NEW HEADLIGHT SWITCH	HL6582	HEADLIGHT SWITCH	24.83	1	\$24.83
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
66-PM-PMA	PERFORM OIL CHANGE	ATM20	FUSE-20 AMP MINI	0.55	1	\$0.55
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	7	\$21.00
66-PM-PMA	PERFORM OIL CHANGE	ATM20	FUSE-20 AMP MINI	0.55	(1)	(\$0.55)
66-PM-PMA	PERFORM OIL CHANGE	ATM20	FUSE-20 AMP MINI	0.55	2	\$1.10
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	7	\$21.00
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	(7)	(\$21.00)
24-71-003	REPAIR SIDE WALL ASSEMBLY	12X12 WHT ALUM PANEL	12X12 WHITE ALUMINUM PANEL	25.00	1	\$25.00
					PARTS	82.85

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 32252

Work Order Notes

(LISAPATE) PM
(EKIMBREL) Top:SH/RC
bottom: ag
coolant temp:-35
SH cleaned battery cables

Job Notes

03-34-016 - REPLACE NEW HEADLIGHT SWITCH

(EKIMBREL) Replaced headlight switch, headlight switches all working properly.

24-71-003 - REPAIR SIDE WALL ASSEMBLY

(EKIMBREL) SH repaired hole on right side of box, used nonstock parts.
(IFALLS) sheet metal purchased from Andrews body shop

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(IFALLS) AG performed pm

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 34142

USING DEPT NO:	504303	OPENED DATE:	09/18/2019 13:22:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2019 08:40:11	METER 1 - M:	152293	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2019 08:40:13	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$0.00	\$28.99	\$0.00	\$28.99

JOB COUNT: 1	WORK ORDER TOTAL:					0.34	0.00	28.99	0.00	28.99
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/18/2019 15:34:21	09/18/2019 15:54:28	0.34	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	7	\$20.72
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
					PARTS	28.99

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 34142

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by RC.JW/SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 34513

USING DEPT NO:	504303	OPENED DATE:	10/18/2019 15:40:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/21/2019 13:45:33	METER 1 - M:	152647	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/21/2019 13:45:35	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	O	N	GARAGE	1.89	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 1.89 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	11213180	10/19/2019 14:24:53	10/19/2019 16:18:26	1.89	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 34513

Work Order Notes

(LISAPATE) Replace RR taillight assy and reposition bracket

Job Notes

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

(LISAPATE) Drilled holes thru bumper to hold tail light assy back away from lift gate. Installed new tail light assy (non-Inventory)

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 35313

USING DEPT NO: 504303	OPENED DATE: 01/06/2020 14:18:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/08/2020 06:53:03	METER 1 - M: 153336 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/08/2020 06:53:05	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	0.39	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.39	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-021	REPLACE NEW GPS SYSTEM	11901357	01/06/2020 14:23:39	01/06/2020 14:47:08	0.39	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 35313

Work Order Notes

(EKIMBREL) Install new 4G GPS

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(EKIMBREL) AG installed New GPS#5041372383
Old GPS#5015915189

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 35482

USING DEPT NO: 504303	OPENED DATE: 01/23/2020 09:18:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/30/2020 08:06:10	METER 1 - M: 153494 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 01/30/2020 08:06:11	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.52	\$0.00	\$0.18	\$0.00	\$0.18
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.59	\$0.00	\$135.74	\$0.00	\$135.74

JOB COUNT: 2 **WORK ORDER TOTAL: 1.11 0.00 135.92 0.00 135.92**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	01/23/2020 09:52:38	01/23/2020 10:28:06	0.59	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	01/23/2020 09:21:37	01/23/2020 09:52:38	0.52	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	93775	TIRE LT225/75R16 BFG COMM T/A	133.78	1	\$133.78
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	1157	BULB-BRAKE/TURN	0.18	1	\$0.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.30	3	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	1.06	1	\$1.06
					PARTS	135.92

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 35482

Work Order Notes

(LISAPATE) LR turn signal and brake light out-check tire pressure in LR tire

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Replaced LR turn/brake light bulb

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) LR outside tire had a nail in the sidewall removed and installed new tire. Rechecked ok

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 35714

USING DEPT NO:	504303	OPENED DATE:	02/20/2020 09:48:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2020 06:49:58	METER 1 - M:	153856	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/27/2020 06:49:59	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-044	REPAIR CAB - COMPLETE	DON	O	N	GARAGE	1.31	\$0.00	\$25.17	\$0.00	\$25.17

JOB COUNT: 1	WORK ORDER TOTAL:	1.31	0.00	25.17	0.00	25.17
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-044	REPAIR CAB - COMPLETE	11074414	02/20/2020 13:15:20	02/20/2020 13:55:47	0.67	\$0.00
24-02-044	REPAIR CAB - COMPLETE	11074414	02/20/2020 10:06:34	02/20/2020 10:44:55	0.64	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-044	REPAIR CAB - COMPLETE	LSB27034145	RV CAULK SELF-LEVELING WHITE	8.39	1	\$8.39
24-02-044	REPAIR CAB - COMPLETE	08984	ADHESIVE REMOVER	16.78	1	\$16.78
					PARTS	25.17

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 35714

Work Order Notes

(EKIMBREL) Cab is leaking where it connects to box bed above driver.

Job Notes

24-02-044 - REPAIR CAB - COMPLETE

(LISAPATE) Resealed cab seams. Sealant was not dry. Dept had to have vehicle back before it could cure. Cab may start leaking water again.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 36072

USING DEPT NO: 504303	OPENED DATE: 03/27/2020 08:20:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/30/2020 13:18:17	METER 1 - M: 154037 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/30/2020 15:14:53	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$98.65	\$0.00	\$98.65
06-34-004	INSPECT CLEARANCE/MARKER	DON	O	N	GARAGE	0.06	\$0.00	\$0.33	\$0.00	\$0.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.80	\$0.00	\$25.97	\$0.00	\$25.97
CL-55-002	CLEANED VERTICAL SLIDES-PWR TAIL	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	3.86	0.00	124.95	0.00	124.95
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-55-002	CLEANED VERTICAL SLIDES-PWR TAIL GATE	12052187	03/30/2020 07:00:00	03/30/2020 07:30:00	0.50	\$0.00
03-32-002	REPLACE NEW BATTERY	11901357	03/30/2020 07:00:00	03/30/2020 07:30:00	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/27/2020 09:30:00	03/27/2020 10:33:54	1.07	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/27/2020 08:37:22	03/27/2020 09:15:00	0.63	\$0.00
06-34-004	INSPECT CLEARANCE/MARKER	12052187	03/27/2020 09:55:35	03/27/2020 09:59:03	0.06	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/27/2020 09:30:00	03/27/2020 09:55:35	0.43	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/27/2020 08:34:09	03/27/2020 09:15:00	0.68	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
06-34-004	INSPECT CLEARANCE/MARKER	ATM20	FUSE-20 AMP MINI	0.33	1	\$0.33
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	124.95

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 36072

Work Order Notes

(IFALLS) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(IFALLS) AG replace battery

06-34-004 - INSPECT CLEARANCE/MARKER

(IFALLS) JW replaced fuse for marker lights and repaired wire for top marker light

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULLSYN OIL BULK

Manufacturer :

Bin :

Part No : FL820S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

Bin : D4D

(IFALLS) JW/AG performed pm

CL-55-002 - CLEANED VERTICAL SLIDES-PWR TAIL GATE

(IFALLS) JW cleaned tracks for lift gate

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 36417

USING DEPT NO:	504303	OPENED DATE:	05/13/2020 14:01:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/14/2020 11:38:34	METER 1 - M:	154393	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	05/14/2020 11:38:39	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	1.38	\$0.00	\$5.42	\$0.00	\$5.42

JOB COUNT: 1	WORK ORDER TOTAL:					1.38	0.00	5.42	0.00	5.42
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	05/14/2020 07:56:21	05/14/2020 09:19:26	1.38	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	2	\$0.54
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	3.82	1	\$3.82
66-17-030	PERFORM TIRE PATCH	22000	VALVE STEM CHROME LOW BOLT IN	1.06	1	\$1.06
					PARTS	5.42

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 36417

Work Order Notes

(EKIMBREL) Bolt in front left tire.

Job Notes

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) AG repaired and balanced LF tire, rechecked good

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 37513

USING DEPT NO: 504303	OPENED DATE: 09/04/2020 07:46:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/04/2020 11:07:17	METER 1 - M: 155272 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/04/2020 12:43:59	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.29	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/04/2020 08:53:51	09/04/2020 09:11:11	0.29	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 37513

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1089 miles since last pm. Checked fluids and tires. Found no issues. Updated sticker. Coolant -34 JAW,SH

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 38047

USING DEPT NO: 504303	OPENED DATE: 10/19/2020 08:30:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/19/2020 09:54:29	METER 1 - M: 155720 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/19/2020 12:32:33	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.02	\$1.97	\$8.85	\$0.00	\$10.82

JOB COUNT: 1	WORK ORDER TOTAL:	0.02	1.97	8.85	0.00	10.82
---------------------	--------------------------	-------------	-------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	12052187	10/19/2020 08:44:03	10/19/2020 08:45:03	0.02	\$1.97
					LABOR	1.97

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	2	\$8.85
					PARTS	8.85

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 38047

Work Order Notes

(LISAPATE) Per driver truck is low on oil

Job Notes

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(JWRIGHT) Topped off oil. No other issues found

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 39547

USING DEPT NO: 504303	OPENED DATE: 04/01/2021 15:37:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/17/2021 11:45:49	METER 1 - M: 156431 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/17/2021 11:46:03	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-16-022	REPLACE NEW SWAY BAR BUSHINGS	DON	O	N	GARAGE	1.50	\$176.77	\$18.51	\$0.00	\$195.28
03-17-028	REPLACE NEW MOUNT AND BALANCE	DON	O	N	GARAGE	0.41	\$48.54	\$408.75	\$0.00	\$457.29
03-30-005	REPLACE NEW LIFTGATE SWITCH	DON	O	N	GARAGE	1.87	\$220.79	\$23.03	\$0.00	\$243.82
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.07	\$7.77	\$0.00	\$0.00	\$7.77
03-55-039	REPLACE NEW LIFTGATE ASSY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$4,323.94	\$4,323.94
16-55	TRANSPORT CARGO HNDLNG,RESTRN	DON	O	N	GARAGE	4.00	\$472.00	\$0.00	\$0.00	\$472.00
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.26	\$148.39	\$0.00	\$0.00	\$148.39
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.44	\$170.22	\$96.97	\$0.00	\$267.19

JOB COUNT: 8	WORK ORDER TOTAL:	10.55	1,244.48	547.26	4,323.94	6,115.68
---------------------	--------------------------	--------------	-----------------	---------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-30-005	REPLACE NEW LIFTGATE SWITCH	11153069	52531		\$0.00
03-30-005	REPLACE NEW LIFTGATE SWITCH	11153069	52531		\$0.00
03-55-039	REPLACE NEW LIFTGATE ASSY	11153069	52531		\$4,323.94
COMML					4323.94

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-55	TRANSPORT CARGO HNDLNG,RESTRN&LIFT SYS	11915538	06/15/2021 07:00:00	06/15/2021 11:00:00	4.00	\$472.00
03-30-005	REPLACE NEW LIFTGATE SWITCH	11310047	05/26/2021 12:58:29	05/26/2021 14:23:49	1.42	\$167.82
03-30-005	REPLACE NEW LIFTGATE SWITCH	11310047	05/26/2021 09:18:28	05/26/2021 09:45:24	0.45	\$52.97
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/02/2021 08:21:41	04/02/2021 08:25:38	0.07	\$7.77
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/02/2021 07:36:02	04/02/2021 08:13:28	0.62	\$73.62
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/02/2021 07:31:53	04/02/2021 07:38:32	0.11	\$13.08
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/02/2021 07:38:52	04/02/2021 08:21:20	0.71	\$83.52
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	12052187	04/02/2021 12:40:34	04/02/2021 12:45:53	0.09	\$10.46

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	11901357	04/02/2021 12:37:20	04/02/2021 12:56:42	0.32	\$38.09
03-16-022	REPLACE NEW SWAY BAR BUSHINGS	11901357	04/02/2021 13:31:13	04/02/2021 15:01:06	1.50	\$176.77
66-17-013	PERFORM ALIGNMENT	11310047	04/05/2021 07:34:34	04/05/2021 08:50:01	1.26	\$148.39
					LABOR	1244.49

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	9.66	1	\$9.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	25.55	1	\$25.55
66-PM-PMA	PERFORM OIL CHANGE	19200	WIPER BLADE OE BEAM STYLE 20IN	8.84	2	\$17.67
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	(1)	(\$6.56)
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	2	\$13.11
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	93775	TIRE LT225/75R16 BFG COMM T/A	201.35	2	\$402.69
03-16-022	REPLACE NEW SWAY BAR BUSHINGS	TRWJBU1089	SWAY BAR BUSHING	18.51	1	\$18.51
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	6	\$2.88
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	(6)	(\$26.55)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	1.59	2	\$3.18
03-30-005	REPLACE NEW LIFTGATE SWITCH	06133	ELECTRICAL TAPE 3M SUPER 33+	7.68	1	\$7.68
03-30-005	REPLACE NEW LIFTGATE SWITCH	PIC5525PT	RED INDICATOR LIGHT	2.81	1	\$2.81
03-30-005	REPLACE NEW LIFTGATE SWITCH	PIC5522PT	PUSH/PULL SWITCH 75AMP	12.54	1	\$12.54
					PARTS	547.26

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 39547

Work Order Notes

(LISAPATE) PM

Job Notes

03-16-022 - REPLACE NEW SWAY BAR BUSHINGS

(AGUERRA) Replaced sway bar to lower control arm bushings. AMG

03-17-028 - REPLACE NEW MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced front tires. Aired to spec and balanced. Torqued all lugs to 140ft lbs. JAW,AMG

(AGUERRA) Replaced and balanced both front tires, Josh assisted. AMG JW

03-30-005 - REPLACE NEW LIFTGATE SWITCH

(EHOWELL) The liftgate stopped operating after it was installed. The circuit breaker at the vehicle battery was thrown. The cables were also loose at the circuit breaker. Reset breaker and tightened cables. The liftgate switch lamp beneath the steering wheel was not illuminating when the switch was in the ON position. Replaced liftgate switch and the lamp for the switch. Secured wires with zip ties to prevent interference with the driver's feet. The liftgate is now operating. EH/IF

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

03-55-039 - REPLACE NEW LIFTGATE ASSY

(LISAPATE) Lyncoach installed new liftgate assy per the quote. Pd by CC

16-55 - TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS

(LISAPATE) Taken to Lyncoach by RC and drivers.

66-17-013 - PERFORM ALIGNMENT

(EKIMBREL) EH performed alignment

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 156598 Completed PM topside, Josh was bottom side. Completed checklist and vacuumed out vehicle. AMG/JW

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 3979

USING DEPT NO: 504303	OPENED DATE: 07/28/2009 13:04:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/03/2009 08:40:57	METER 1 - M: 42320 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/04/2009 08:15:18	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.50	\$28.75	\$80.82	\$0.00	\$109.57
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$199.19	\$199.19
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,088.79	\$1,088.79
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	3.21	\$184.83	\$0.00	\$0.00	\$184.83
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.71	\$0.00	\$0.00	\$57.71
66-79-003	PERFORM SAFETY INSPECTION	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$62.88	\$0.00	\$80.71

JOB COUNT: 8	WORK ORDER TOTAL:	6.28	361.00	174.60	1,287.98	1,823.58
---------------------	--------------------------	-------------	---------------	---------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11245625	044250	0005313	\$199.19
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	D205695	0005314	\$1,088.79
COMML					1287.98

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11268671	08/03/2009 06:00:00	08/03/2009 07:00:00	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	11088474	07/28/2009 14:41:15	07/28/2009 14:56:15	0.25	\$14.38
03-51-038	REPLACE NEW WIPER BLADES	11088474	07/28/2009 14:41:15	07/28/2009 14:41:25	0.00	(\$0.16)
03-51-038	REPLACE NEW WIPER BLADES	11088474	07/28/2009 14:41:15	07/28/2009 14:41:25	0.00	\$0.16
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/28/2009 14:41:30	07/28/2009 14:41:41	0.00	\$0.18
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/28/2009 14:41:30	07/28/2009 14:41:41	0.00	(\$0.18)
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/28/2009 14:41:30	07/28/2009 15:00:06	0.31	\$17.83
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11088474	07/28/2009 14:41:57	07/28/2009 14:42:10	0.00	\$0.21
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11088474	07/29/2009 07:47:15	07/29/2009 07:47:32	0.00	\$0.27

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11088474	07/29/2009 07:47:15	07/29/2009 07:47:32	0.00	(\$0.27)
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11088474	07/29/2009 07:47:15	07/29/2009 08:47:15	1.00	\$57.50
16-02	TRANSPORT CAB & SHEET METAL	11088474	07/29/2009 09:30:00	07/29/2009 11:15:30	1.76	\$101.10
16-02	TRANSPORT CAB & SHEET METAL	11088474	07/29/2009 07:47:38	07/29/2009 09:15:00	1.46	\$83.73
03-02-010	REPLACE NEW MIRRORS	11088474	07/31/2009 09:52:10	07/31/2009 10:22:10	0.50	\$28.75
03-02-010	REPLACE NEW MIRRORS	11088474	07/31/2009 09:52:10	07/31/2009 09:52:23	0.00	\$0.21
03-02-010	REPLACE NEW MIRRORS	11088474	07/31/2009 09:52:10	07/31/2009 09:52:23	0.00	(\$0.21)
					LABOR	361.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	31.50	1	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.86	1	\$7.86
03-02-010	REPLACE NEW MIRRORS	GRO12010	10' CONVEX MIRROR ROUND	80.82	1	\$80.82
					PARTS	174.60

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 3979

Work Order Notes

(LPATE) PM-GREASE LIFTGATE-REPLACE WIPERS-NEEDS WINDSHIELD CRACK GOING ACROSS WINDHIELD-NEEDS ALL 6 TIRES REPLACED AND ALIGNMENT-REAR CONVEX MIRROR IS BROKEN

Job Notes

Work Order Charge Detail

03-02-010 - REPLACE NEW MIRRORS

(LPATE) REPLACED 10" ROUND CONVEX MIRROR ON BACK OF TRUCK

03-02-061 - REPLACE NEW WINDSHIELD

(LPATE) ROZAR'S REPLACED WINDSHIELD P0022780

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) GOODYEAR REPLACED ALL 6 TIRES AND ALIGNED P0022756

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPER BLADES

16-02 - TRANSPORT CAB & SHEET METAL

(LPATE) JE TOOK TO ROZAR'S

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) JE TOOK TO GOODYEAR

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) INSPECTED BRAKES AND LOWER CHASSIS NO MAINT NEEDED AT THIS TIME

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

(LPATE) The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 51372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 224
Description : OIL-MOTOR
Manufacturer :

Part No : FA1632
Qty : 1
Description : FILTER-AIR FORD
Manufacturer :

(LPATE) PM BY JE-REPLACED AIR FILTER-GREASED LIFT GATE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 40517

USING DEPT NO: 504303	OPENED DATE: 07/22/2021 09:42:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/23/2021 10:06:13	METER 1 - M: 157365 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/23/2021 10:41:41	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$47.20	\$0.00	\$0.00	\$47.20

JOB COUNT: 1	WORK ORDER TOTAL:	0.40	47.20	0.00	0.00	47.20
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12052187	07/22/2021 10:02:59	07/22/2021 10:09:04	0.10	\$11.96
66-17-030	PERFORM TIRE PATCH	12052187	07/22/2021 10:02:59	07/22/2021 10:09:04	(0.10)	(\$11.96)
66-17-030	PERFORM TIRE PATCH	12052187	07/22/2021 10:02:59	07/22/2021 10:26:59	0.40	\$47.20
					LABOR	47.20

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 40517

Work Order Notes

(LISAPATE) Nail in LR inside tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) LRI tire was flat. Aired and found valve core leaking. Replaced core with new non inventory part. Aired to spec and torqued lugs to spec. JAW

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 40900

USING DEPT NO: 504303	OPENED DATE: 09/01/2021 07:12:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/03/2021 08:11:10	METER 1 - M: 158105 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/07/2021 08:22:10	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.03	\$15.18	\$0.00	\$19.21
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.59	\$69.39	\$170.15	\$0.00	\$239.54
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.80	\$94.86	\$0.00	\$0.00	\$94.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$52.15	\$35.69	\$0.00	\$87.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.87	220.43	221.02	2.00	443.45
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12052187	09/01/2021 10:08:44	09/01/2021 10:11:40	0.05	\$5.77
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	09/01/2021 09:33:20	09/01/2021 10:08:37	0.59	\$69.39
66-79-003	PERFORM SAFETY INSPECTION	12052187	09/01/2021 08:47:55	09/01/2021 09:33:13	0.76	\$89.09
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/01/2021 08:45:44	09/01/2021 08:47:47	0.03	\$4.03
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/01/2021 08:19:03	09/01/2021 08:45:34	0.44	\$52.15
				LABOR		220.43

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.71	1	\$4.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	167.57	1	\$167.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	2	\$0.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	1.59	1	\$1.59
					PARTS	221.02

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 40900

Work Order Notes

(LISAPATE) Right rear outside tire has a hole in the sidewall

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced rro tire. Aired and balanced. Torqued all lug nuts to spec. JAW

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Rear brakes are below spec and needs replaced. Per IF and EH, department will bring back in a few weeks for brake job. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-158105

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 42246

USING DEPT NO: 504303	OPENED DATE: 02/01/2022 13:46:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/02/2022 09:33:32	METER 1 - M: 159556 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/02/2022 12:46:08	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.75	\$15.18	\$0.00	\$19.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$14.91	\$0.00	\$0.00	\$14.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.17	19.66	15.18	2.00	36.84
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/02/2022 07:21:41	02/02/2022 07:24:06	0.04	\$4.75
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/02/2022 07:13:54	02/02/2022 07:21:29	0.13	\$14.91
LABOR					19.66	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
PARTS					15.18	

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 42246

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1451 miles. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-159556

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 43291

USING DEPT NO: 504303	OPENED DATE: 05/18/2022 08:27:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/19/2022 15:19:44	METER 1 - M: 160381 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/20/2022 14:00:47	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.15	\$17.70	\$5.82	\$0.00	\$23.52
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.15 17.70 5.82 2.00 25.52

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	12052187	05/19/2022 07:00:00	05/19/2022 07:09:00	0.15	\$17.70
					LABOR	17.70

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20QT	5W20 FULL SYN QTS	5.82	1	\$5.82
					PARTS	5.82

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 43291

Work Order Notes

(EKIMBREL) ADD QT OIL

Job Notes

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(LISAPATE) added 1 qt of oil, checked all fluids

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 4372

USING DEPT NO: 504303	OPENED DATE: 09/24/2009 08:11:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/24/2009 09:32:43	METER 1 - M: 43961 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/24/2009 09:32:45	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	N	N	GARAGE	0.30	\$17.25	\$38.81	\$0.00	\$56.06

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	38.81	0.00	56.06
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	11088858	09/24/2009 16:00:00	09/24/2009 16:18:00	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	GRO53762	TAILLIGHT ASSY	38.81	1	\$38.81
					PARTS	38.81

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 4372

Work Order Notes

(LPATE) LEFT REAR TAILLIGHT OUT

Job Notes

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

(LPATE) REPLACED LEFT REAR TAILLIGHT ASSY

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 43947

USING DEPT NO: 504303	OPENED DATE: 07/12/2022 15:15:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/25/2022 13:40:28	METER 1 - M: 160940 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/26/2022 10:31:44	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-01-066	REPLACE NEW VACUUM TANK UNIT	DON	O	N	GARAGE	0.67	\$78.73	\$28.26	\$0.00	\$106.99
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	1.54	\$181.29	\$87.61	\$0.00	\$268.90
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.27	\$32.22	\$0.00	\$0.00	\$32.22
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.49	\$57.33	\$0.00	\$0.00	\$57.33
24-52-024	REPAIR BACK UP CAMERA	DON	O	N	GARAGE	4.28	\$505.27	\$98.46	\$20.10	\$623.83
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.33	\$39.40	\$0.00	\$0.00	\$39.40
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	3.44	\$405.36	\$543.07	\$0.00	\$948.43
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.81	\$49.26	\$0.00	\$68.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 9 **WORK ORDER TOTAL:** 11.17 1,318.41 806.66 25.10 2,150.17

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-52-024	REPAIR BACK UP CAMERA	5761126	CS0001945		\$20.10
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					25.10

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11310047	07/22/2022 11:12:41	07/22/2022 14:11:43	2.98	\$352.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11310047	07/25/2022 14:03:01	07/25/2022 14:15:00	0.20	\$23.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11310047	07/25/2022 14:30:00	07/25/2022 14:45:06	0.25	\$29.70
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	07/25/2022 14:45:06	07/25/2022 15:52:47	1.13	\$133.11
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	07/26/2022 07:01:20	07/26/2022 07:25:50	0.41	\$48.18
24-52-024	REPAIR BACK UP CAMERA	11310047	07/13/2022 10:00:37	07/13/2022 10:42:10	0.69	\$81.72
24-52-024	REPAIR BACK UP CAMERA	11310047	07/27/2022 09:30:00	07/27/2022 10:46:30	1.28	\$150.45
24-52-024	REPAIR BACK UP CAMERA	11310047	07/27/2022 11:03:15	07/27/2022 11:52:40	0.82	\$97.19

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-52-024	REPAIR BACK UP CAMERA	11310047	07/27/2022 13:30:12	07/27/2022 14:15:00	0.75	\$88.11
66-13-130	PERFORM Burnish Brakes	11310047	07/27/2022 14:15:24	07/27/2022 14:15:24	0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	11310047	07/27/2022 14:30:00	07/27/2022 14:50:02	0.33	\$39.40
03-01-066	REPLACE NEW VACUUM TANK UNIT	11310047	07/27/2022 15:29:12	07/27/2022 15:51:07	0.37	\$43.10
03-01-066	REPLACE NEW VACUUM TANK UNIT	11310047	07/28/2022 07:18:24	07/28/2022 07:36:31	0.30	\$35.63
06-15	INSPECT STEERING	11310047	07/28/2022 07:47:08	07/28/2022 08:03:31	0.27	\$32.22
09-15	ALIGN STEERING	11310047	07/28/2022 08:03:31	07/28/2022 08:32:40	0.49	\$57.33
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/13/2022 09:05:26	07/13/2022 09:15:00	0.16	\$18.81
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/13/2022 09:15:37	07/13/2022 09:15:37	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/13/2022 09:15:37	07/13/2022 09:15:37	0.00	\$0.00
24-52-024	REPAIR BACK UP CAMERA	11310047	07/26/2022 14:34:55	07/26/2022 15:05:59	0.52	\$61.10
24-52-024	REPAIR BACK UP CAMERA	11310047	07/27/2022 09:01:25	07/27/2022 09:15:00	0.23	\$26.71
					LABOR	1318.43

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-01-066	REPLACE NEW VACUUM TANK UNIT	DOR47076	VACUUM TANK RESERVOIR	26.36	1	\$26.36
03-01-066	REPLACE NEW VACUUM TANK UNIT	GAT27041	7/64 VACUUM HOSE	0.41	1	\$0.41
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	7	\$42.63
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	6.63	1	\$6.63
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ36802	REAR BRAKE PADS	81.68	1	\$81.68
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	4.79	2	\$9.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	264.99	2	\$529.98
24-52-024	REPAIR BACK UP CAMERA	DORBOLT	BOLT	1.20	9	\$10.80
03-01-066	REPLACE NEW VACUUM TANK UNIT	GAT27043	7/32 VACUUM / WSW HOSE FT	0.50	3	\$1.49
24-52-024	REPAIR BACK UP CAMERA	8050061	10M AHD CABLE	45.00	1	\$45.00
09-15	ALIGN STEERING	TOP533	1" HOOK BRACKET	4.74	(9)	(\$42.66)
24-52-024	REPAIR BACK UP CAMERA	TOP533	1" HOOK BRACKET	4.74	9	\$42.66
09-15	ALIGN STEERING	TOP533	1" HOOK BRACKET	4.74	9	\$42.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	3	\$1.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26

Work Order Charge Detail

PARTS

806.66

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 43947

Work Order Notes

(LISAPATE) PM-replace wipers-back up camera is not working

Job Notes

03-01-066 - REPLACE NEW VACUUM TANK UNIT

(EHOWELL) The air was blowing out of the defrost vent when the vehicle was placed under a load. Installed a new vacuum tank unit. The air is now being distributed properly. EH

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EHOWELL) Relaced rear brake pads. Greased caliper slide pins. EH

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

06-15 - INSPECT STEERING

(EHOWELL) Front end good. JAW/AMG

09-15 - ALIGN STEERING

(EHOWELL) Checked alignment and it was within spec. EH

24-52-024 - REPAIR BACK UP CAMERA

(EHOWELL) The cable going to the backup camera was damaged. Ran a new cable from inside of the cab, through the box sitting on the frame, to the rear camera. Ran cable through plastic pipe to protect it from falling into the rollers of the roll up door. Secured the plastic pipe to the wall inside of the box using metal straps and screws. The backup camera is now coming on when the vehicle is placed in reverse. EH/MS 1.5 HR

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made hard stops after new brake pads were installed. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EHOWELL) Mounted and balanced two new tires. Installed new tires on the front of the vehicle and rotated the used tires to the rear. EH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW
MILEAGE-160940

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 44929

USING DEPT NO: 504303	OPENED DATE: 10/10/2022 09:02:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/14/2022 10:33:40	METER 1 - M: 161165 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2022 08:14:16	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.62	\$15.63	\$0.00	\$20.25
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.17	\$19.80	\$0.00	\$0.00	\$19.80
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.32	\$24.06	\$0.00	\$38.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.33	38.74	39.69	5.00	83.43
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-32	DIAGNOSE CRANKING SYSTEM	11074414	10/10/2022 10:47:52	10/10/2022 10:57:56	0.17	\$19.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/10/2022 10:58:10	10/10/2022 11:00:31	0.04	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2022 10:40:22	10/10/2022 10:47:39	0.12	\$14.32
					LABOR	38.74

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	24.06	1	\$24.06
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
					PARTS	39.69

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 44929

Work Order Notes

(LISAPATE) Check battery jumped off a few times

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

35-32 - DIAGNOSE CRANKING SYSTEM

(SHARBIN) Battery tested good ALT was charging at 14.4 volts. Vehicle is cranking good starter is not dragging. The switch for the lift gate was on when the vehicle was pulled into the shop. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 255 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 45085

USING DEPT NO: 504303	OPENED DATE: 10/26/2022 12:03:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/28/2022 15:35:00	METER 1 - M: 161185 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 10/31/2022 08:10:52	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.03	\$3.08	\$113.55	\$0.00	\$116.63
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.70	\$82.83	\$0.00	\$0.00	\$82.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.73	85.91	113.55	5.00	204.46
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	10/26/2022 13:17:15	10/26/2022 13:18:49	0.03	\$3.08
66-79-002	PERFORM SERVICE CALL	12052187	10/26/2022 12:34:57	10/26/2022 13:17:04	0.70	\$82.83
LABOR					85.91	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
PARTS					113.55	

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 45085

Work Order Notes

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery. Alternator charging at 14.8 volts. JAW
MILEAGE-161185

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) Went on service call and replaced battery. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 46406

USING DEPT NO: 504303	OPENED DATE: 03/08/2023 09:04:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/09/2023 14:00:03	METER 1 - M: 161331 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/09/2023 14:31:53	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.75	\$15.63	\$0.00	\$18.38
06-02-016	INSPECT TAIL&LIFT GATE	DON	N	N	GARAGE	0.10	\$12.36	\$0.00	\$0.00	\$12.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.60	\$49.73	\$0.00	\$85.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.30	\$35.60	\$0.00	\$0.00	\$35.60

JOB COUNT: 5	WORK ORDER TOTAL:	0.73	86.31	65.36	5.00	156.67
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	03/08/2023 13:56:54	03/08/2023 14:15:00	0.30	\$35.60
06-02-016	INSPECT TAIL&LIFT GATE	12201267	03/08/2023 13:38:37	03/08/2023 13:44:54	0.10	\$12.36
03-51-038	REPLACE NEW WIPER BLADES	12201267	03/08/2023 13:32:26	03/08/2023 13:33:50	0.02	\$2.75
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/08/2023 13:14:01	03/08/2023 13:32:07	0.30	\$35.60
					LABOR	86.31

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	7	\$43.79
					PARTS	65.36

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 46406

Work Order Notes

(EHANNAH) pm- replace wipers- wash vehicle- lift gate spring is broken

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

06-02-016 - INSPECT TAIL&LIFT GATE

(GRCOOK) Installed new spring, other spring was broke on one end. -GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, air filter good, tires and tire pressure
Miles, 161,331

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Performed wash vehicle-GC

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 4760

USING DEPT NO: 504303	OPENED DATE: 11/16/2009 07:46:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/16/2009 08:15:33	METER 1 - M: 45192 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/16/2009 08:15:34	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$31.29	\$0.00	\$45.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$71.55	\$0.00	\$89.38

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **102.84** **0.00** **135.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10041963	11/16/2009 17:00:00	11/16/2009 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	10041963	11/16/2009 17:18:36	11/16/2009 17:33:36	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.65	2	\$31.29
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	8.99	1	\$8.99
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	23.83	1	\$23.83
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	MERCON SP	TRANSMISSION FLUID	7.35	1	\$7.35
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.86	1	\$7.86
					PARTS	102.84

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 4760

Work Order Notes

(LPATE) PM-REPLACE WIPERS-LUBE LIFT GATE

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 51372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 224
Description : OIL BOTTLE
Manufacturer :

Part No : FA1632
Qty : 1
Description : FILTER-AIR
Manufacturer :

(LPATE) PM BY FC-REPLACED OIL DRAIN PLUG-LUBED LIFT GATE-REPLACED AIR FILTER-ADDED TRANS FLUID

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 48378

USING DEPT NO: 504303	OPENED DATE: 10/02/2023 10:06:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/16/2023 15:31:31	METER 1 - M: 161657 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/18/2023 08:55:32	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-16-003	REPLACE NEW FRONT SHOCK ABSORBER	DON	N	N	GARAGE	0.34	\$40.12	\$296.67	\$0.00	\$336.79
03-79-009	REPLACE NEW SEAT BELT(S)	DON	N	N	GARAGE	0.85	\$99.71	\$387.03	\$0.00	\$486.74
24-34-004	REPAIR CLEARANCE/MARKER	DON	N	N	GARAGE	0.27	\$31.37	\$17.39	\$0.00	\$48.76
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	3.94	\$464.43	\$0.00	\$0.00	\$464.43
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$67.65	\$0.00	\$0.00	\$67.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.34	\$39.60	\$0.00	\$0.00	\$39.60

JOB COUNT: 7	WORK ORDER TOTAL:	6.30	742.88	701.09	5.00	1,448.97
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11310047	10/03/2023 09:30:00	10/03/2023 10:34:02	1.07	\$125.93
66-79-003	PERFORM SAFETY INSPECTION	11310047	10/03/2023 07:02:20	10/03/2023 09:15:00	2.21	\$260.91
66-79-003	PERFORM SAFETY INSPECTION	11310047	10/02/2023 15:14:53	10/02/2023 15:54:20	0.66	\$77.59
03-79-009	REPLACE NEW SEAT BELT(S)	11310047	10/12/2023 07:02:29	10/12/2023 07:38:12	0.60	\$70.24
03-79-009	REPLACE NEW SEAT BELT(S)	11310047	10/11/2023 15:37:42	10/11/2023 15:52:41	0.25	\$29.47
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/05/2023 08:26:15	10/05/2023 08:38:22	0.20	\$23.83
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/05/2023 07:23:23	10/05/2023 07:45:40	0.37	\$43.82
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	12052187	10/05/2023 07:02:36	10/05/2023 07:23:00	0.34	\$40.12
24-34-004	REPAIR CLEARANCE/MARKER	11310047	10/04/2023 13:01:34	10/04/2023 13:17:31	0.27	\$31.37
WA-00	WASH COMPLETE VEHICLE	12052187	10/05/2023 08:38:38	10/05/2023 08:45:36	0.12	\$13.70
WA-00	WASH COMPLETE VEHICLE	12052187	10/05/2023 08:45:49	10/05/2023 08:45:53	0.00	\$0.13

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12052187	10/05/2023 08:46:16	10/05/2023 08:46:25	0.00	\$0.30
WA-00	WASH COMPLETE VEHICLE	12395904	10/05/2023 08:35:57	10/05/2023 08:47:24	0.19	\$22.52
WA-00	WASH COMPLETE VEHICLE	12052187	10/05/2023 08:46:34	10/05/2023 08:47:50	0.02	\$2.49
WA-00	WASH COMPLETE VEHICLE	12052187	10/05/2023 08:48:00	10/05/2023 08:48:14	0.00	\$0.46
					LABOR	742.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-79-009	REPLACE NEW SEAT BELT(S)	6C2Z1561203AA	SEAT BELT BUCKLE	387.03	1	\$387.03
03-79-009	REPLACE NEW SEAT BELT(S)	6C2Z1561203AA	SEAT BELT BUCKLE	387.03	(1)	(\$387.03)
03-79-009	REPLACE NEW SEAT BELT(S)	6C2Z1561203AA	SEAT BELT BUCKLE	387.03	1	\$387.03
24-34-004	REPAIR CLEARANCE/MARKER	GRO62231	BACK UP/MARKER LIGHT	17.39	1	\$17.39
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	KYB565014	FRONT SHOCK	148.34	2	\$296.67
					PARTS	701.09

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 48378

Work Order Notes

(EHANNAH) pm-do SI wash

Job Notes

03-02-057 - REPLACE NEW DOOR HANDLE EXTERIOR

03-16-003 - REPLACE NEW FRONT SHOCK ABSORBERS

(EHOWELL) Replaced left front shock absorber. EH
(JWRIGHT) Replaced rf shock. EH replaced the left front shock. JAW

03-79-009 - REPLACE NEW SEAT BELT(S)

(EHOWELL) Replaced driver's seat belt buckle/pretensioner. Verified operation of buckle and seat belt light after repair. EH

24-34-004 - REPAIR CLEARANCE/MARKER

(EHOWELL) There was a broken wire at the top left front marker light on the box. Repaired wire and verified operation of light after repair. EH .3 HR

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Performed safety inspection. The boards for the floor in the box are rotten and need to be replaced. EH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 359 miles since last pm. Updated sticker. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-161690

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Wash Bay closed

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 49061

USING DEPT NO: 504303	OPENED DATE: 11/27/2023 14:50:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/29/2023 07:26:07	METER 1 - M: 161657 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/29/2023 08:41:44	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.40	\$47.20	\$12.51	\$0.00	\$59.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.40 47.20 12.51 5.00 64.71

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12395904	11/29/2023 07:00:00	11/29/2023 07:24:00	0.40	\$47.20
					LABOR	47.20

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.46	1	\$5.46
66-17-030	PERFORM TIRE PATCH	22000	VALVE STEM CHROME LOW BOLT IN	5.40	1	\$5.40
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-030	PERFORM TIRE PATCH	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
					PARTS	12.51

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 49061

Work Order Notes

(EHANNAH) RP tire on the outside is leaking air.

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) FC PATCHED RR TIRE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 49917

USING DEPT NO: 504303	OPENED DATE: 02/23/2024 09:02:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/29/2024 15:38:42	METER 1 - M: 161770 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/01/2024 15:49:45	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.01	\$1.74	\$199.98	\$0.00	\$201.72
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.10	\$16.65	\$0.00	\$18.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.04	\$122.92	\$45.53	\$0.00	\$168.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.41	\$48.87	\$0.00	\$0.00	\$48.87

JOB COUNT: 5	WORK ORDER TOTAL:	1.49	175.63	262.16	5.00	442.79
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	02/26/2024 13:19:42	02/26/2024 13:44:33	0.41	\$48.87
03-51-038	REPLACE NEW WIPER BLADES	12395904	02/26/2024 11:33:04	02/26/2024 11:34:08	0.02	\$2.10
03-32-002	REPLACE NEW BATTERY	12395904	02/26/2024 11:31:44	02/26/2024 11:32:37	0.01	\$1.74
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/26/2024 10:28:47	02/26/2024 11:31:17	1.04	\$122.92
					LABOR	175.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	2	\$16.65
03-32-002	REPLACE NEW BATTERY	651	BATTERY BCI 65 750CCA	199.98	1	\$199.98
					PARTS	262.16

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 49917

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(FCONTRER) replaced new battery fc

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers fc

06-32-002 - INSPECT BATTERY

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

UNIT NO: 236965 **2006 FORD E350**

WORK ORDER NO: 51877

USING DEPT NO: 504303	OPENED DATE: 08/20/2024 08:57:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/22/2024 12:14:55	METER 1 - M: 161959 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/23/2024 11:40:06	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 51877

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Unit has been 189 miles. Checked fluids and tires. JAW
Miles-161959

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed unit. JAW

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 53407

USING DEPT NO: 504303	OPENED DATE: 01/17/2025 08:39:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/21/2025 15:17:34	METER 1 - M: 162659 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/21/2025 15:19:48	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-004	REPLACE NEW CLEARANCE/MARKER	DON	N	N	GARAGE	0.00	\$0.00	\$11.87	\$0.00	\$11.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.00 0.00 11.87 5.00 16.87

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-004	REPLACE NEW CLEARANCE/MARKER	GRO52892	TAILLIGHT	11.87	1	\$11.87
					PARTS	11.87

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 53407

Work Order Notes

Job Notes

03-34-004 - REPLACE NEW CLEARANCE/MARKER

(GARAGE) FJ- Replaced tail/brake light unit ordered by GC.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 5350

USING DEPT NO:	504303	OPENED DATE:	03/01/2010 07:08:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/09/2010 07:31:56	METER 1 - M:	46856	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	03/09/2010 07:31:59	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-028	REPLACE NEW ABS ECU/ECM	DON	O	N	GARAGE	2.80	\$161.00	\$1,299.21	\$0.00	\$1,460.21
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.26	\$72.18	\$31.38	\$0.00	\$103.56
SO-13-028	SCAN OUT ABS ECU/ECM	DON	O	N	GARAGE	0.01	\$0.32	\$0.00	\$0.00	\$0.32

JOB COUNT: 3	WORK ORDER TOTAL:	4.06	233.50	1,330.59	0.00	1,564.09
---------------------	--------------------------	-------------	---------------	-----------------	-------------	-----------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11268671	03/01/2010 07:19:36	03/01/2010 07:20:12	0.01	\$0.58
66-PM-PMA	PERFORM OIL CHANGE	11268671	03/01/2010 09:15:00	03/01/2010 10:29:43	1.25	\$71.60
SO-13-028	SCAN OUT ABS ECU/ECM	11268671	03/08/2010 09:52:33	03/08/2010 09:52:53	0.01	\$0.32
03-13-028	REPLACE NEW ABS ECU/ECM	11274660	03/08/2010 07:00:00	03/08/2010 09:48:00	2.80	\$161.00
66-PM-PMA	PERFORM OIL CHANGE	11268671	03/01/2010 07:19:36	03/01/2010 09:00:00	(1.67)	(\$96.21)
66-PM-PMA	PERFORM OIL CHANGE	11268671	03/01/2010 07:19:36	03/01/2010 09:00:00	1.67	\$96.21
					LABOR	233.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-028	REPLACE NEW ABS ECU/ECM	7C2Z2C219CA	HCU	434.49	1	\$434.49
03-13-028	REPLACE NEW ABS ECU/ECM	6C2Z2C286BA	ECU	861.09	1	\$861.09
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
03-13-028	REPLACE NEW ABS ECU/ECM	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	1.82	2	\$3.63
					PARTS	1330.59

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 5350

Work Order Notes

(RWINTERS) PM, LUBE LIFT GATE AND ABS LIGHT IS ON

Job Notes

03-13-028 - REPLACE NEW ABS ECU/ECM

(LPATE) REPLACED ABS PUMP AND MODULE, BLED BRAKES LINES, CLEARED CODES, TEST DROVE DID NOT RESET

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS)

The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 51372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 224
Description : OIL BOTTLE
Manufacturer :

Part No : FA1632
Qty : 1
Description : FILTER-AIR
Manufacturer :

(RWINTERS) PM AND LUBE LIFT GATE BY IF

SO-13-028 - SCAN OUT ABS ECU/ECM

(LPATE) RAN DIAG CIRCUIT CHECK-ORDERED ABS PUMP AND MODULE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 53678

USING DEPT NO: 504303	OPENED DATE: 02/10/2025 08:39:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/11/2025 07:30:57	METER 1 - M: 162874 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/11/2025 14:26:07	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$30.09	\$0.00	\$30.09
06-55-039	INSPECT LIFTGATE ASSY	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$69.57	\$0.00	\$69.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	99.66	5.00	104.66
---------------------	--------------------------	-------------	-------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	5W20 FULL SYN QTS	9.09	7	\$63.63
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.05	2	\$30.09
					PARTS	99.66

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 53678

Work Order Notes

(EHANNAH) pm- wash- SI
(EHOWELL)
(GARAGE) Pending SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- replaced wiper blades

06-00 - INSPECT COMPLETE VEHICLE

06-55-039 - INSPECT LIFTGATE ASSY

(EHOWELL) FJ- Inspected operation of liftgate & lubricates at hinge points (.5h labor)

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si cm checked over vehicle brake pads 6 mm on front 8 mm on rear unit checked ok,

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, filled up washer fluid
162857
(EHOWELL)

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 547

USING DEPT NO:	504303	OPENED DATE:	12/17/2007 08:00:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2007 08:02:21	METER 1 - M:	19160	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	12/17/2007 08:02:22	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$27.59	\$0.00	\$41.54

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 13.95 27.59 0.00 41.54

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	12/17/2007 08:05:00	12/17/2007 08:23:36	0.31	\$13.95

LABOR 13.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.09	224	\$20.16
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.43	1	\$7.43

PARTS 27.59

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 547

Work Order Notes

(LOBRIEN) PM, GREASE LIFT TRACK AND REPLACE BOLT (LIFT PANEL).

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY JASON ELMORE. GREASED LIFT TRACK AND REPLACED THE LIFT PANEL BOLT.

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 5583

USING DEPT NO: 504303	OPENED DATE: 04/09/2010 11:48:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/13/2010 06:58:48	METER 1 - M: 47740 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/13/2010 06:58:51	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	0.70	\$40.25	\$74.43	\$0.00	\$114.68
35-05	DIAGNOSE ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **2.20** **126.50** **74.43** **0.00** **200.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-05	DIAGNOSE ELECTRONIC ENGINE EEC SYSTEM	11268671	04/09/2010 15:00:29	04/09/2010 16:30:29	1.50	\$86.25
03-33-003	REPLACE NEW COIL	11268671	04/12/2010 06:00:00	04/12/2010 06:42:00	0.70	\$40.25
35-05	DIAGNOSE ELECTRONIC ENGINE EEC SYSTEM	11268671	04/09/2010 15:00:29	04/09/2010 15:00:42	0.00	(\$0.21)
35-05	DIAGNOSE ELECTRONIC ENGINE EEC SYSTEM	11268671	04/09/2010 15:00:29	04/09/2010 15:00:42	0.00	\$0.21
					LABOR	126.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-33-003	REPLACE NEW COIL	MOTDG508	IGNITION COIL	74.43	1	\$74.43
03-33-003	REPLACE NEW COIL	MOTDG508	IGNITION COIL	74.43	(41)	(\$3,051.63)
03-33-003	REPLACE NEW COIL	MOTDG508	IGNITION COIL	74.43	41	\$3,051.63
					PARTS	74.43

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 5583

Work Order Notes

(LPATE) CHECK ENGINE LIGHT ON RUNNING ROUGH

Job Notes

03-33-003 - REPLACE NEW COIL

(LPATE) REPLACED IGNITION COIL W/BOOT
(RWINTERS) ON # 3 CYLINDER

35-05 - DIAGNOSE ELECTRONIC ENGINE EEC SYSTEM

(LPATE) RAN DIAGNOSTICS CHECKED FOUND NEEDS NEW COIL WITH BOOT

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 56030

USING DEPT NO: 504303	OPENED DATE: 08/21/2025 07:14:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/21/2025 15:07:08	METER 1 - M: 164208 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/22/2025 07:45:23	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.58	\$72.12	\$0.00	\$0.00	\$72.12
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$53.45	\$0.00	\$53.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.58	72.12	53.45	5.00	130.57
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12201267	08/21/2025 13:00:00	08/21/2025 13:34:37	0.58	\$72.12
LABOR					72.12	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF5W20BT	5W20BT OIL - STIVERS	5.87	7	\$41.06
66-PM-PMA	PERFORM OIL CHANGE	SFFL8010S	FL8010S OIL FILTER - STIVERS	12.39	1	\$12.39
PARTS					53.45	

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 56030

Work Order Notes

(CWIGLEY) PM. Wash. SI Inspection

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) GC,FJ- safety inspection, found no issues at this time, steering and front end all good, FJ- greased front end components, pulled all tires off and inspected brakes. Front brakes are 6mm and rear brakes are 10mm
Miles, 164,208

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) 164,208 miles
PM

GC- Added oil & checked oil level, checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths
FJ- Oil change

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 57938

USING DEPT NO: 504303	OPENED DATE: 01/21/2026 08:22:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/21/2026 12:33:04	METER 1 - M: 164735 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/21/2026 13:19:49	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.50	\$75.00	\$0.00	\$0.00	\$75.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.50	225.00	0.00	5.00	230.00
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	01/21/2026 12:32:43	01/21/2026 13:32:43	1.00	\$150.00
25-52-021	REMOVE GPS SYSTEM	12478231	01/21/2026 11:33:43	01/21/2026 12:03:43	0.50	\$75.00
					LABOR	225.00

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 57938

Work Order Notes

(EKIMBREL) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(EKIMBREL) removed GPS# 87u030640012 from vehicle. CQ

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) Prepped vehicle for decommission. CQ

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 6104

USING DEPT NO: 504303	OPENED DATE: 06/25/2010 11:12:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/25/2010 13:24:58	METER 1 - M: 48754 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/25/2010 13:25:00	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350	2006 Ford E350	UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$39.18	\$0.00	\$53.56
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$28.03	\$0.00	\$45.86

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **67.21** **0.00** **99.42**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	06/25/2010 17:00:00	06/25/2010 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11328035	06/25/2010 17:18:36	06/25/2010 17:33:36	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
03-51-038	REPLACE NEW WIPER BLADES	60-2240	WIPER BLADE	19.64	2	\$39.27
03-51-038	REPLACE NEW WIPER BLADES	60-2240	WIPER BLADE	19.64	(2)	(\$39.27)
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.59	2	\$39.18
					PARTS	67.21

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 6104

Work Order Notes

(RWINTERS) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY TM

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 6939

USING DEPT NO:	504303	OPENED DATE:	10/07/2010 13:38:47	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	10/15/2010 07:11:24	METER 1 - M:	49616	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/15/2010 07:11:25	IN-SERVICE DATE:	10/30/2006		
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-44	WARRANTY FUEL SYSTEM	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	0.10	\$5.91	\$0.00	\$0.00	\$5.91

JOB COUNT: 2 WORK ORDER TOTAL: 0.10 5.91 0.00 0.00 5.91

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost	
15-44	WARRANTY FUEL SYSTEM	11078175	17323	0009457	\$0.00	
					COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-44	TRANSPORT FUEL SYSTEM	11328035	10/12/2010 15:15:32	10/12/2010 15:21:42	0.10	\$5.91
					LABOR	5.91

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 6939

Work Order Notes

(LPATE) RECALL 08S02 FROM FORD FUEL RAIL ASSY REPLACEMENT-TAKE TO TOWNSEND FOR TO BE COMPLETED

Job Notes

15-44 - WARRANTY FUEL SYSTEM

(LPATE) FORD COMPLETED RECALL 08S02 REPLACED FUEL RAIL ASSY

16-44 - TRANSPORT FUEL SYSTEM

(LPATE) TAKEN TO FORD BY TM

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 7403

USING DEPT NO: 504303	OPENED DATE: 12/17/2010 14:24:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/03/2011 15:02:41	METER 1 - M: 52409 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/03/2011 15:02:43	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$333.19	\$333.19
07-02-016	LUBRICATE TAIL&LIFT GATE	DON	O	N	GARAGE	0.96	\$54.95	\$16.26	\$0.00	\$71.21
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$42.10	\$0.00	\$59.93

JOB COUNT: 4	WORK ORDER TOTAL:	2.27	130.28	58.36	333.19	521.83
---------------------	--------------------------	-------------	---------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	D216394	0010224	\$333.19	
					COMML	333.19

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10230946	12/20/2010 09:02:24	12/20/2010 09:21:00	0.31	\$17.83
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10230946	12/20/2010 09:21:00	12/20/2010 10:21:00	1.00	\$57.50
07-02-016	LUBRICATE TAIL&LIFT GATE	10230946	12/20/2010 08:05:04	12/20/2010 09:02:24	0.96	\$54.95
					LABOR	130.28

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.07	1	\$14.07
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
07-02-016	LUBRICATE TAIL&LIFT GATE	C111	RED BRAKE CLEANER	4.37	2	\$8.73
07-02-016	LUBRICATE TAIL&LIFT GATE	TUBE GREASE	TUBE GREASE	3.12	1	\$3.12
07-02-016	LUBRICATE TAIL&LIFT GATE	C111	RED BRAKE CLEANER	4.37	(2)	(\$8.73)
07-02-016	LUBRICATE TAIL&LIFT GATE	C111	RED BRAKE CLEANER	4.38	3	\$13.14
					PARTS	58.36

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 7403

Work Order Notes

(LPATE) PM-GREASE LIFTGATE, CLEAN SLIDES-PER RANDALL 2 FRONT TIRES ARE WEARING UNEVEN NEED TO BE REPLACED AND FRONT END ALIGNED

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) GOODYEAR REPLACED 2 FRONT TIRES AND ALIGNED POO32823

07-02-016 - LUBRICATE TAIL&LIFT GATE

(LPATE) CLEANED ALL GREASE OUT OF CHAIN TRACKS AND RELUBRICATED WITH NEW GREASE AND LUBED LIFTGATE ALSO

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO GOODYEAR BY JM

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY JM/RS-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 796

USING DEPT NO: 504303	OPENED DATE: 02/08/2008 13:54:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/11/2008 11:27:51	METER 1 - M: 21517 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/11/2008 11:27:51	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.00	\$0.00	\$29.82	\$0.00	\$29.82
15-33-005	WARRANTY IGNITION SYSTEM SECON	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-33-005	TRANSPORT IGNITION SYSTEM SECOI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.45	\$0.00	\$51.45

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	81.27	0.00	81.27
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-33-005	WARRANTY IGNITION SYSTEM SECONDARY	11112000	MRCS107857	00971	\$0.00
				COMML	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.46	1	\$7.46
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	23.84	1	\$23.84
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.09	224	\$20.16
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	14.91	2	\$29.82
					PARTS	81.28

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 796

Work Order Notes

(RWINTERS) PM, GREASE LIFT AND THE ENGINE HAS A SKIP IN IT.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(RWINTERS) REPLACED THE WIPER BLADES.

15-33-005 - WARRANTY IGNITION SYSTEM SECONDARY

(LOBRIEN) REPLACED COIL AND PLUG.

16-33-005 - TRANSPORT IGNITION SYSTEM SECONDARY

(LOBRIEN) TAKEN TO MADDEN.

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) PM BY CM AND LUBED LIFT GATE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 863

USING DEPT NO: 504303	OPENED DATE: 02/20/2008 09:05:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/20/2008 09:09:46	METER 1 - M: 22319 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 02/20/2008 09:09:48	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$121.70	\$121.70

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	121.70	121.70
---------------------	--------------------------	-------------	-------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	193641	01020	\$121.70
				COMML	121.70

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 863

Work Order Notes

(RWINTERS) RR OUTSIDE TIRE IS FLAT.

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(RWINTERS) INSTALLED SPARE TO RR OUTSIDE, HAD NEW TIRE MOUNTED AND PUT TO SPARE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 867

USING DEPT NO:	504303	OPENED DATE:	02/20/2008 14:21:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/20/2008 14:25:40	METER 1 - M:	23391	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/20/2008 14:25:43	IN-SERVICE DATE:	10/30/2006	
TECH SPEC NO:	06VNFORDE350	2006 Ford E350		UNIT SERIAL NO:	1FDWE35L66DB35805	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-55-010	REPLACE NEW HYDRAULIC LIFT SYST	DON	O	N	GARAGE	0.00	\$0.00	\$2.13	\$0.00	\$2.13

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 2.13 0.00 2.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-55-010	REPLACE NEW HYDRAULIC LIFT SYSTEM	PIC5525C	INDICATOR PILOT LIGHT	2.13	1	\$2.13
					PARTS	2.13

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 867

Work Order Notes

(RWINTERS) PILOT LIGHT FOR REAR LIFT IS INOP.

Job Notes

03-55-010 - REPLACE NEW HYDRAULIC LIFT SYSTEM

(RWINTERS) REPLACED THE PILOT LIGHT

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 8818

USING DEPT NO: 504303	OPENED DATE: 07/29/2011 06:52:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/10/2011 09:58:14	METER 1 - M: 54040 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/10/2011 09:58:16	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.30	\$17.25	\$22.43	\$0.00	\$39.68
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	O	N	GARAGE	0.30	\$17.25	\$37.71	\$0.00	\$54.96
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.69	\$96.93	\$0.00	\$0.00	\$96.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$14.46	\$31.56	\$0.00	\$46.02

JOB COUNT: 4	WORK ORDER TOTAL:	2.54	145.89	91.70	0.00	237.59
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	11328035	08/09/2011 07:18:00	08/09/2011 07:36:00	0.30	\$17.25
03-02-010	REPLACE NEW MIRRORS	11328035	08/09/2011 07:00:00	08/09/2011 07:18:00	0.30	\$17.25
66-79-003	PERFORM SAFETY INSPECTION	11328035	08/01/2011 11:17:15	08/01/2011 12:58:24	1.69	\$96.93
66-PM-PMA	PERFORM OIL CHANGE	11328035	08/01/2011 11:02:10	08/01/2011 11:17:15	0.25	\$14.46
					LABOR	145.89

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	UBLCX850SS	CONVEX MIRROR	22.43	1	\$22.43
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	GRO53762	TAILLIGHT ASSY	37.71	1	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.68	1	\$4.68
					PARTS	91.70

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 8818

Work Order Notes

(LPATE) PM-DO SAFETY INSPECTION-CONVEX MIRROR FOR REAR OF TRUCK IS MISSING-LEFT REAR TAILLIGHT IS BROKEN

Job Notes

03-02-010 - REPLACE NEW MIRRORS

(LPATE) REPLACED CONVEX MIRROR AT TOP REAR LEFT SIDE OF TRUCK WAS MISSNG.

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

(LPATE) REPLACED LEFT REAR TAILLIGHT ASSY WAS BROKEN

66-79-003 - PERFORM SAFETY INSPECTION

(RWINTERS) SAFETY INSPECTION COMPLETE-PM DONE-REPLACED REAR CONVEX MIRROR AT TOP OF TRUCK AND LEFT REAR TAILLAMP ASSY. WITHIN NEXT 12 MONTHES WILL NEED FRONT AND REAR BRAKE JOB QUOTED DEPT \$800.00

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY TM-LUBED LIFT GATE

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 9623

USING DEPT NO: 504303	OPENED DATE: 11/07/2011 14:08:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/08/2011 14:10:21	METER 1 - M: 54915 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/08/2011 14:10:33	IN-SERVICE DATE: 10/30/2006
TECH SPEC NO: 06VNFORDE350 2006 Ford E350		UNIT SERIAL NO: 1FDWE35L66DB35805

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
07-02-016	LUBRICATE TAIL&LIFT GATE	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
07-02-016	LUBRICATE TAIL&LIFT GATE	11413680	11/07/2011 17:00:00	11/07/2011 18:00:00	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

UNIT NO: 236965 2006 FORD E350

WORK ORDER NO: 9623

Work Order Notes

(LPATE) CLEAN AND LUBE LIFT GATE

Job Notes

07-02-016 - LUBRICATE TAIL&LIFT GATE

(RWINTERS) CLEANED WITH MINERAL SPIRITS AND LUBED WITH OPEN GEAR GREASE. CHECKED HYD FLUID IS OK

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Jan 22 2026 12:26:02 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '236965') //Q=