

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 45030

USING DEPT NO:	507301	OPENED DATE:	10/19/2022 09:16:53	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	10/20/2022 08:13:23	METER 1 - M:	3205	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/20/2022 09:46:17	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.78	\$0.00	\$0.00	\$22.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.19 22.78 0.00 5.00 27.78

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMM
					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/19/2022 09:30:00	10/19/2022 09:41:35	0.19	\$22.78
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/19/2022 09:26:08	10/19/2022 09:26:08	0.00	\$0.00
					LABOR	22.78

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 45030

Work Order Notes

(CWIGLEY) PM

Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has 3205 miles on it. Will go to Toyota at 10,000 miles for service. Checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 46127

USING DEPT NO:	507301	OPENED DATE:	02/13/2023 10:37:26	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/16/2023 12:07:18	METER 1 - M:	10342	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2023 07:23:52	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-PM	TRANSPORT PM SERVICE	DON	P	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 WORK ORDER TOTAL: 0.50 59.00 0.00 5.00 64.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-PM	TRANSPORT PM SERVICE	11399745	02/16/2023 07:00:00	02/16/2023 07:30:00	0.50	\$59.00
					LABOR	59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 46127

Work Order Notes

(LISAPATE) pm-

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

**16-PM - TRANSPORT PM SERVICE**

(LISAPATE) Taken to Toyota by CW

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Oil change done by Tuscaloosa Toyota

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 46906

USING DEPT NO:	507301	OPENED DATE:	04/28/2023 13:53:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2023 08:42:47	METER 1 - M:	15409	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2023 10:01:46	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.33 38.94 0.00 5.00 43.94

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/01/2023 12:51:18	05/01/2023 13:11:06	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/01/2023 12:51:18	05/01/2023 12:51:18	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/01/2023 12:51:18	05/01/2023 12:51:18	0.00	\$0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 46906

---

## Work Order Notes

(EHANNAH) pm- replace wiper- wash

---

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

## **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit is in between oil changes from dealer. Checked fluids and tires. Updated sticker. Coolant -34°. JAW,CW  
MILEAGE-15409

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 47749

USING DEPT NO:	507301	OPENED DATE:	07/26/2023 11:04:29	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	08/07/2023 07:21:54	METER 1 - M:	21246	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/07/2023 09:52:09	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-PM	TRANSPORT PM SERVICE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 3** **WORK ORDER TOTAL:** **0.33** **38.94** **0.00** **5.00** **43.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6213425		\$0.00
				COMM	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-PM	TRANSPORT PM SERVICE	11399745	08/07/2023 07:00:00	08/07/2023 07:19:48	0.33	\$38.94
					LABOR	<b>38.94</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 47749

## Work Order Notes

(LRUSHING) PM

## Job Notes

**16-PM - TRANSPORT PM SERVICE**

(LISAPATE) Taken to Toyota by CW

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) 20,000 mile service done by Toyota no charge

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 48380

USING DEPT NO:	507301	OPENED DATE:	10/02/2023 10:23:57	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	10/03/2023 15:44:26	METER 1 - M:	26532	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/04/2023 07:26:06	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.54	\$24.08	\$0.00	\$35.62
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.08	\$9.34	\$0.00	\$0.00	\$9.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.67	\$50.24	\$0.00	\$71.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 4** **WORK ORDER TOTAL:** **0.36** **42.55** **74.32** **5.00** **121.87**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12395904	10/03/2023 08:19:34	10/03/2023 08:24:19	0.08	\$9.34
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/02/2023 15:22:37	10/02/2023 15:28:29	0.10	\$11.54
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/02/2023 15:11:36	10/02/2023 15:22:37	0.18	\$21.67

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.14	1	\$6.14
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.82	5	\$44.10

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 48380

---

## Work Order Notes

(EHANNAH) pm- wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) replased new wepers fc

### **66-79-003 - PERFORM SAFETY INSPECTION**

(FCONTRER) Perform safety inspection found no issues at this time-FC

Brake pads Front 10mm Rear 8mm

Miles, 26,532

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) perform oil chenged fluid check tread tires pressure fc

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 49370

USING DEPT NO:	507301	OPENED DATE:	01/08/2024 09:11:36	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	01/09/2024 15:22:42	METER 1 - M:	30944	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/10/2024 07:16:38	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$62.56	\$0.00	\$101.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.33 38.94 62.56 5.00 106.50

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/08/2024 12:26:18	01/08/2024 12:46:06	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/08/2024 12:26:18	01/08/2024 12:26:18	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/08/2024 12:26:18	01/08/2024 12:26:18	0.00	\$0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	11.03	5	\$55.13
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	(1)	(\$11.78)
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43

PARTS 62.56

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 49370

---

Work Order Notes

(EHANNAH) pm

---

Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(GRCOOK) Performed PM-GC;FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 30,944

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 49593

USING DEPT NO:	507301	OPENED DATE:	01/26/2024 11:20:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/29/2024 11:53:22	METER 1 - M:	32775	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2024 08:32:09	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.02	\$2.07	\$4.60	\$0.00	\$6.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.02 2.07 4.60 5.00 11.67

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	01/26/2024 13:00:00	01/26/2024 13:01:03	0.02	\$2.07
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	01/26/2024 12:57:24	01/26/2024 12:57:24	0.00	\$0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	1	\$3.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	5	\$0.98

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 49593

---

## Work Order Notes

(LRUSHING) back right tire is flat

---

## Job Notes

14-17-030 - INSTALL TIRE PATCH

## **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GRCOOK) Installed 1 used tire for unit 9339B that came in for flat tire, tire had screw or nail to close to side wall. -GC  
Miles, 32,775

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 49868

USING DEPT NO:	507301	OPENED DATE:	02/20/2024 11:26:29	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/21/2024 13:20:01	METER 1 - M:	34390	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/26/2024 11:02:52	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.66	\$42.53	\$0.00	\$82.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.34 39.66 42.53 5.00 87.19

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/20/2024 13:16:05	02/20/2024 13:36:15	0.34	\$39.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 49868

---

Work Order Notes

(LRUSHING) PM

---

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes ah - fc

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 50689

USING DEPT NO:	507301	OPENED DATE:	04/26/2024 10:15:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2024 12:59:31	METER 1 - M:	38456	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2024 12:08:58	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.92	\$24.08	\$0.00	\$25.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.11	\$127.27	\$0.00	\$128.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 WORK ORDER TOTAL: 0.02 2.03 151.35 5.00 158.38

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/26/2024 11:19:22	04/26/2024 11:19:56	0.01	\$1.11
03-51-038	REPLACE NEW WIPER BLADES	12395904	04/26/2024 11:18:35	04/26/2024 11:19:03	0.01	\$0.92

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	15.32	5	\$76.58
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER	35.61	1	\$35.61
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43

PARTS 151.35

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 50689

---

## Work Order Notes

(EHANNAH) pm- wipers

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(FCONTRER) replaced new wipers fc

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) perform oil changed fc

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 51278

USING DEPT NO:	507301	OPENED DATE:	06/24/2024 11:20:28	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/25/2024 08:27:32	METER 1 - M:	41783	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/25/2024 10:30:01	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.61	\$48.18	\$0.00	\$49.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.01 1.61 48.18 5.00 54.79

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/24/2024 13:47:41	06/24/2024 13:48:30	0.01	\$1.61

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.26	5	\$41.32
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.86	1	\$6.86

PARTS 48.18

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 51278

## Work Order Notes

(LRUSHING) pm

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc - ah

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 52168

USING DEPT NO:	507301	OPENED DATE:	09/19/2024 08:37:24	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2024 13:51:45	METER 1 - M:	45851	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2024 14:34:16	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.11	\$0.00	\$24.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.09	\$0.00	\$51.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 WORK ORDER TOTAL: 0.00 0.00 75.20 5.00 80.20

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.32	5	\$36.60
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23

PARTS 75.20

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 52168

---

## Work Order Notes

(EHANNAH) pm- wipers

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) REPLACED WIPER BLADES CM

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) PERFORMED PM CM CHANGED MOTOR OIL AND FILTER CHECKED ALL FLUIDS AND TIRES CHECKED OK, CM 45851

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 52886

USING DEPT NO:	507301	OPENED DATE:	11/22/2024 08:41:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/25/2024 07:36:58	METER 1 - M:	50257	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/25/2024 08:51:39	IN-SERVICE DATE:	09/02/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.60	\$0.00	\$51.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 WORK ORDER TOTAL: 0.00 0.00 51.60 5.00 56.60

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.40	5	\$42.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 52886

---

## Work Order Notes

(EHANNAH) pm- SI- inspect tire

---

## Job Notes

### **06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

(GARAGE) CHECKED TIRES AND FOUND TO CHECK OK. CQ

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) PERFORMED INSPECTION PER SI SHEET FOUND TO CHECK OUT OK. CQ

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) JR- perform PM, changed oil and filter, checked air filter, checked fluids, checked tires and tire pressures

50258 miles

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 54378

USING DEPT NO:	507301	OPENED DATE:	04/07/2025 13:22:00	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/08/2025 08:36:21	METER 1 - M:	56136	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/11/2025 15:19:45	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$56.55	\$0.00	\$56.55
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$26.71	\$0.00	\$26.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 WORK ORDER TOTAL: 0.00 0.00 83.26 5.00 88.26

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	26.71	1	\$26.71
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.28	5	\$41.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 54378

---

Work Order Notes

(EHANNAH) pm- wiper

---

Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**03-53-003 - REPLACE NEW CABIN FILTER**

(GARAGE) GC- replaced cabin filter

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) JR- top side, checked fluids, filters good, tires and tire pressure, filled with oil.

GC- bottom side, drained oil and changed oil filter.

Miles, 56,137

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(EKIMBREL) GC- replaced cabin filter

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 55153

USING DEPT NO:	507301	OPENED DATE:	06/20/2025 08:22:37	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/20/2025 13:30:53	METER 1 - M:	60273	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/23/2025 08:33:23	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>48.90</b>	<b>5.00</b>	<b>53.90</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.28	5	\$41.40
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 55153

---

## Work Order Notes

(EHANNAH) pm- wiper- inspect brakes- driver reports p brakes not working

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- Not needed at this time.

**06-13 - INSPECT BRAKES**

**66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) perform si cm checked brakes front 10 mm rear 8 mm rotated tires, checked front end, checked parking brake, checked over unit checked ok, test drove brake system checked ok,

(GARAGE) put better tire on front 6mm tread depth on front, 4 mm on back

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- PM. Mileage: 60,273. Oil change, checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths.

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY WORK ORDER NO: 56379

USING DEPT NO:	507301	OPENED DATE:	09/15/2025 09:08:47	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	09/15/2025 14:22:45	METER 1 - M:	65317	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2025 12:27:05	IN-SERVICE DATE:	09/02/2022		
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3PU080716		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$32.76	\$0.00	\$32.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$56.55	\$0.00	\$56.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 WORK ORDER TOTAL: 0.00 0.00 89.31 5.00 94.31

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	1	\$15.04
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	17.72	1	\$17.72
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.28	5	\$41.40

PARTS 89.31

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 56379

---

## Work Order Notes

(EHANNAH) pm-wip[ers

---

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- topside

FJ- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid  
65317 miles

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO:

244964

2022 TOYOTA CAMRY

WORK ORDER NO:

57814

USING DEPT NO:

507301

OPENED DATE:

01/12/2026 07:18:35

LOCATION: GARAGE - University Automotive Services

WO STATUS:

OPEN

COMPLETED DATE:

METER 1 - M:

METER 2 - N:

0

WO VISIT REASON:

SCHEDULED

CLOSED DATE:

IN-SERVICE DATE:

09/02/2022

TECH SPEC NO:

22TOYCAMRY

2022 Toyota Camry

UNIT SERIAL NO:

4T1C11AK3PU080716

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-999	PREP SERVICE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.40	\$60.13	\$0.00	\$0.00	\$60.13

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.40</b>	<b>60.13</b>	<b>0.00</b>	<b>0.00</b>	<b>60.13</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-999	PREP SERVICE PREPARE UNIT FOR DISPOSAL	12480657	01/12/2026 07:21:48	01/12/2026 07:45:51	0.40	\$60.13
					<b>LABOR</b>	<b>60.13</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

UNIT NO: 244964 2022 TOYOTA CAMRY

WORK ORDER NO: 57814

## Work Order Notes

(EKIMBREL) prep for sale

## Job Notes

PS-00-999 - PREP SERVICE PREPARE UNIT FOR DISPOSAL

(GARAGE) CM performed prep for sale unit had 70,305 miles, unit checked ok,

# Work Order Charge Detail

The University of Alabama

Report Printed: 01/12/2026 08:34:09 By User: GLOBETTI

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~1  
**Data Extracted:** Mon Jan 12 2026 08:34:09      **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '244964') //Q=