

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 49774

USING DEPT NO: 401101	OPENED DATE: 02/12/2024 07:49:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/16/2024 15:07:19	METER 1 - M: 8 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/19/2024 09:19:53	IN-SERVICE DATE: 02/01/2024
TECH SPEC NO: 24TOYHIGHLNDR 2024 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH9RS531441	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **5.00** **123.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12201267	02/16/2024 07:00:00	02/16/2024 08:00:00	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 49774

Work Order Notes

(EHANNAH) new unit

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI by GC

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 51333

USING DEPT NO: 401101	OPENED DATE: 06/27/2024 15:05:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/28/2024 07:51:44	METER 1 - M: 1905 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/28/2024 08:45:53	IN-SERVICE DATE: 02/01/2024
TECH SPEC NO: 24TOYHIGHLNDR 2024 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH9RS531441	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.11	\$0.00	\$0.00	\$1.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.87	\$1.87
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.75	\$0.00	\$0.00	\$0.75

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	1.86	0.00	1.87	3.73
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$1.87
COMML					1.87

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	06/28/2024 07:26:28	06/28/2024 07:26:51	0.01	\$0.75
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/28/2024 07:25:32	06/28/2024 07:26:06	0.01	\$1.11
LABOR					1.86	

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 51333

Work Order Notes

(LRUSHING) pm and wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 52421

USING DEPT NO: 401101	OPENED DATE: 10/08/2024 11:25:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/09/2024 09:11:58	METER 1 - M: 4119 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/09/2024 09:45:36	IN-SERVICE DATE: 02/01/2024
TECH SPEC NO: 24TOYHIGHLNDR 2024 Toyota Highlander		UNIT SERIAL NO: 5TDKDRAH9RS531441

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$62.82	\$0.00	\$62.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.00 0.00 62.82 5.00 67.82

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.36	1	\$9.36
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	8.91	6	\$53.46
PARTS						62.82

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 52421

Work Order Notes

(CWIGLEY) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-CM.RC,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 4,119

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 54132

USING DEPT NO: 401101	OPENED DATE: 03/24/2025 14:43:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/25/2025 14:37:15	METER 1 - M: 8476 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/26/2025 07:47:33	IN-SERVICE DATE: 02/01/2024
TECH SPEC NO: 24TOYHIGHLNDR 2024 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH9RS531441	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$47.19	\$0.00	\$47.19
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$34.07	\$0.00	\$34.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	81.26	5.00	86.26
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	34.07	1	\$34.07
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	8.67	1	\$8.67
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
PARTS						81.26

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 54132

Work Order Notes

(EHANNAH) pm- wipers- wash
(GARAGE) Pending SI & wash.

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) JR- perform SI per SI sheet, everything Checked OK
front brakes were 10s, rear brakes were 8s

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Mileage is 8476. Oil change, topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) FJ- Replaced cabin filter.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 55991

USING DEPT NO: 401101	OPENED DATE: 08/18/2025 15:15:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/19/2025 10:26:37	METER 1 - M: 11081 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/19/2025 15:48:53	IN-SERVICE DATE: 02/01/2024
TECH SPEC NO: 24TOYHIGHLNDR 2024 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH9RS531441	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$45.93	\$0.00	\$45.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	45.93	5.00	50.93
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.41	6	\$38.43
PARTS						45.93

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 55991

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) 11,081 miles

FJ- PM. Oil change, checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 56647

USING DEPT NO: 401101	OPENED DATE: 10/03/2025 14:34:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/03/2025 15:09:14	METER 1 - M: 11081 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2025 12:42:04	IN-SERVICE DATE: 02/01/2024
TECH SPEC NO: 24TOYHIGHLNDR 2024 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH9RS531441	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	5	N	GARAGE	0.32	\$47.63	\$480.62	\$0.00	\$528.25
CH-SP	CHARGE Shop Supplies	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.32** **47.63** **480.62** **5.00** **533.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	12051004	10/03/2025 14:48:54	10/03/2025 15:07:57	0.32	\$47.63
					LABOR	47.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	815500E360	TAIL LIGHT ASSEMBLY	480.62	1	\$480.62
					PARTS	480.62

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 56647

Work Order Notes

(EKIMBREL) REPLACE TAILLIGHT ASSEMBLY
(IFALLS) unit was turned in by department, they no longer need to lease it.
will be released to another department.

Job Notes

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY
(GARAGE) JR- replaced passenger side tail light assembly
CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 58288

USING DEPT NO: 401101	OPENED DATE: 02/12/2026 14:34:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: OPEN	COMPLETED DATE:	METER 1 - M: 11958 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE:	IN-SERVICE DATE: 02/01/2024
TECH SPEC NO: 24TOYHIGHLNDR 2024 Toyota Highlander		UNIT SERIAL NO: 5TDKDRAH9RS531441

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 245914 2024 TOYOTA HIGHLANDER

WORK ORDER NO: 58288

Work Order Notes

(EKIMBREL) prep for sale

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Sun Feb 15 2026 06:04:33 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '245914') //Q=