

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 42927

USING DEPT NO: 505161	OPENED DATE: 04/14/2022 13:05:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/14/2022 13:06:45	METER 1 - M: 18 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/15/2022 09:41:09	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA	2022 Toyota Tacoma	UNIT SERIAL NO: 3TYAX5GN4NT050746

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **2.00** **120.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11213180	04/14/2022 13:06:08	04/14/2022 14:06:08	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 42927

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) MS completed PDI

Work Order Charge Detail

UNIT NO: 244606 **2022 TOYOTA TACOMA** **WORK ORDER NO:** 42941

USING DEPT NO: 505161	OPENED DATE: 04/15/2022 12:25:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/13/2022 14:52:20	METER 1 - M: 18 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/14/2022 07:21:11	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA	2022 Toyota Tacoma	UNIT SERIAL NO: 3TYAX5GN4NT050746

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-051	INSTALL SEAT COVER	DON	O	N	GARAGE	1.00	\$118.00	\$734.98	\$14.95	\$867.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **734.98** **16.95** **869.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-02-051	INSTALL SEAT COVER	11074386	100642630		\$14.95
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					16.95

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-051	INSTALL SEAT COVER	11213180	06/13/2022 07:00:00	06/13/2022 08:00:00	1.00	\$118.00
LABOR						118.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-051	INSTALL SEAT COVER	SS2509WFG	SEAT COVER	329.99	1	\$329.99
14-02-051	INSTALL SEAT COVER	SS8452WFG	SEAT COVER	404.99	1	\$404.99
PARTS						734.98

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 42941

Work Order Notes

(EKIMBREL) INSTALL SEAT COVERS

Job Notes

14-02-051 - INSTALL SEAT COVER

(EKIMBREL) MS INSTALLED SEAT COVERS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244606 **2022 TOYOTA TACOMA** **WORK ORDER NO:** 44401

USING DEPT NO:	505161	OPENED DATE:	08/19/2022 15:28:44	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	08/24/2022 13:51:15	METER 1 - M:	992	METER 2 - H:	0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/25/2022 08:52:49	IN-SERVICE DATE:	04/12/2022		
TECH SPEC NO:	22TOYTACOMA	2022 Toyota Tacoma		UNIT SERIAL NO:	3TYAX5GN4NT050746		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.33	\$39.24	\$0.00	\$0.00	\$39.24
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$32.88	\$0.00	\$0.00	\$32.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.61** **72.12** **0.00** **5.00** **77.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/22/2022 09:47:46	08/22/2022 10:04:29	0.28	\$32.88
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/22/2022 10:04:29	08/22/2022 10:24:26	0.33	\$39.24
LABOR					72.12	

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 44401

Work Order Notes

(LRUSHING) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) cross rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Vehicle has 992 miles on it. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244606 **2022 TOYOTA TACOMA** **WORK ORDER NO:** 45951

USING DEPT NO:	505161	OPENED DATE:	01/27/2023 08:18:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2023 15:36:18	METER 1 - M:	1856	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/30/2023 08:24:27	IN-SERVICE DATE:	04/12/2022	
TECH SPEC NO:	22TOYTACOMA	2022 Toyota Tacoma		UNIT SERIAL NO:	3TYAX5GN4NT050746	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.68	\$0.00	\$0.00	\$24.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.21** **24.68** **0.00** **5.00** **29.68**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2023 08:52:08	01/27/2023 09:04:41	0.21	\$24.68
LABOR						24.68

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 45951

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has 1856 miles on it. Will go to Toyota at 10,000 miles. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244606 **2022 TOYOTA TACOMA** **WORK ORDER NO:** 47318

USING DEPT NO: 505161	OPENED DATE: 06/09/2023 15:47:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/13/2023 07:24:43	METER 1 - M: 2466 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/13/2023 10:39:42	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA	2022 Toyota Tacoma	UNIT SERIAL NO: 3TYAX5GN4NT050746

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.17	\$46.97	\$0.00	\$96.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.25	\$29.43	\$0.00	\$0.00	\$29.43

JOB COUNT: 3	WORK ORDER TOTAL:	0.67	78.60	46.97	5.00	130.57
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/12/2023 10:53:13	06/12/2023 11:08:11	0.25	\$29.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/12/2023 10:27:53	06/12/2023 10:52:53	0.42	\$49.17
LABOR					78.60	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	6.80	6	\$40.77
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.20	1	\$6.20
PARTS					46.97	

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 47318

Work Order Notes

(EHANNAH) pm- replace wipers- wash
(EKIMBREL) NEW VEHICLE, DID NOT NEED WIPERS YET

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 244606 **2022 TOYOTA TACOMA** **WORK ORDER NO:** 49028

USING DEPT NO: 505161	OPENED DATE: 11/21/2023 07:11:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/21/2023 12:38:32	METER 1 - M: 3060 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/21/2023 13:10:58	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA 2022 Toyota Tacoma	UNIT SERIAL NO: 3TYAX5GN4NT050746	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.10	\$16.66	\$0.00	\$18.76
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.57	\$67.13	\$0.00	\$0.00	\$67.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.64	\$0.00	\$0.00	\$1.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.32	\$37.43	\$0.00	\$0.00	\$37.43

JOB COUNT: 5	WORK ORDER TOTAL:	0.92	108.30	16.66	5.00	129.96
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	11/21/2023 11:22:34	11/21/2023 11:41:36	0.32	\$37.43
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	11/21/2023 10:47:56	11/21/2023 11:22:04	0.57	\$67.13
03-51-038	REPLACE NEW WIPER BLADES	12395904	11/21/2023 10:46:26	11/21/2023 10:47:30	0.02	\$2.10
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/21/2023 10:45:10	11/21/2023 10:46:00	0.01	\$1.64
LABOR					108.30	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
PARTS					16.66	

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 49028

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Perform rotate the tires and check brake F 8 m R 5 m fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash Fc

Work Order Charge Detail

UNIT NO: 244606 **2022 TOYOTA TACOMA** **WORK ORDER NO:** 50812

USING DEPT NO: 505161	OPENED DATE: 05/10/2024 12:25:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/13/2024 08:10:06	METER 1 - M: 3603 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/13/2024 14:42:48	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA	2022 Toyota Tacoma	UNIT SERIAL NO: 3TYAX5GN4NT050746

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.08	\$55.32	\$0.00	\$56.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.11	\$0.00	\$0.00	\$1.11

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.02** **2.19** **55.32** **5.00** **62.51**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	05/10/2024 13:31:46	05/10/2024 13:32:20	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/10/2024 13:14:18	05/10/2024 13:14:51	0.01	\$1.08
LABOR					2.19	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
PARTS					55.32	

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 50812

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed was full of gas. SH

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 52537

USING DEPT NO: 505161	OPENED DATE: 10/21/2024 07:24:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/22/2024 07:30:41	METER 1 - M: 4271 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/22/2024 07:48:50	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA 2022 Toyota Tacoma		UNIT SERIAL NO: 3TYAX5GN4NT050746

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.66	\$0.00	\$16.66
06-31	INSPECT CHARGING SYSTEM	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	16.66	5.00	21.66
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
					PARTS	16.66

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 52537

Work Order Notes

(EHANNAH) pm- wipers-wash
(EHANNAH) inspect charging system

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced blades, cm

06-31 - INSPECT CHARGING SYSTEM

(IFALLS) The "Service Charging System" message was displayed with the engine off. This is normal for this vehicle.

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) CM performed safety inspection.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm cm 4721 miles, checker checked all fluids filters tires checked ok,

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed cm

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 54205

USING DEPT NO: 505161	OPENED DATE: 03/28/2025 07:55:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/31/2025 07:54:56	METER 1 - M: 4615 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/31/2025 09:06:46	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA 2022 Toyota Tacoma		UNIT SERIAL NO: 3TYAX5GN4NT050746

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$45.14	\$0.00	\$45.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **45.14** **5.00** **50.14**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.62	1	\$6.62
PARTS						45.14

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 54205

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
4615 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 56343

USING DEPT NO:	505161	OPENED DATE:	09/11/2025 09:14:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2025 12:03:07	METER 1 - M:	5078	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2025 14:51:02	IN-SERVICE DATE:	04/12/2022	
TECH SPEC NO:	22TOYTACOMA	2022 Toyota Tacoma		UNIT SERIAL NO:	3TYAX5GN4NT050746	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 56343

Work Order Notes

(EHANNAH) pm- wipers wash - SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, fluid check only, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
5078 miles, 363 miles driven

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 56347

USING DEPT NO: 505161	OPENED DATE: 09/11/2025 12:03:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/12/2025 08:56:12	METER 1 - M: 5078 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/12/2025 12:45:47	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA 2022 Toyota Tacoma	UNIT SERIAL NO: 3TYAX5GN4NT050746	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 56347

Work Order Notes

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(EKIMBREL) Cancelled from Work Order# 56343. By User ID EKIMBREL on 9/11/2025 12:02 PM.

(GARAGE) JR- perform SI per SI sheet, everything checked OK

front pads were 9s, rear drums and rotors were good

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 58283

USING DEPT NO: 505161	OPENED DATE: 02/12/2026 10:22:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/16/2026 09:57:49	METER 1 - M: 5376 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/16/2026 09:59:33	IN-SERVICE DATE: 04/12/2022
TECH SPEC NO: 22TOYTACOMA	2022 Toyota Tacoma	UNIT SERIAL NO: 3TYAX5GN4NT050746

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **150.00** **0.00** **5.00** **155.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11779687	02/12/2026 10:28:34	02/12/2026 11:28:34	1.00	\$150.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11779687	02/12/2026 10:28:34	02/12/2026 10:55:44	0.45	\$67.92
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11779687	02/12/2026 10:28:34	02/12/2026 10:55:44	(0.45)	(\$67.92)
LABOR					150.00	

Work Order Charge Detail

UNIT NO: 244606 2022 TOYOTA TACOMA

WORK ORDER NO: 58283

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) 5,376 miles

Prep for sale

FJ- Removed all lettering/wordmarks, removed all UA paperwork, noted any damage to the vehicle, removed seat covers, removed state tag,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Feb 17 2026 10:15:08 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244606' //Q=